

Trouble Shooting Guide, Advanced

by Toko (toko@gsm-free.org)

Contents

1	Explanations.....	3
2	Enter Test Program	7
3	Calibration IQ	12
4	TxVCO	14
5	VCXO.....	19
6	Calibration RSSI.....	23
7	Power Level Calibration.....	25
8	Intermediate Power Calibration.....	30
9	Transient Spectrum (Spectrum due to Switching).....	31
10	Modulation Spectrum Switched Mode (Spectrum due to Modulation)	36
11	EE-prom	45
12	ADC Calibration (Voltage Calibration).....	46
13	Current Calibration.....	49
14	Network Problems	53
15	Phase and Frequency Error	62
16	Output Power	63
17	Burst Timing (Power Time Template).....	67
18	Sensitivity (Rx Quality)	69
19	Rx Level	74
20	Audio	76
21	Keyboard	83
22	Display.....	85
23	Buzzer	89
24	Illumination	90
25	Top Indicator.....	92
26	SIM Problems (“Insert card”)	94
27	Selftest	97
28	ADC Values	99
29	Revision History	102

1 Explanations

1.1 Conditions

All measurements described in this Trouble Shooting Guide – Advanced, are performed in EFRA with test program in the phone. Some of the faults can occur in tests without test program, e.g. Go/No Go -tests. In these cases you have to program the phone with test program before starting to trouble shoot using this guide.

For trouble shooting with signal program, see 4/00021-2/FEA 209 544/16.

For component placing see 1078-2/FEA 209 544/16.

In case of liquid damage no further action should be taken, handle the unit according to the local company directives.

When measuring with the probe, remember to set the correct attenuation (ext. preamp. gain) on the spectrum analyzer. To get the most appropriate value, set the gain according to Tx output on a correct working card.

1.2 Abbreviations

- B: Crystal.
- C: Capacitor.
- D: Digital circuit.
- F: Over voltage protection.
- H: Buzzer, LED and pads for display.
- J: Connector.
- L: Coil.
- N: Analogue circuit.
- P: Test point.
- R: Resistor.
- S: Keyboard pads.
- U: BALUN Component that converts a balanced signal to an unbalanced or the other way around.
- V: Transistor or diode.
- X: Contact surface on the circuit board.
- Z: Filter.


AGND:	Ground for analogue signal.
AFMS:	Audio from mobile station.
ATMS:	Audio to mobile station.
DCIO:	DC voltage through the system connector for charging.
GND:	Ground.
LED3K:	Logical signal that activates the background illumination.
ONSWAn:	Voltage from the On/Off key that starts the phone.
RTC:	Real Time Clock. The clock that keeps track of time and date.
SIMCLK:	Signal from the processor used for communication to SIM, clock signal.
SIMDAT:	Signal from the processor used for communication to SIM, data signal.
SIMRST:	Signal from the processor used for communication to SIM, reset signal.
SIMVCC:	Feed voltage for SIM.
VBATT:	Battery voltage (4.8V)
VCORE:	DC voltage for the processor and memory (2.5 V)
VDIG:	DC voltage for the processor and memory (3.2 V)
VLCD:	DC voltage for the display that controls the contrast.
VRAD:	DC voltage for the radio part except the synthesiser. (3.75 V)
VRTC:	DC voltage for the real time clock. (2.5 V)
VVCO:	DC voltage for the synthesiser (3.75 V)
I2C:	Communications standard for two-way communication using only 2 wires, clock and data.


1.3 Pin placing

 Resistor, usually blue or black

 Capacitor, usually green or brown

 Coil, usually white/gray







14- pin circuit




16- pin circuit




20- pin circuit




40- pin circuit




64- pin circuit




128- pin circuit




80- pin circuit



28- pin circuit



RX- VCO



TX-VCO

2 Enter Test Program

2.1 Introduction

To be able to use EFRA, the phone has to be programmed with test program. The programming is also performed in EFRA.

If the phone cannot be programmed, proceed to section 2.3.

If the phone does not start in the radio calibration or trouble shooting part of EFRA, despite an approved flash programming, proceed to section 2.2.

2.2 The phone does not start in the test program

Attach a dummy battery and press the On/Off button. Check the display and the current consumption.

If the phone starts (showing the revision of the test program in the display) and consumes 30 – 50 mA, the phone is usually without fault.

Check your equipment.

The following things are necessary for the phone to start in the test program:

Correct battery voltage (4.8 V).

Correct feed voltage to the trouble shooting box (15 V).

The current limitation must be set high enough on both outputs of the power amplifier (2A).

The phone must be started before clicking on the "Startup" in EFRA.

The following signal must be found at the system connector of the phone: TTMS, TFMS, VPPFLASH, GND and VDD.

Correct serial port of the trouble shooting box chosen.

"Mode"-switch should be in position "Service".

A Hardlock connected and installed.

If the fault really is electrical, open the phone and make a visual check of the board.

Make sure that there is not any liquid damage, burned or damaged pads at the system connector or bad soldering of e.g. D600 or D610.

Power up the board and start it by using a pulse at the DCIO (or the On/Off button).

Check the amplitude of MCLK at C680 using the spectrum analyser (>3 dBm). We have been using the following settings: CF – 13MHz, SPAN – 1 MHz, RBW – 10 kHz, VBW – 10 kHz and SWEEP – 30 ms.

If MCLK is too low, the fault usually is due to L340, B301 or a short circuit in C343.

If the fault still remains, try to program the phone again.

If the phone consumes *more than 200 mA*, proceed to section 2.4.3.

If the phone consumes *no current at all*, when the button is pressed, open the phone and check for liquid damage. Also make sure that the keyboard and the keyboard pads are okay and that they are clean.

If there is a signal program in the phone, you have to program it with the test program.

2.3 The phone cannot be programmed

Make sure that:

the battery screws are okay and tightened;

the system connector is not dirty or liquid damaged.

Attach a dummy battery. If the phone consumes current immediately, the fault is usually due to a short circuit of VBATT, but first you must make sure that the isolation of the frame is not in contact with the plus pole of the board.

Start the phone with the On/Off button and check the current consumption.

If the phone consumes *no current at all* when the button is pressed, there is probably liquid damage. Open the phone and check for liquid damage. Also make sure that the keyboard and the keyboard pads are okay and that they are clean.

If the phone consumes more than 200 mA, proceed to section 2.4.3.

If the phone does not start, try to program it on board level.

If the phone does not start in the flash programmer, proceed to section 2.4.1.

If the phone can be programmed, but does not start afterwards or is troublesome in the flash programmer, proceed to section 2.4.2.

If the phone starts after programming, the fault is probably solved, but to eliminate the possibility of intermittent faults make sure that the soldering at D600, D610 or D630 are correct.

2.4 Measuring at a powered circuit board

2.4.1 Does not start in the flash programmer

Make sure that the pads of the system connector are not burned or in any way damaged.

Attach the board to the fixture. Power up the board by keeping DCIO high.

Measure the voltages VDIG (3.2 V) and VCORE (2.5 V).

If any of the voltages are too low, measure the resistance to ground (VDIG > 1 kohm, VCORE > 25 kohms).

If the resistance is correct, replace the corresponding circuit (VDIG - N701, VCORE - N700).

If the resistance is too low, use the schematics. Remove the components one by one (or lift the pin/pins feeding the circuit), that is fed from the short circuited voltage, and measure the resistance after each removal. You have found the faulty component when the resistance is increasing after removal. Do not forget to mount all the components that have been removed. You should also replace the circuits on which you have lifted the pins. The short circuit is usually due to D610, D600 or any of C600, C602-C611, C614, C800, C802-C807, C902, C906 for VDIG and D900 or any of C900, C901, C903-C905 for VCORE.

If any of the voltages are too high, replace the corresponding circuit.

Measure the power reset at C710 (>3 V). If it is lower, the fault is probably due to C710 or N550.

Measure the voltage VRAD/VVCO (3.8 V).

If the voltage is incorrect, measure the resistance between ground and N580:5 (50 kohms).

If the resistance is correct, replace N580.

If the resistance is too low, use the schematics. Remove the components one by one (or lift the pin/pins feeding the circuit), that is fed from the short-circuited voltage, and measure the resistance after each removal. You have found the faulty component when the resistance is raising after removal. Do not forget to mount all the components that have been removed. You should also replace the circuits on which you have lifted the pins. The short circuit is usually due to N550, or any of the 10nF-capacitors on VRAD/ VVCO.

Check the amplitude of the clock, using the oscilloscope, at B301:3 (>0.7 V t-t). You can also use the spectrum analyser to check the amplitude (>1 dBm). We have been using the following settings for the oscilloscope: CF – 13MHz, SPAN – 1 MHz, RBW – 10 kHz, VBW – 10 kHz and SWEEP – 30 ms. A fault of the clock can be due to L340, B301 or a short circuit in C343, D600, N300 or C300. Sometimes the fault is due to N202.

Make sure that the soldering at D600, D610 or D630 are correct. If they are correct and all the feed voltages and the clock are correct, the fault is usually due to D600. The fault can also be due to D610 or D630.

Try to program the phone between each replacement.

2.4.2 Can be programmed, but does not start afterwards or is troublesome in the flash programmer

Make sure that the pads of the system connector are not burned or in any way damaged.

Open the phone and check for liquid damage.

Attach the board to the fixture. Power up the board by keeping DCIO high.

Measure the voltages VDIG (3.2 V) and VCORE (2.5 V).

If any of the voltages are too low, measure the resistance to ground (VDIG > 1 kohm, VCORE > 25 kohms).

If the resistance is correct, replace the corresponding circuit (VDIG - N701, VCORE - N700). If the resistance is too low, use the schematics. Remove the components one by one (or lift the pin/pins feeding the circuit), that is fed from the short circuited voltage, and measure the resistance after each removal. You have found the faulty component when the resistance is raising after removal. Do not forget to mount all the components that have been removed. You should also replace the circuits on which you have lifted the pins. The short circuit is usually due to D610, D600 or any of C600, C602-C611, C614, C800, C802-C807, C902, C906 for VDIG and D900 or any of C900, C901, C903-C905 for VCORE.

If any of the voltages are too high, replace the corresponding circuit.

Measure the voltage VRAD/VVCO (3.8 V).

If the voltage is incorrect, measure the resistance between ground and N580:5 (50 kohms).

If the resistance is correct, replace N580.

If the resistance is too low, use the schematics. Remove the components one by one (or lift the pin/pins feeding the circuit), that is fed from the short circuited voltage, and measure the resistance after each removal. You have found the faulty component when the resistance is raising after removal. Do not forget to mount all the components that have been removed. You should also replace the circuits on which you have lifted the pins. The short circuit is usually due to N550, or any of the 10nF-capacitors on VRAD/ VVCO.

Check the amplitude of the clock, using the oscilloscope, at B301:3 (>0.7 V t- t). You can also use the spectrum analyser to check the amplitude (>1 dBm). We have been using the following settings for the oscilloscope: CF – 13MHz, SPAN – 1 MHz, RBW – 10 kHz, VBW – 10 kHz and SWEEP – 30 ms. A fault of the clock can be due to L340, B301 or a short circuit in C343, D600, N300 or C300. Sometimes the fault is due to N202.

Make sure that the soldering at D600, D610 or D630 are correct. If they are correct and all the feed voltages and the clock are correct, the fault is usually due to D600. The fault can also be due to D610 or D630.

Try to program the phone between each replacement.

2.4.3 Consumes more then 200 mA

Open the phone and check for liquid damage.

Make sure that the pads of the system connector are not burned.

Attach the board to the fixture. Power up the board by keeping DCIO high.

Measure the voltages VDIG (3.2 V) and VCORE (2.5 V).

If any of the voltages are too low, measure the resistance to ground (VDIG >1 kohm, VCORE >25 kohms).

If the resistance is correct, replace the corresponding circuit (VDIG - N701, VCORE - N700).

If the resistance is too low, use the schematics. Remove the components one by one (or lift the pin/pins feeding the circuit), that is fed from the short circuited voltage, and measure the resistance after each removal. You have found the faulty component when the resistance is raising after removal. Do not forget to mount all the components that have been removed. You should also replace the circuits on which you have lifted the pins. The short circuit is usually due to D610, D600 or any of C600, C602-C611, C614, C800, C802-C807, C902, C906 for VDIG and D900 or any of C900, C901, C903-C905 for VCORE.

If any of the voltages are too high, replace the corresponding circuit.

Measure the voltage VRAD/VVCO (3.8 V).

If the voltage is incorrect, measure the resistance between ground and N580:5 (50 kohms).

If the resistance is correct, replace N580.

If the resistance is too low, use the schematics. Remove the components one by one (or lift the pin/pins feeding the circuit), that is fed from the short circuited voltage, and measure the resistance after each removal. You have found the faulty component when the resistance is raising after removal. Do not forget to mount all the components that have been removed. You should also replace the circuits on which you have lifted the pins. The short circuit is usually due to N550, or any of the 10nF-capacitors on VRAD/ VVCO.

Check the amplitude of the clock, using the oscilloscope, at B301:3 (>0.7 V t-t). You can also use the spectrum analyser to check the amplitude (>1 dBm). We have been using the following settings for the oscilloscope: CF – 13MHz, SPAN – 1 MHz, RBW – 10 kHz, VBW – 10 kHz and SWEEP – 30 ms. A fault of the clock can be due to L340, B301 or a short circuit in C343, D600, N300 or C300. Sometimes the fault is due to N202.

Make sure that the soldering at D600, D610 or D630 are correct. If they are correct and all the feed voltages and the clock are correct, the fault is usually due to D600. The fault can also be due to D610 or D630.

Try to program the phone between each replacement.

3 Calibration IQ

3.1 What is calibration IQ

The IQ-filter consists of two parts. The first part is a passive lowpass-filter between the waveform generator in D600 and N202 consisting of R642-R645, C106 and C108. The second part is a software- controlled filter in N202 that is calibrated with a certain test signal from the waveform generator.

When calibrating, the transmitter is powered up in static mode with the test modulation. The peak, that exists at CF-201 kHz related to the highest peak (CF+67 kHz), is measured, and the LPBW/LPQ parameters in Homeros are tuned, until correct suppression (typ -21 dBm) is obtained.




Fig. 3.1

3.2 How to find the fault


Open the phone and check for liquid damage.

Attach the board in the fixture and start the test program.

NOTE! If the card is of type 2, with the EKA power module, remember to attach the negative bias voltage in the fixture.

Change the settings on the spectrum analyser to: SPAN: 1 MHz, RBW: 10 kHz, VBW:10 kHz, SWEEP: 30 ms.

Start the transmitter in static mode with modulation on the middle channel (699) on the DCS 1800-band (Fig. 3.2). If the transmitter does not lock, decrease the sweep current.

*Fig. 3.2*

Make sure that the spectrum looks like in *Fig. 3.1*.

If the spectrum does not look like the figure it is either one of the modulation signals (MODQN, MODQP, MODIN, MODIP) that is missing from D600 or the lowpass-filter to the modulation signals that is faulty (R642-R645, C106, C108).

Measure on the capacitors with an oscilloscope. The signals are sinus shaped with the frequency 67.7 kHz and the amplitude 3.0 V. Compare the signals with each other. The fault is probably on the one modulation signal that differ from the others. If the modulation signals looks good and are in the right phase (90 degrees turned compared to each other) then the fault could be caused by N202.

4 TxVCO

4.1 What is TxVCO – Calibration

In the GSM900-system a phone can communicate with the base station at 124 frequencies in each direction (890.2 - 914.8 MHz for the transmitter and 935.2 - 959.8 MHz for the receiver). In the GSM1800-system it is possible to communicate at 374 frequencies in each direction (1710.2 – 1784.8 MHz for the transmitter and 1805.2 – 1879.8 MHz for the receiver).

The communication between the base station and the phone are done switched. The system makes it possible to change frequency between each burst. For every new burst the transmitter synth of the phone has to lock again at the frequency the base station expects, before activating the transmitter.

Fig 4.1 and *Fig 4.2* shows two simplified diagrams over the lock-on of the Tx-synth. The frequencies are for channel 62 (GSM900) and channel 699(GSM1800).




Fig. 4.1

GSM 1800




Fig. 4.2

The frequency of the transmitter has to lock during a predestinated time. To make the locking time fast enough, the phone uses pre-learned TxVCO-values read from the EEPROM. The lock-on begins with the TxVCO-AC transforming a, for this particular channel, saved EEPROM-value to a start value for the control voltage of the VCO (N390). The voltage is a little bit higher than the expected value when the synth has locked on. By using the start value of the control voltage the VCO generates a transmitter frequency that is only a little too high. The transmitter frequency is fed back through a mixer to the Phase detector (both inside N202). The Phase detector compares the mixed frequency (91 or 52 MHz) with an intern reference signal ($7 \times 13 = 91$ or $4 \times 13 = 52$ MHz). The result of the phase comparison is a DC voltage that controls the VCO. The TxVCO-DAC is disconnected and the Phase detector takes over the adjustment of the control voltage to the VCO. When the transmitter synth has locked on (the Phase detector in N202 has stabilized the control voltage and the frequency), the phone can begin to transmit.

The start value of the synth, the TxVCO value, has to be calibrated due to the differences of tolerance in the components of the transmitter synth. The calibration is performed in switched mode, at two channels: for GSM900 high (channel 94 or 908,8 MHz) and low (channel 30 or 896 MHz) and for GSM1800 high (channel 826 or 1773.0 MHz) and low (channel 570 or 1721.8 MHz). The values for other channels you get by interpolation.

The tables below (Table 4.1 and 4.2) show the limits for the TxVCO – values.

GSM 900

TxVCO	Min	Max	
Ch 30	56	A6	Hex
	86	166	Dec
CH 94	6A	BA	Hex
	106	186	Dec

*Table 4.1***GSM 1800**

TxVCO	Min	Max	
Ch 570	37	87	Hex
	55	135	Dec
CH 826	7E	CE	Hex
	126	206	Dec

Table 4.2

4.2 How to find the fault

Open the phone and check for liquid damage.

Power up the board and start the phone in the test program.

Measure the voltage at C853 and C854. Replace the corresponding capacitor if the voltage is lower than approximately 1.1 V.

NOTE! If the card is of type 2 (roa 117 3258/2 or roa 117 3920/2), remember to attach the negative bias voltage before changing to static mode.

GSM900:

Start the transmitter in static mode at channel 62 (902.4 MHz) and check the amplitude and the frequency. If the frequency is faulty, try to decrease the "Adjust sweep current" until the frequency of the transmitter has locked on. We have been using the following settings on the spectrum analyser while measuring: CF- 902.4 MHz, SPAN- 200 MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30 ms.

If the transmitter locks, start the transmitter in switch mode at middle channel (62) with "DAC 4 value" at FF. We have been using the following settings on the spectrum analyser while measuring: CF- 902.4 MHz, SPAN- 0 MHz, RBW- 300 kHz, VBW- 100 kHz and Sweep- 0.8 ms.

Check if there is an output power (32 dBm) at the antenna plate using the spectrum analyser. If the output power is correct, the phone is probably without fault. Try the phone in the test again.

If there is no switched output power at all or if it is too low, proceed to chapter 14 ("Network problem") section 14.3.1.

If the transmitter does not lock, start the transmitter in static mode again and change the settings for the spectrum analyser to: 954.4 MHz, SPAN- 200 MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30ms.

Check the frequency and the amplitude of the LO-signal at N331:1 (0dBm).

If the amplitude and the frequency is correct, proceed to section 14.2.1.

If the frequency is correct, but the amplitude is too low, check the feed voltage at N331:7 (3.7 V).

If the voltage is correct, replace N331.

If the voltage is incorrect, check VVCO (3.8 V), SYNTON (3.8 V), BANDSEL and V337 with the belonging components.

If the amplitude is correct, but the frequency is incorrect, the fault is usually due to N300. It can also be due to N331 or D600.

If the signal is several MHz wide, replace C313.

(To make a more accurate frequency measuring, try to decrease SPAN to 1 MHz.)

GSM1800:

Start the transmitter in static mode at channel 699 (1747.4 MHz) and check the amplitude and the frequency. If the frequency is faulty, try to decrease the "Adjust sweep current" until the frequency of the transmitter has locked on. We have been using the following settings on the spectrum analyser while measuring: CF- 1747.4 MHz, SPAN- 200 MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30 ms.

If the transmitter locks, start the transmitter in switch mode at middle channel (699) with "DAC 4 value" at FF. We have been using the following settings on the spectrum analyser while measuring: CF- 1747.4 MHz, SPAN- 0 MHz, RBW- 300 kHz, VBW- 100 kHz and Sweep- 0.8 ms.

Check if there is an output power (28-32 dBm) at the antenna plate using the spectrum analyser. If the output power is correct, the phone is probably without fault. Try the phone in the test again.

If there is no switched output power at all or if it is too low, proceed to chapter 14 ("Network problem") section 14.3.1.

If the transmitter does not lock on, start the transmitter in static mode again and change the settings for the spectrum analyser to: 1838.6 MHz, SPAN- 200 MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30ms.

Check the frequency and the amplitude of the LO-signal at N330:1 (0dBm).

If the amplitude and the frequency are correct, proceed to section 14.2.2.

If the frequency is correct, but the amplitude is too low, check the feed voltage at N330:7 (3.7 V).

If the voltage is correct, replace N330.

If the voltage is incorrect, check VVCO (3.8 V), SYNTON (3.8 V), BANDSEL and V338 with the belonging components.

If the amplitude is correct, but the frequency is incorrect, the fault is usually due to N300. It can also be due to N330 or D600.

If the signal is several MHz wide, replace C313.

(To make a more accurate frequency when measuring, try to decrease SPAN to 1 MHz.)

4.2.1 Tx–synth fault for GSM900

Power up the board and enter the test program.
Start the transmitter in static mode at channel 62.

Use the following settings for the spectrum analyser: CF- 902.4 MHz, SPAN- 200 MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30 ms.

Measure the amplitude and the frequency of the signals TXINA and TXINB at C370 and C371 (-13 dBm, the frequency should be 902.4 MHz when the synth has locked). Measure on both sides of the capacitors to make sure that they are not broken.

If the TXIN-signal is too low, the fault is usually due to N390 (9 dBm at N390:6) or its feed voltages. The fault can also be due to too large attenuation in N391, C370 or C371.

If the level of the TXIN-signal is correct, find out if the LO signal (954.4 MHz) is correct. Measure at L331 (-7 dBm).

If the LO signal is correct the fault is probably due to N202, see chapter 18.5.

If it is low or missing, follow the signal back to the VCO (N331:1).

If the signal is low or missing at the VCO, check that the feed voltage, VVCO on N331:7, is correct (3.8 V). Also check the control voltage on N331:5 (2.0 V).

If the control voltage is incorrect, the fault is probably due to N300 or C300.

If the voltages are correct, N331 is probably broken.

4.2.2 Tx–synth fault for GSM1800

Power up the board and enter the test program.
Start the transmitter in static mode at channel 699.

Use the following settings for the spectrum analyser: CF- 1747.6 MHz, SPAN- 200 MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30 ms.

Measure the amplitude and the frequency of the signals TXINA and TXINB at C370 and C371 (-10 dBm, the frequency should be 1747.6 MHz when the synth has locked). Measure on both sides of the capacitors to make sure that they are not broken.

If the TXIN-signal is too low, the fault is usually due to N390 (11dBm at N390:6) or its feed voltages. The fault can also be due to too large attenuation in N391, C370 or C371.

If the level of the TXIN-signal is correct, find out if the LO signal (1838.6 MHz) is correct.

Measure at N202:40,41.

If the LO signal is correct the fault is probably due to N202, see chapter 18.5.

If it is low or missing, follow the signal back to the VCO (N330:1).

If the signal is low or missing at the VCO, check that the feed voltage, VVCO on N330:7, is correct (3.8 V). Also check the control voltage on N330:5 (2.0 V).

If the control voltage is incorrect, the fault is probably due to N300 or C300.

If the voltages are correct, N330 is probably broken.

All values are approximates, measure the exact values for your equipment using an approved phone.

5 VCXO

5.1 What is VCXO

The phone has got a reference crystal of 13 MHz, which signal is used for both the radio and the logic.

The logic uses the clock signal MCLK as master clock and for the synchronisation of the digital circuits of the logic.

The radio uses the 13 MHz signal as a reference signal for frequency regulation of both the transmitter and the receiver.

The frequency fault of both the transmitter and the receiver must be inside the valid limits. The phone has to have the possibility to control the frequency of the reference crystal to be able to maintain the limits during different circumstances. This is possible since the reference crystal is a Voltage Controlled Crystal Oscillator (VCXO). The schematic is shown in the figure below.




Fig. 5.1

The crystal B301, the capacitors C321, C322, C323 and the varicap diode V302 are forming an oscillating circuit. The active part of the oscillating circuit is in N202. By changing the DC voltage of the varicap diode its capacitance changes, this changes the frequency of the oscillating circuit. The control voltage VcxoCont for the varicap diode comes from a DAC in N800. The range of the DAC is between 0 and 3FF Hex, that is equivalent to a control voltage between 0 and 3 V.

The frequency of the oscillating circuit is amplified in N202 and goes to the radio and the logic through two outputs called 13MHz and MCLK.

5.2 VCXO measurements in the radio calibration in EFRA

There are three measurements and one calibration, concerning VCXO, in the radio calibration in EFRA. The measurements are:

1. VCXO Control at DAC 00 Hex;
2. VCXO Control at DAC 3FF Hex;
3. VCXO Control Range.

These three measurements control the adjustment range, in ppm, of the crystal. The measurement is performed as follow:

The transmitter is started in static mode at any channel and the VCXO value 00 Hex.

The output frequency of the transmitter is measured.

The adjustment range in ppm for DAC 00 Hex is measured according to the formula below:

The adjustment range (in ppm) = (The measured frequency – the frequency of the channel) * 1000000 / the frequency of the channel

E.g. channel 699:

The frequency of the channel: 1747.6 MHz

The measured frequency: 1747.4 MHz

$(1747.4 - 1747.6) * 1000000 / 1747.6 = -114 \text{ ppm}$

The abbreviation ppm means "parts per million", i.e. 1 Hz divergence per MHz of the output frequency of the transmitter. Meaning that a difference of one ppm at the middle channel of the transmitter (1747.6 MHz) gives a frequency divergence of 1747.6 Hz.

The VCXO value changes to 3FF and the frequency of the transmitter is measured again. The adjustment range is calculated in the same way, but the result should be positive.

The VCXO Control Range is calculated from the values from the two measurements above. You check the adjustment range for the values between 00 and 3FF Hex.

The measuring of the adjustment range is important to verify that the reference frequency can be controlled enough, up and down.

In Calibration VCXO, the 13 MHz crystal is being trimmed at channel 570. By sending the DAC value 200 Hex and comparing the received frequency to the one for channel 570, an offset is calculated. This offset is used in an algorithm to establish the value for the DAC for the TCXO.

The calibrated VCXO value is somewhere in the middle of 00 and 3FF, Hex.

Table 5.1 shows the limits for the VCXO measurements.

Parameter	Min	Max	Unit
VCXO Control at DAC 00 Hex	-67	-13	ppm
VCXO Control at DAC 3FF Hex	13	67	ppm
VCXO Control Range	40	80	ppm
Calibrated VCXO DAC	262	762	Dec
	106	2FA	Hex

Table 5.1

5.3 How to find the fault

Open the phone and check for liquid damage.

Start the phone in the test program.

Start the transmitter in static mode at middle channel (699). Make sure that the transmitter locks.

Turn off the modulation by selecting "Mod off".

Go to Misc /DAC Parameter.

Set TCXO to 00 Hex. Notice that the DAC value does not change until clicking at "Close".

Measure the DC voltage at C320 (0.3 V).

Set TCXO to 3FF Hex. Notice that the DAC value does not change until clicking at "Close".

Measure the DC voltage at C320 (2.9V).

If both voltages are correct, but any of the VCXO measurements are incorrect, the fault is usually due to B301. Sometimes the fault is due to V302, C321, C322 or C323.

If both voltages are constantly too low, remove C320. Measure the voltages again.

If the voltages are correct now, the fault was a short circuit in the capacitor.

If the fault remains, it is usually due to N800, C853 or C854. (The voltage at C853 and C854 should be 1.1V)

If both voltages are equal, but not 0 V, the fault is almost always due to N800.

If both voltages are correct, but the VCXO calibration is incorrect, the fault is usually due to B301 or V302. Sometimes it is due to C321, C322 or C323.

VCXO faults can be due to N202, but that is not very common.

You can verify that the fault is gone by measuring the output frequency of the transmitter with VCXO-DAC at 00 and 3FF Hex and compare the result with table 5.2.

Parameter	Min	Max	Unit
VCXO Control at DAC 00 Hex	1747.4829	1747.5773	MHz
VCXO Control at DAC 3FF Hex	1747.6227	1747.7171	MHz

Table 5.2 (Applies for channel 699)

6 Calibration RSSI

6.1 What is RSSI

In the mobile phone, the received RF-signal strength is measured and indicated by a function called RSSI, Received Signal Strength Indicator.

During a call in progress the phone measures the current signal strength sequentially from a number of base stations ordered by the switch when setting up the call. The measurement starts at the base station serving cell and continues with the RF-signals of up to 6 surrounding base stations. The measurement cycle is continually repeated.

The logic part of the phone then calculates a number of values of the received RF-signals and reports the amplitude of the RF-signals from the different base station to the switch through a logical channel.

The signal strength report is used in an evaluation process for *Location* and *Handover*, i.e. when the switch evaluates the speech quality, signal strength and traffic parameters to be outside the limit values of the current physical channel and chooses to start a new channel for the connection. A *physical channel* is the combination of a *timeslot* (TS) and a *radio channel* (ARFCN). The physical channel (TS/ARFCN) can be allocated to the current base station or any of the surrounding base stations at handover.

For the speech quality and the MS to Base distance, it is important that the reported measurements of the RF-signal are correct and calibrated towards known values. If the reported values are too high it results in late handovers and bad readability due to the limits that are set out of reach for the MS. The opposite, too low values, provokes the switch to make unnecessary handovers, increased traffic load and perhaps dropped calls by forced release.

The received signal carries information both in *phase* as well as *amplitude*. The phase contains the digital information (speech and signalling data) and is detected in a phase digitizer for further processing in the main program. The amplitude of the received signal is measured in N800, giving a value called RSSI.

RSSI is used for two measurement functions, *electrical* and *numerical* (mean value and momentary value). The electrical value of the RSSI is used to report the signal strength to the switch through the base station as current Rx-level. The numerical RSSI-value is calculated and only used internally in the phone by the DSP.

The RSSI measuring procedure is to compare the strength of the measured signals and compare them to a calibrated scale of reference levels and point out the one closest to the current RF-level. There are two scales, one for GSM900 and one for GSM1800, both are calibrated separately. To create these scales, the MS is calibrated with known RF-signal levels from –110dBm to –40dBm, with a 5dBm increment at a frequency in the Mid ARFCN range (ARFCN 62 is usually used as a mid channel for GSM900 and ARFCN 699 for GSM1800). This procedure is called RSSI calibration.

These 15 RF-signal levels are digitized by the RSSI function and temporarily saved in the RAM memory by a test program. The test program then performs an interpolation and calculates the rest of the (up to 256) reference value positions and loads them into a part of the MS program memory, EEPROM.

Every RF-signal level, that is processed by the RSSI-function, can now be presented in digital form by reading the nearest corresponding reference level from the EE-PROM, with a resolution of 16 bits, and sending it as current Rx-level information to the base station.

These reference levels are unique for every phone since the signal path through every receiver is dependent on unique parameter values. As, for instance, component tolerances, mounting, soldering and so on. Every change, for instance a repair, an adjustment, a component being soldered, a component ageing and so on, brings the possible need of a new calibration.

6.2 How to find the fault

The fault can be due to either an incorrect measurement of the RSSI value or too large losses in the signal path. If the RSSI calibration is incorrect for only one frequency band, GSM900 or GSM1800, the fault is usually in the signal path, see chapter 18 (Sensitivity and Rx-quality) for a hint on where to troubleshoot. To check the measurement of the RSSI value, only one of the frequency bands is needed. We have used the GSM900 band.

Set Rx-amplitude from GSM-test set to **947.4 MHz** and **-50 dBm**. Use a modulated signal (GMSK on).

Open the phone and check for liquid damage.

Attach the board to the fixture and start the test program.

Go to Radio/RSSI Measurement and make a RSSI measurement at **channel 62**.

If the RSSI value is about 0xC8, it is probably okay. But to be sure, measure at -100 dBm (should be about 0x44).

If the RSSI value is 0x00 or 0xFF (for different signal strengths), the fault is usually due to N800 or D600.

If the value is faulty, the problem is probably in N202, N800 or N300.

7 Power Level Calibration

7.1 Introduction

In the GSM 900 system, it is possible for a phone to transmit with 15 different power levels, from 33 dBm (power level 5) to 5 dBm (power level 19). In the GSM1800 system, it is possible for a phone to transmit with 16 different power levels, from 30 dBm (power level 0) to 0 dBm (power level 15). It is best to transmit at as low output power as possible, but with maintained transfer quality, in order to e.g. save current in the battery and restrict the disturbances. The base station evaluates the transfer quality and informs the phone when to change the output power. For the base station to be able to regulate the output power of the phone in a satisfying way, the power levels of the phone have to be as the base station expect. This means that the power levels of the phone have to be calibrated to be accurate enough.

Fig 7.1 shows a very simplified schematic of the power regulation.




Fig. 7.1

The calibrated DAC values are stored in the EEPROM. When the base station orders the phone to transmit at a certain power level, the DAC value for the current power level is taken from the EEPROM and sent to the Power level-DAC in N800. The output voltage POWLEV of the DAC, lets the power regulation of the radio know how large the power should be. N550 uses POWLEV to create the control voltage VREG with *Offset level* and *Full Power level*. It regulates the amplification of the power amplifier. The regulation is fed back by measuring the current consumption of the power amplifier using R412. The signal is called VSENSE.

Table 7.1 (GSM900) and 7.2 (GSM1800) shows the allowed DAC values and the output power goal of the calibration.

Power Level	Output Power (dBm)
5	32.5 \pm 0.3
6	30.5 \pm 0.3
7	29 \pm 0.5
8	27 \pm 0.5
9	25 \pm 0.5
10	23 \pm 0.5
11	21 \pm 0.7
12	19 \pm 0.7
13	17 \pm 0.7
14	15 \pm 0.5
15	13 \pm 0.5
16	11 \pm 0.5
17	9 \pm 0.5
18	7 \pm 0.5
19	5 \pm 0.5

Table 7.1 (GSM 900)

Power Level	Output Power (dBm)
0	30 \pm 0.3
1	28 \pm 0.5
2	26 \pm 0.5
3	24 \pm 0.5
4	22 \pm 0.5
5	20 \pm 0.7
6	18 \pm 0.7
7	16 \pm 0.7
8	14 \pm 0.7
9	12 \pm 0.7
10	10 \pm 0.7
11	8 \pm 0.7
12	6 \pm 0.7
13	4 \pm 0.7
14	2 \pm 0.7
15	0 \pm 0.7

Table 7.2 (GSM1800)

The power calibration is a part of the radio calibration in EFRA. The calibration is performed in 15 steps, from the highest (5) to the lowest (19), for GSM900 and in 16 steps for GSM1800 (0-15), one step for each power level. The computer controls the calibration by setting the Power level DAC for the phone at the current power level and checking the output power using a spectrum analyser or a GSM test set. Default values are used as starting DAC values. The computer changes the DAC value to attain the correct output power for the current power level. The value is temporarily saved in the RAM of the phone. When the computer has attained the right output power for each power level, the values for the power levels not in use are first interpolated, then all DAC values are saved in the EEPROM. If the correct power is not achieved or one of the DAC values is outside of the limits, then the calibration has failed and nothing is written in the EEPROM.

7.2 How to find the fault

If the power calibration failed or if the output power is several dBm too low, open the phone and check for liquid damage.

Make sure that the antenna connector (W101) is okay.

Power up the board and start it in the test program.

Measure the voltage at C833. If it is lower than approximately 1.5 V, replace the capacitor.

For GSM900:

Start the transmitter in switch mode at middle channel (62) and **"DAC 4 value" at FF**. Check if there is enough output power (30- 35 dBm) at the antenna plate using the spectrum analyser. We have been using the following settings while measuring: CF- 902.4MHz, SPAN- 0 Hz, RBW- 300 kHz, VBW- 100 kHz and Sweep- 0.8 ms.

If the output power is correct, the fault can be due to the frame. The fault can also be due to a change in the characteristics in some of the components, participating in the power regulation, because of ageing. For some power levels this can make the output power or the DAC values ending up outside the limits. In that case, the fault is usually due to N400 or N550. The fault can also be due to N800, N390 or D600.

If the output power is too low, measure the control voltage POWLEV at N550:10 using an oscilloscope. It should look like in *Fig 7.2*.




Fig. 7.2

If the control voltage is too low, the fault is usually due to N800. It can also be due to D600.
If the control voltage is correct, measure VREG at N550:16 or N400:4 (type 2 PA 3.5 V, same frequency), N400:7(Type 1 PA).

If VREG is too low, the fault is probably due to N550 or N400.
If VREG is correct, measure the signal Tx at N390:6 (10 dBm).

If the signal Tx is correct at N390:6, check the output power from N400:16 (Type 2 PA28 dBm), N400:4 (Type 1 PA 31 dBm).

If the output power is too low, replace N400.
If the output power is correct at N400 but low or missing at the antenna connector, the fault is probably due to N203.

If the signal Tx is too low at N390:6, measure the feed voltage at N390:3 using an oscilloscope (3.8 V, 215 Hz).

If the feed voltage is correct, the fault is usually due to N390 or N400.
If the feed voltage is incorrect, the fault is usually due to V350 or V351. Make sure that VRAD is okay.

For GSM1800:

Start the transmitter in switch mode at middle channel (699) and "DAC 4 value" at FF. Check if there is enough output power (28- 32 dBm) at the antenna plate using the spectrum analyser. We have been using the following settings while measuring: CF- 1747.6MHz, SPAN- 0 Hz, RBW- 300 kHz, VBW- 100 kHz and Sweep- 0.8 ms.

If the output power is correct, the fault can be due to the frame. The fault can also be due to a change in the characteristics in some of the components, participating in the power regulation, because of ageing. For some power levels this can make the output power or the DAC values ending up outside the limits. In that case, the fault is usually due to N400 or N550. The fault can also be due to N800, N390 or D600.

If the output power is too low, measure the control voltage POWLEV at N550:10 using an oscilloscope. It should look like in *Fig 7.2*.

If the control voltage is too low, the fault is usually due to N800. It can also be due to D600.
If the control voltage is correct, measure VREG at N550:16 or N400:4 (type 2 PA 3.5 V, same frequency), N400:7(Type 1 PA).

If VREG is too low, the fault is probably due to N550 or N400.
If VREG is correct, measure the signal Tx at N390:6 (13 dBm).

If the signal Tx is correct at N390:6, check the output power from N400:26(Type 2 PA31 dBm), C408 (Type 1 PA 28 dBm).

If the output power is too low, replace N400.
If the output power is correct at N400 but low or missing at the antenna connector, the fault is probably due to N203.

If the signal Tx is too low at N390:6, measure the feed voltage at N390:3 using an oscilloscope (3.8 V, 215 Hz).

If the feed voltage is correct, the fault is usually due to N390 or N400.

If the feed voltage is incorrect, the fault is usually due to V350 or V351. Make sure that VRAD is okay.

All the mentioned signal strength levels are approximate, especially when measuring at the signal before the power amplifier, since the output power of the power amplifier radiates back to the probe. You have to consider this when comparing your values with a reference.

8 Intermediate Power Calibration

8.1 What is intermediate power

Intermediate Power is a calibration necessary to do to fulfil the demands of the GSM-specification for the up- and down-ramping of the power and to minimize the transient spectra.

The up- and down-ramping of the control voltage of the power amplifier does not change momentarily from zero-to-max/max-to-zero. That would cause a large number of over tones due to the switch. The up- and down-ramping of the control voltage are instead performed with two help steps. The control voltage then passes through an exponential amplifier and a Bessel low pass filter in N550 where the transient disturbance is reduced. This gives a control voltage without the straight, vertical edges and the sharp corners that produces the over tones. The two help steps in the up- and down-ramping of the power are called Intermediate Power level.

The figure below shows the up-ramping of the control voltage before it passes through the exponential amplifier and the low pass filter, i.e. what the up-ramping steps looks like.




Fig. 8.1

The three power steps Low Intermediate Power level, High Intermediate Power level and Full Power level are set by the power level DAC in N800 and are amplified and filtrated in N550.

Low and High Intermediate Power level uses default values to generate the voltage.

Full power level (5 – 19 for GSM900 and 0 – 15 for GSM1800) is calibrated so that the Power levels are correct according to the GSM – specification.

Intermediate Power level is calculated at the power calibration and is not shown in the test protocol.

9 Transient Spectrum (Spectrum due to Switching)

9.1 What is transient spectrum

In the GSM-system is all communication between the base station and the phone done switched, in shape of bursts. The burst is a squared output power pulse with step up- and down-ramping. Every time the voltage of the squared pulse changes rapidly there will be formed a number of over tones. The over tones have got different frequencies and amplitudes. The amount of over tones and what amplitude they have got depends on how steep the up- and down-ramping is, the higher up- and down-ramping, the higher amplitude and frequency of the over tone. The over tones form a spectrum that is called transient spectrum or "Spectrum due to switching".

To be able to get lower amplitudes for the over tones in the transient spectrum, the up- and down-ramping does not change momentarily from zero-to-max/max-to-zero. Instead this is done with two help steps, these two help steps are called Low and High Intermediate Power level. The figure below shows what the control signal POWLEV from N800 (DAC 2) looks like. The times in the figure are approximate measured at an approved phone at full Power level.




Fig. 9.1

The control voltage POWLEV then passes through an exponential amplifier and a Bessel low pass filter in N550 where the transient disturbance is reduced. This gives a control voltage without the straight, vertical edges and the sharp corners that produces the over tones. The amplified and filtrated control voltage is called VREG and looks like the figure below.




Fig. 9.2

The actual up- and down-ramping are much shorter then other parts of the control voltage. Therefore it is only the up- and down-ramping in the figure that is timely proportional to each other. The proportion for the amplitude is correct at Power level 5 (for GSM900) and Power level 0 (for GSM1800).

The Zero Power level is a voltage level from the DAC that assures no output power at all. The Offset level is the highest possible voltage before the power amplifier starts to transmit. The Offset voltage compensates for the differences of voltage fault between different power amplifiers and is produced in N550.

The tables below show the limits for maximum power levels at transient disturbances.

GSM 900				
Parameter	Min	Normal	Max	Units
Fc +400 kHz	-	-	-19	dBm
Fc -400 kHz	-	-	-19	dBm

Table 9.1

GSM 1800				
Parameter	Min	Normal	Max	Unit
Fc +400 kHz	-	-	-22	dBm
Fc -400 kHz	-	-	-22	dBm

Table 9.2

”Measure Transient Spectra” is a part of the radio calibration in EFRA. It is performed after the power calibration and measures the power levels at the middle channel frequency (± 400 kHz) of the transmitter. The power level must not be higher then -19 dBm for GSM900 and -22 dBm for GSM1800.

9.2 How to measure the transient spectrum

GSM900:

Power up the board and start it in the test program.

Start the transmitter in switched mode at channel 64 and power level 5.

(Before performing a transient spectrum measurement you have to make sure that the spectrum analyser has got the correct amplitude compensation. To do this you use a phone with a known output power and start the transmitter in static mode at power level 5. Then you compensate the spectrum analyser until the correct output power is achieved. Convenient settings for this are: CF – 902.8 MHz, SPAN – 0 MHz, RBW – 300 kHz, VBW – 100 kHz and SWEEP – 0.8ms.)

One method to measure the transient spectrum is to use the following settings at the spectrum analyser: CF – 903.2 MHz, SPAN – 0 MHz, RBW – 30 kHz, VBW – 100 kHz and SWEEP – 6 ms. You measure the highest level of the signal. The easiest way to do it is to use "single sweep" to freeze the picture and "peak search" to find the highest level. The spectrum should look like the figure below.




Fig. 9.3

For the example in the picture we have measured the transient spectrum at channel 64 + 400 kHz. Do the same measurement at channel 64 - 400 kHz, by changing CF at the spectrum analyser to 902,4 MHz. The power level must be inside the limits, i.e. lower than -19 dBm, for both frequencies.

It is very difficult to make an exact transient spectrum measurement on a trouble-shooting site since there are a lot of disturbances in the air. It can be a difference of a few dBm compared to the measurement in EFRA.

GSM1800:

Same as for GSM900, but do not forget to change to GSM1800 and Power level 0 in the test program, also change CF at the spectrum analyser. The Power level must be inside the limits, i.e. lower than -22 dBm, for both frequencies.

9.3 How to find the fault

The fault is usually due to too low amplification in the power amplifier. When the amplification in the power amplifier is lower than normal, but still high enough for the phone to pass the power level calibration, the power amplifier is working at its maximum limit. This can result in over tones in the shape of distortion.

The fault can also be due to a fault in the up- and down-ramping or one of the synths producing over tones.

You must start the phone in the test program and activate the transmitter in static mode at full Power level.

Check the control voltage VREG at N550:16 or N400:4 (type 2 PA 3.5 V, same frequency), N400:7 (Type 1 PA) using the oscilloscope. It should look like in the *Fig. 9.4*. Note that the sweep time are different in the upper picture compared to lower pictures (the upper picture 0.2 ms/square and the lower pictures 10 μ s/square). We have been using a 10 times-probe, which means that the amplitude are 10 times higher in the reality compared to what the picture is showing (500 mV/square instead of 50 mV).




Fig. 9.4

If the up- and down-ramping looks like the pictures above, the fault almost always is due to distortion caused by the power amplifier. Replace N400 and do a new radio calibration. The few times the fault are not due to N400 it is usually N390.

If the up- and down-ramping does not look like the pictures, the fault can be due to the exponential amplifier, the low pass filter or the offset voltage. All three of the parts are functions in N550.

If the offset voltage is too low, the fault is probably due to N550.

If the offset voltage is too high, the fault is probably due to C564. When C564 is faulty, it can be difficult to calibrate the lowest power levels.

If the up- and down-ramping is steeper and/or there is a large curve in the middle of the ramping, it is the low pass filter or the exponential amplifier that is faulty. The fault is due to C561, C562 or N550.

If the up- and down-ramping is considerably shorter than in the pictures, the fault is due to either C560 or N550. When C560 is faulty, it can be difficult to calibrate the lowest power levels.

10 Modulation Spectrum Switched Mode (Spectrum due to Modulation)

10.1 Introduction

10.1.1 Description

In the GSM system the mobile phone (MS) transmitter (Tx) output RF- signal is time-shared, according to the principle of TDMA. This implies the transmitter to be STARTED exactly at a controlled point of time to reach a specific RF-powerlevel within a very short and clearly defined period of time $< 28 \mu\text{S}$. This RF-power levelshift, called *upramp*, must be as smooth and linear as possible during the transition low to high, in order to limit the spectral propagation. The controlfunction for this levelshift is accordingly preprogrammed in three steps, each of which is smoothed in a digital function of a *besselfilter*.

When the transmitter is up at the decided RF-powerlevel, it is ready to send the message in a digital burstformat. The message must be fully completed during a clearly defined period on the timeaxis. Two different time interval exist. It is during this interval, the real significant message is going to be sent. Some of the messages are system information only and some are digital speech frames. But mostly both types in the same data packet. The method chosen for the transmission via the transmitter carrier is decided to be GMSK *digital modulation*. Also during this time interval, the spectral propagation must be limited within a specified bandwidth for the system. Because of that limitation, there will be a compromise between readability / penetration and the available frequency band. More about this in section 10.1.3.

After hopefully a completed message time-lapse, the transmitter shall be STOPPED exactly at a controlled point of time, to return to RF-off level again, within a very short and clearly defined period of time $< 28 \mu\text{S}$. The transmitter RF-powerlevel downshift is called *downramp* and also this must be as smooth and linear as possible during the transition from high to low, in order to limit the spectral propagation. Same control functionality, as in the previous upramp, over three steps and a *besselfilter*, is also utilized for the downramp.

The transmitter RF-powerlevel as a function of time can be seen in *Fig 10.1*.




Fig. 10.1

Time mask for *normal duration burst* 147 bits 542.8 μ S. There is also a shorter *accessburst* 87 bits 321.2 μ S. (not present). Both have the same time period-length for the RF-levelshift.

According to the principle of TDMA and the burst nature of the signal, the output *RF spectrum* results from two effects:

the RF-power levelshift at *upramp* and *downramp*. Designated: Spectrum due to **Switching transients**.

the *digital modulation* process. Designated: **Spectrum due to the Modulation and wide band noise**.

10.1.2 Consequences in spectrum and testing

In digital TDMA-systems as GSM 900 -1800 -1900 the transmitted RF-signal is repeated over time, in a synchronous timepattern. The active time intervals in the system, for the transmitter and the receiver respectively, are called *Timeslot* (TS). In the system, the timeslots are allocated on RF-carriers, in two frequency duplex at an Absolute Radio Frequency Channel Number (ARFCN). This combination of time and frequency TS / ARFCN, is called a *physical channel*. The system also has the ability to change the ARFCN each time the physical channel is opened, in a programmable so called *frequency hopping pattern* controlled by the switch.

The MS consequently has the ability to synchronous follow the *physical channel*, both in the time-domain and in the frequency-domain. Accordingly the MS timing functions are facing specific demands, on precisely switching the transmitter and receiver up and down and for the stability and rapid changing of RF-channel in the frequencygenerator. Due to this rapid RF-levelshift, in both the time- and frequency-domain, unwanted spectrum components are generated and occupying some space in the total spectrumdistribution, in excess to the modulation from the wanted signal.

The two effects of, the RF-power levelshift *upramp / downramp* and the *digital modulation* respectively, are specified separately in GSM 11.10 and 11.20. The measurement method used to analyse separately those two effects is based on the "ringing effect" during the transients and is a measurement in the time domain, at each point in frequency.

In order to get a reliable testresult, the two effects must be separated in two different measurements, which is possible thanks to the fact, they are separated in the time domain. This will also put demands on the instruments, to have the feature of synchronising to the *physical channel* TS / ARFCN, both in normalmode and hoppingmode. And in addition to that also timegating, to make it possible to activate the measurement, between a START point and a STOP point, in the RF-signals time domain. So called *Gated Measurements*.

The effect of the RF-power levelshift, designated Spectrum due to switching transients, will then be possible to separate from the total spectrum by setting the timegate closed and deactivate the instrument for the time interval where switching is present. Gate closed, will exclude measurement results from the instrument video screen.

By adaptation of START and STOP points in the time domain for *Gated Measurements* in spectrum, it will be possible to analyse also this effect of switching. But, that is a measurement not included in the scope of this description.

10.1.3 The actual RF-spectrum

When the MS has a call in progress, the transceiver is switching between receive / transmit, to follow the physical channel according to the principle of TDMA. In the frequency domain around the carrier ARFCN, the transmitter produces a RF-spectrum with an amplitude and bandwidth depending on the Tx RF-power and the two effects of switching and modulation, as we have learned from the previous description. The spectrum is spread over a wide frequency band, but is technically limited by the equipment design and must conform within the GSM spectrum mask.

To verify that the MS really conform to the spec GSM 11.10 it is tested over the frequency band, at integer multiples of the channelseparation 200 kHz, on both sides of the carrier ARFCN specified in a Method of test 13.4 and a Procedure. This test is rather complicated and time consuming and is mandatory for design and production to fulfill the requirements for type approval. But for testing at normal maintenance and repair, it is permitted to reduce the testand simplify for economical reasons, at a reasonable level.

With a Spectrum Analyser set to zero span, resolution bandwidth 30 kHz, peak hold and video bandwidth 100 kHz, it is possible to catch a narrow sample of the spectrum, as a time waveform due to a transmitted burst. By repeating that sample over the time- and frequency - domains for a long raw of consecutive bursts it will be possible to measure the average of the spectrum components selected, in a timegated measurement. The example of such a time waveform as seen in a 30 kHz RBW offset from the carrier, is given in *Fig 10.2*.




Fig. 10.2

Note that in this time waveform spectrum components from both the switching and the modulation are visible. Looking at the timeaxis we know that the transmitter is started before the useful burst at the *upramp*. The instrument is time gated and the START point is set to the beginning of the burst (0%).

At that part of the waveform the spectrum is still affected by the upramp and a peak of switching transients is visible. The beginning of the time waveform is therefor not good for measuring the modulation spectrum.

In the middle of the burst there is a *training sequence* usually called midamble, with an equal bitpattern in every normal burst. This part is not interesting for modulation measurements either.

The part of the waveform that follows after the midamble, called the "Averaging period" in the picture, is the part decided to be measured as the *Spectrum due to the Modulation and wide band noise* by definition in the GSM spec. This period is finished at 90%, before the end of the burst. This is to avoid interference from switching transients at the *downramp*. At the end of the time waveform again spectrum components from the switching is present, because the timegated measurement has got a STOP point at the end of the *downramp* period.

By setting the START- and STOP points to the appropriate timing around the specified period, the modulation spectrum generated by at least 40 of the bits 87 to 132 is measured. The spectrum analyser averages over the gated period and over 50 bursts when the MS is commanded to its maximum power or 200 bursts at the minimum power level.

This measurement is referred to the GSM specification 05.05 s 4.2 Output RF spectrum.

10.1.4 Spectrum due to the modulation and wide band noise

The telephone is connected to a test equipment: Fixture, Computer with a testprogram, Communication Tester or a Spectrum Analyser and a Powersource. The Tx is started at high power level PL 5 in switched mode on an ARFCN in the Mid ARFCN range. At the same time the Rx is switched OFF.

A specific designed base band signal for testing is generated by the testprogram and injected to the Tx- modulator. The signal, only used for testing has a digital pattern combined from a Pseudo Random Bit Sequence (PRBS) and Training Sequence (TSC nr 0). These are combined in a burst with the two datafields filled with PRBS and TSC 0 as the midamble. The signal pattern is designed to give a modulation spectrum, good for testing, that optimally uses the channel bandwidth.

A gated measurement is performed with the Spectrum Analyser set to capture the whole useful part of the burst, i.e. from 0% to 100% in *Fig 10.2*. No matter of the interference from switching transients. Assumed to be negligible.

Each carrier is measured at the time. Beginning with the ARFCN here called Fc. An average of the modulation power content in the spectrum on Fc is taken from 3 repeated bursts. The result will be used as a reference level.

Two more measurements will be done at the adjacent RF-channels + 400kHz and - 400kHz apart from the Fc. But still the Fc as the active modulated carrier. Equally an average of the modulation power content in the spectrum on the adjacent RF-channel is taken from 3 repeated bursts on each of the two RF-channels at the time. The two results from Fc+400kHz and Fc-400kHz are compared to the result from Fc as a reference RF-power level in dBm.

When compared to the reference, each of the two adjacent RF-channels gets a lower value, calculated as a difference in dBc down from the Fc. The smallest difference is the valid measurement result. (Easiest to achieve, but closest to the limit).

This is the measurement result of Spectrum due to the Modulation and wide band noise and will be examined according to the requirements specification in the doc 1524 TEST DATA written and approved by the Ericsson Testengineering and based on the GSM specification.

The requirement is that the absolute RF levels in dBm and the levels in dBc relative to Fc, from all three results must not exceed the limit of a modulation spectrum mask decided in the GSM spec. Any crossing of this limit is considered as a failure.

10.2 How to find the fault

The "Modulation Spectrum Switched Mode" is sometimes called "Spectrum due to modulation" or "Switched Modspectra" and is a measurement in the radio calibration in EFRA. The measurement is done at middle channel with the highest calibrated power level in switched mode, Power level 5 for GSM900 and Power level 0 for GSM1800.

An average value over a number of bursts at carrier wave frequency (902.4 MHz for GSM900 and 1747.6 MHz for GSM1800) is calculated at first.

Then a new average value over some other bursts is calculated, but at a frequency +400 kHz from the carrier wave frequency.

One more average value is calculated, now at a frequency -400 kHz from the carrier wave frequency.

The level (+400 kHz or -400 kHz) with the most faulty value is reported as the measured value related to the carrier wave amplitude.

The measurement "Modulation Spectrum Switched Mode" is very difficult to perform at a trouble shooting bench. Since you only measure at a part of the burst, between the up- and down-ramping, it demands among other things a special trig. You calculate the average value by measuring at a number of bursts at the chosen part. You can measure at correct number of bursts, trig in the correct way (measure at correct part of the burst), calculate the average value and finally relate the value to the output power using a computer (and the appropriate software). But since you do not have access to computer controlled instrument when trouble shooting, you have to use indirect measuring methods, for example checking the static spectra.

A "Modulation Spectrum Switched Mode"- fault usually occurs together with a "Transient Spectra"-fault. Such a fault is usually due to a fault in the up- and down-ramping. If this is the case, start trouble shooting according to chapter 9 ("Transient spectrum").

The fault is usually due to too low amplification in the power amplifier. When the amplification is lower than normal, but still high enough for the phone to pass the Power Level Calibration, the power amplifier is working at its maximum limit. This can result in over tones in the shape of distortion. The fault can also be due to noise at one of the feed voltages of the radio or an appearance of unwanted frequencies (e.g. noise) in the output signal.

Open the phone and check for liquid damage.

Start the phone in the test program.


Start the transmitter of the phone in static mode, without modulation, at channel 62 for GSM900 or channel 699 for GSM1800.

NOTE! If the card is type 2, remember to use the negative bias voltage when changing to static Tx mode.

Compare the spectrum with the one of a working phone. Make sure that the level of the noise is not higher than for a working phone. Sometimes the level of the noise is low, but wide banded. To be able to find the noise during such circumstances you have to check the spectrum at both 1 MHz and 10 MHz SPAN.


The settings for the spectrum analyser are, for GSM900: CF- 902.4 MHz, RBW- 10 kHz, VBW- 10 kHz, Sweep- 30 ms and SPAN 1 MHz, respectively 10 MHz. For GSM1800: CF- 1747.6 MHz, RBW- 10 kHz, VBW- 10 kHz, Sweep- 30 ms and SPAN 1 MHz, respectively 10 MHz.

The spectra should look like the figures below.




1 MHz SPAN, no modulation

Fig. 10.3



10 MHz SPAN, no modulation

Fig. 10.4




10 MHz SPAN, no modulation
Wide banded noise

Fig. 10.5

Turn the modulation on.

Compare the inter modulation products with the one of a working phone. They must not be too high.

A normal spectrum with modulation should look like the figure below.



1 MHz SPAN, modulation set on
Correct spectrum

Fig. 10.6

If there is noise in the spectrum, the fault can be due to noise in one of the feed voltages, VRAD, VVCO or maybe VDIG. Noise can be due to e.g. ageing filter capacitors (usually the electrolytes) or deteriorated performance in the voltage regulators of the radio. If you have got a really good oscilloscope, it is possible to measure the noise. Noise in the spectrum can also come from the synths, either in the PLL-circuit N300, N202 or in one of the VCO's.

If the inter modulation products have not got the right level, proceed to chapter 3 ("Calibration IQ"-fault).

If the static spectrum looks correct, the fault most certainly is due to the power amplifier, N400. Replace the power amplifier and perform a new radio calibration.

If the radio calibration succeeded, the fault was due to the power amplifier.

If the radio calibration failed, the fault can be due to noise in one of the feed voltages VRAD, VVCO or VDIG. Noise can be due to e.g. ageing filter capacitors (usually the electrolytes) or deteriorated performance in the voltage regulators of the radio.

11 EE-prom

11.1 Write to EE-prom

Large amount of data is stored in the RAM memory of the phone during the radio calibration in EFRA. This information is stored permanently in a 16 kB large EE-prom after interpolation. The data transfer is done serially at an I²C-bus (Inter IC). The I²C-bus consists of two lines, I2CDAT for data and I2CCLK for clocking. (The I²C -bus also goes to the display).

The figure below shows a schematic over the data transfer.




Fig. 11.1

11.2 How to find the fault

There is a possibility, in the trouble shooting part of EFRA, to test the communication and a limited part of the function in the self test. The functionality test that is done is the processor writing and reading at a few addresses. If the self test shows w"Check EEPROM Failed", the phone is faulty, but the self test does not display all faults, so there is a possibility for the self test not to detect the fault.

Open the phone and check for liquid damage.

Check the soldering at D600:3, 4.

Check R619, R620.

Make sure that there is not a short circuit against ground at I2CCLK or I2CDAT (usually at the display).

Power up the board and check VDIG (3.2 V).

Mostly it is D630 that is broken (cannot be replaced), but sometimes the fault can also be due to D600.

12 ADC Calibration (Voltage Calibration)

12.1 What is ADC calibration

For the processor to be able to control the phone in a correct way it has to know the current battery voltage. The battery voltage is measured using N550 and N800. N550 compares VBATT and VRAD according to the formula below. The result of the comparison is presented as an analogue voltage VTRACK.

$$0.85 * (VBATT - VRAD) = VTRACK$$

Since the processor needs the information presented in digital form, VTRACK is transformed in an ADC in N800. To make the measurement of the battery voltage precise it is necessary to perform a calibration. The calibration is performed at two voltages (4.5 V and 6.5 V). The corresponding ADC-values are stored in the EEPROM. The ADC-values for other battery voltages are produced by interpolation of the two calibrated voltages.

12.2 How to perform an ADC calibration

Start the phone in the testprogram.

Go to Logic\ ADC Calibrate.

When you have started ADC Calibrate following window is shown, telling you to set the battery voltage on the power supply to 6.5V. When you have done that, click on OK.




Fig. 12.1

A new window shows up, telling you to change the battery voltage to 4.5 V on the power supply. When you have done that, click on OK.




Fig. 12.2

The result is shown in two windows, first "High ADC calibration" (6.5V) and then "Low ADC calibration" (4.5V).




Fig. 12.3




Fig. 12.4

Table 12.1. shows the limits for the ADC-values at the calibration. When calibrating there must be an accuracy of ± 15 mV.

Battery voltage	min	max	
6.5 V	D2	FF	hex
	210	255	dec
4.5 V	32	5F	hex
	50	95	dec

Table 12.1

12.3 How to find the fault

Start the phone in the test program.
Set the battery voltage at 6.5 V.

Measure the exact voltage at VBATT (N550:18) and VRAD (N550:7).
Use the formula in section 12.1 to calculate VTRACK.

Example: VBATT= 6.5 V, VRAD= 3.8 V gives VTRACK 2.3 V

Measure VTRACK on N550:2.
If VTRACK is incorrect, it is due to the feed voltage VRAD or N550.
If VTRACK is correct, go to Logic\Read ADC. Read the value for VTRACK.

If both the voltage VTRACK and the ADC-value are correct there is probably nothing wrong with the phone. Calibrate again.
If only the ADC-value is incorrect, it is usually due to the feed voltage VDIG or N800 and sometimes D600.

13 Current Calibration

13.1 What is current calibration

A simplified diagram for the regulation of the charging current is shown below.




Fig. 13.1

The information about the charging current is achieved by measuring the potential drop over the resistor R553. This potential drop is then transformed in N550 to an analogue voltage, IMEAS. Since the processor needs the information in digital form, IMEAS has to pass through an ADC in N800 on the way to the processor. This information lets the processor know how large the charging voltage is at the moment and adjusts it, using the digital control signal ICONT. The signal ICONT is transformed to the signal CH_SW in N550, with which the transistor V450 is opened and closed.

The processor supervises the charging, using IMEAS to be able to have the average charging current at a constant level, during the charging time.

For the adjusting to be exact, you need to calibrate the charging current. The calibration is performed in two steps:

1. *Zero current calibration* – Measuring the level on IMEAS when there is no charger connected, i.e. DCIO open.
2. *High current calibration* – The same measuring as above, but with DCIO high, and set on a certain voltage and current limitation.

13.2 How to perform a current calibration

Start the phone in the test program.

Go to Logic \Current calibration.

When you start the Current calibration, the window below is shown telling you to set the battery voltage for dummy battery to 5.8 V at the power supply and keep DCIO open. When you have done that, click on OK.




Fig. 13.2

The next window shows the result of the calibration.




Fig. 13.3

A new window is shown telling you to keep the battery voltage at 5.8 V and set the DCIO-voltage on the power supply at 6.8 V with the current limit at 800 mA. Use the same power supply if it is possible to set two different voltages, otherwise use two power supplies.

One way to connect DCIO to the phone is to cut a cable from a battery charger and connect it to the power supplier.




Fig. 13.4

The result is shown in two windows, *fast calibration* and *slow calibration*. The fast calibration is performed after 10-40 ms and verifies that C552 is mounted. The slow calibration is performed after 350 ms and is the real calibration.




Fig. 13.5




Fig. 13.6

The limits for the calibrations are displayed in the table below

Type of calibration	min	max	dec / hex
Zero calibration	23	65	dec
	17	41	hex
High current - Fast	10	98	dec
	0A	62	hex
High current - Slow	101	166	dec
	65	A6	hex

Table 13.1

13.3 How to find the fault

The fault can be in either the current measuring or the logical part/the AD-transforming. You can find out which part is broken by measuring IMEAS and ICONT.

Start the board in the test program.

Set the battery voltage at 4.8 V.

Set DCIO at 6.8 V, but do not connect the DCIO-voltage to the phone.

Measure IMEAS on N550:3 (0 V).

Go to Logic \ Logic/SIM.

Set ICTRL high by pressing ICTRL.

Measure IMEAS again (0.4 V).

Turn off ICTRL.

If the voltage is incorrect, the fault can be due to R553, VRAD or N550.

Connect DCIO to the system connector.

Set ICTRL high.

Measure IMEAS (It varies from 0.4 V to 1.5V).

Set ICTRL low.

If the voltage IMEAS is too high, the fault is usually due to R553 or N550, but sometimes also N800.

If the voltage IMEAS is too low, measure the resistance of V450:1 - V450:4

If the resistance is 0 ohm, there is a short circuit in V450.

If the resistance is correct (high), start the board in the test program and check VRAD.

If VRAD is too low, the fault is probably due to N550, N580 or a short circuit in one of the components fed by VRAD.

If VRAD is correct, set ICTRL high again and measure the voltage on V450:3 (0 V).

If the voltage on V450:3 is too high, measure ICONT on N550:24 (3.2 V).

If ICONT is missing, the fault is probably due to D600.

If ICONT is correct but the voltage on V450:3 is incorrect, the fault is due to N550.

If IMEAS and ICONT are correct, the fault is in the AD-transforming, but first measure the resistance between AGND- J602:4 and GND- J602:10 (0 ohm).

If the resistance is too high, there is a foil damage and the board is not repairable.

If the resistance is correct, the fault usually depends on the feed voltage VDIG or N800, but sometimes on D600.

14 Network Problems

14.1 Find out if the fault is related to Rx or Tx

Connect the phone to a GSM test instrument. GSM test set must be set as active base station and use a test SIM for best result.

Attach a dummy battery and an antenna cable. Start the test program.

Go to: MISC \ Go to call processing.

Try to get serv at - 68.5 dBm input signal.

If the phone cannot get serv, proceed to section 14.2.

If the phone can get serv, proceed to section 14.3.

14.2 The phone cannot get serv

If the phone cannot get serv, then the fault is probably somewhere in the LO-part or the losses in the signal path are too large.

Open the phone and check for liquid damage.

Attach the board to the fixture and start the test program.

If you want to continue to trouble-shoot after signal test, perform “Reset MS” as follow:

1. Cut the battery voltage to the phone.
2. Set the battery voltage again.
3. Start the phone using a pulse on DCIO or the On/Off button.
4. Click on “Reset MS”. It will occur a message window that tells you to start the phone. Click on OK.
5. The test program is running again.

For GSM900: Set Radio in Rx Static mode on channel 62.

Set Rx amplitude from the GSM test set to 947.4 MHz and -50 dBm.

Make sure that the Rx amplitude really is what it should be at the antenna plate using a spectrum analyser. Increase or decrease the amplitude on the GSM- test set if necessary. We have been using the following settings on the spectrum analyser when measuring the transmitter: CF- 947.4 MHz, SPAN- 1 MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30 ms.

For GSM1800: Set Radio in Rx Static mode on channel 699.

Set Rx amplitude from the GSM test set to 1842.6 MHz and -50 dBm.

Make sure that the Rx amplitude really is what it should be at the antenna plate using a spectrum analyser. Increase or decrease the amplitude on the GSM- test set if necessary. We have been using the following settings on the spectrum analyser when measuring the transmitter: CF- 1842.6 MHz, SPAN- 1 MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30 ms.

14.2.1 Fault in the LO

For GSM900: Change CF on the spectrum analyser to 947.4 MHz and increase the SPAN to 200 MHz.

Measure frequency and amplitude on the local oscillator at N331:1 (947.4 MHz, 0 dBm).

If the LO signal is correct there are either too large losses in the signal path, a phase error or a logical fault. Proceed to section 14.2.2.

If the frequency is correct, but the amplitude is too low, check the feed voltage on N331:7 (3.7 V).

If the voltage is correct, replace N331.

If the voltage is incorrect, check VVCO (3.8 V), SYNTON (3.2 V) and V337 with the components that belongs to it.

If the amplitude is correct, but the frequency is incorrect, it is often due to N300. It can also be due to N331 or D600.

If the signal is several MHz wide, replace C313.

If the amplitude and the frequency is correct, decrease SPAN to 1 MHz and measure the LO signal again. If there is noise on the signal, replace N300.

For GSM1800: Change CF on the spectrum analyser to 1842.6 MHz and increase the SPAN to 200 MHz.

Measure frequency and amplitude on the local oscillator at N330:1 (1842.6 MHz, 0 dBm).

If the frequency is correct, but the amplitude is too low, check the feed voltage on N330:7 (3.7 V).

If the voltage is correct, replace N330.

If the voltage is incorrect, check VVCO (3.8 V), SYNTON (3.2 V) and V338 with the components that belongs to it.

If the amplitude is correct, but the frequency is incorrect, it is often due to N300. It can also be due to N330 or D600.

If the signal is several MHz wide, replace C313.

If the amplitude and the frequency is correct, decrease SPAN to 1 MHz and measure the LO signal again. If there is noise on the signal, replace N300.

If the LO signal is correct there are either too large losses in the signal path, a phase error or a logical fault.

14.2.2 Too large losses in the signal path

For GSM900: Measure the signal at N203:5 (-53 dBm).

If the signal is low, the fault is probably due to N203, C225, C227 or L203.

If the signal is missing, check that the pins on N203 has correct voltages (see table below)

N203	pin 2	pin 4	pin 8	pin 10
Rx 900/1800	0 V	3.8 V	3.8 V	0 V

Table 14.1

If the values are correct, the fault is probably due to N203, C225, C227 or L203.
If any of the values are incorrect, there is probably a broken transistor, see schematics.

If the signal is correct at N203:5, continue measuring along the signal path.
At Z200:4 you should have -55 dBm and at Z200:6 -57 dBm.
At N202:10,11 you should have -56 - -58 dBm.

For GSM1800: The easiest point to first measure the signal is at Z201:1 (-54 dBm).

If the signal is low, the fault is probably due to N203, C225, C227, L203 or Z201.
If the signal is missing, check that the pins on N203 has correct voltages (see table below)

N203	pin 2	pin 4	pin 8	pin 10
RxRx 900/1800	0 V	3.8 V	3.8 V	0 V

Table 14.2

If the values are correct, the fault is probably due to N203, C225, C227, L203 or Z201.
If any of the values are incorrect, there is probably a broken transistor, see schematics.

If the signal is correct at Z201:1, continue measuring along the signal path.
At N201:4,6 you should have -60 dBm.
At N202:7,8 you should have approximately the same.

14.2.3 Phase error or logical fault

For measuring phase error, go to Radio \ Sensitivity.

The RF-signal from the GSM test instrument must be non-modulated and the frequency must be in accordance with the chosen channel.

For GSM900: At an input signal of -102 dBm, the phase error should be: PEAK 0-70, RMS 0-15 deg. The highest allowed frequency error is + 2000 Hz.

For GSM1800: At an input signal of -100 dBm should the phase error be: PEAK 0-70, RMS 0-15 deg. The highest allowed frequency error is + 2000 Hz.

When both the Peak phase error and the RMS phase error (sometimes even the frequency error) are too large, it is usually due to a too large attenuation in the signal path.

When both the Peak phase error and the RMS phase error (sometimes even the frequency error) are too large, but all the radio signals have correct amplitude and frequency, it can be due to anyone of N800, D600 or N202.

When the Peak phase error is 1, the RMS phase error is 0 and the frequency error is 20000 Hz it can be a frequency fault on B301 or a fault on N800.

14.3 Connect a call against the instrument at power level 5 (GSM900) or power level 0 (GSM1800) and input signal - 68.5 dBm

If it works, proceed to section 24.4.

If it does not work, it is most likely a Tx related fault.

If it only is at low channels on GSM900 you cannot connect a call, but you can at high channels (GSM900) and at GSM1800, it is usually N390 that is faulty.

Open the phone and check for liquid damage.

Make sure that the antenna connector W101 is not mechanically damaged, unsoldered or dirty (varnish, glue, oxide...).

Power up the board and start the test program.

Measure the voltage on C853 and C854(1.1 V). If the voltage is too low, replace the corresponding capacitor.

For GSM900: Start the transmitter in static mode on channel 62 and check the transmitter's output power and frequency.

NOTE! If the card is type 2, remember to use the negative bias voltage when changing to static Tx mode.

We have used the following settings on the spectrum analyser: CF- 902.4 MHz, SPAN- 200 MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30 ms.

If the transmitter does not lock, first make sure that LO is working (see chapter 14.2.1). If LO is okay, but the transmitter still does not lock or have no output power measure the voltage on N550:16 (VREG 1.2 V).

If VREG is too low, measure the signal POWLEV (1.45 V) on N550:10.

If the voltage POWLEV is too low, check the soldering at N800:61. If the soldering is correct, the fault is usually due to N800. The fault can also be due to D600 or a short circuit in C853 or C854.

If POWLEV is correct the fault is due to a break in R412 (0.1 ohm) (can be verified by measuring the resistance between pin 17 and 18 on N550), N550, or a short circuit of the control voltage VREG caused by N400.

If VREG is too high, measure the signal TXIN on C370 and C371(-10 dBm).Measure on both sides of the capacitors to make sure that they are not broken.

If TXIN has got the right amplitude, check if there is a signal on R402 (Type 1 PA 3 dBm on one side and 7 dBm on the other), N400:9 (Type 2 PA 0 dBm). If the signal is missing it can depend on R400, R401, R402 or for type 2 cards D400. If the signal has got the right amplitude, the fault depends on N400.

If the amplitude on TXIN is too low, measure the signal on N390:6 (9 dBm).

If the signal on N390 has got the right amplitude, the fault probably depends on N391.

If the signal on N390 is missing, measure the feed voltage on N390:3 (3.7 V).

If the feed voltage is correct, the fault probably depends on N390 or BANDSEL is faulty.

If the feed voltage is incorrect, the fault usually depends on Z301, C350, C351, V350, V351 or some of the following voltages are missing: VRAD or TXON. If TXON is missing, check D600.

If VREG is correct, measure the signal TXIN on C370 and C371 (-10 dBm). Measure on both sides of the capacitors to make sure that they are not broken.

If TXIN has got the right amplitude, measure the signal at N400:4 (Type 1 PA 16 dBm), N400:16 (Type 2 PA 12 dBm).

If the signal on N400:4 (Type 1 PA) ,N400:16 (Type 2 PA) is too low, the fault is probably due to N400.

If the signal is too low at the antenna plate, the fault is probably the antenna switch N203, V202, V203 or one of the associated components.

If the amplitude on TXIN is too low, the fault can depend on N391, C370 or C371.

If the transmitter locks, start the transmitter in switch mode on middle channel (62) with “DAC 4 value” on FF. Check if there is output power (30 - 35 dBm) at the antenna plate using the spectrum analyser. We have used the following settings on the spectrum analyser: CF- 902.4 MHz, SPAN- 0 Hz, RBW- 300 kHz, VBW- 100 kHz and Sweep- 0.8 ms.

If there is no output power at all or if it is too low, proceed to section 24.3.1.

If the output power is correct, proceed to section 24.3.2.

For GSM1800: Start the transmitter in static mode on channel 699 and check the transmitter's output power and frequency.

NOTE! If the card is type 2, remember to use the negative bias voltage when changing to static Tx mode.

We have used the following settings on the spectrum analyser: CF- 1747.6 MHz, SPAN- 200 MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30 ms.

Check the frequency of the transmitter (1747.6 MHz). If the frequency is misplaced, try to decrease the “Adjust sweep current” until the frequency of the transmitter locks.

If the transmitter does not lock, first make sure that LO is working (see chapter 14.2.1). If LO is okay, but the transmitter still does not lock or have no output power, measure the voltage on N550:16 (VREG 1.2 V).

If VREG is too low, measure the signal POWLEV (1.45 V) on N550:10.

If the voltage POWLEV is too low, check the soldering at N800:61. If the soldering is correct, the fault is usually due to N800. The fault can also be due to D600 or a short circuit in C853 or C854.

If POWLEV is correct the fault is due to a break in R412 (0.1 ohm) (can be verified by measuring the resistance between pin 17 and 18 on N550), N550, or a short circuit of the control voltage VREG caused by N400.

If VREG is too high, measure the signal TXIN on C370 and C371 (-9 dBm). Measure on both sides of the capacitors to make sure that they are not broken.

If TXIN has got the right amplitude, check if there is a signal on R402 (Type 1 PA 4 dBm on one side and 10 dBm on the other), N400:7 (Type 2 PA 8 dBm). If the signal is missing it can depend on R400, R401, R402 or for type 2 cards D400. If the signal has got the right amplitude, the fault depends on N400.

If the amplitude on TXIN is too low, measure the signal on N390:6 (12 dBm).

If the signal on N390 has got the right amplitude, the fault probably depends on N391.

If the signal on N390 is missing, measure the feed voltage on N390:3 (3.7 V).

If the feed voltage is correct, the fault probably depends on N390 or BANDSEL is faulty.

If the feed voltage is incorrect, the fault usually depends on Z301, C350, C351, V350, V351 or some of the following voltages are missing: VRAD or TXON . If TXON is missing, check D600.

If VREG is correct, measure the signal TXIN on C370 and C371 (-9 dBm). Measure on both sides of the capacitors to make sure that they are not broken.

If TXIN has got the right amplitude, measure the signal at N400:5 (Type 1 PA 20 dBm), N400:26 (Type 2 PA) (14 dBm).

If the signal on N400:5 (Type 1 PA) ,N400:26 (Type 2 PA) is too low, the fault probably depends on N400.

If the signal is too low at the antenna plate, the fault is probably the antenna switch N203, V202, V203 or one of the associated components.

If the amplitude on TXIN is too low, the fault can depend on N391, C370 or C371.

If the transmitter locks, start the transmitter in switch mode on middle channel (699) with “DAC 4 value” on FF. Check if there is output power (28 - 32 dBm) at the antenna plate using the spectrum analyser. We have used the following settings on the spectrum analyser: CF- 902.4 MHz, SPAN- 0 Hz, RBW- 300 kHz, VBW- 100 kHz and Sweep- 0.8 ms.

If there is no output power at all or if it is too low, proceed to section 24.3.1.

If the output power is correct, proceed to section 24.3.2.

14.3.1 Low or no switched output power

For GSM900: Measure the control voltage POWLEV on N550:10 (Fig. 14.1) using an oscilloscope.




Fig. 14.1

If the control voltage is too low, check the soldering at N800:61. If the soldering is correct, the fault usually depends on N800. It can also depend on D600 or a short circuit in C853 or C854. If the control voltage is correct, measure VREG at N550:16 or N400:4 (type 2 PA 3.5 V, same frequency), N400:7(Type 1 PA).

If VREG is too low, the fault is probably due to N550 or N400.

If VREG is correct, measure the signal Tx at N390:6 (9 dBm).

If the signal Tx is correct at N390:6, check the output power from N400:16 (Type 2 PA 28 dBm), N400:4 (Type 1 PA 31dBm).

If the output power is too low, replace N400.

If the output power is correct at N400 but low or missing at the antenna connector, the fault is probably due to N203.

If the signal Tx is too low at N390:6, measure the feed voltage at N390:3 using an oscilloscope (3.8 V, 215 Hz).

If the feed voltage is correct, the fault is usually due to N390 or N400.

If the feed voltage is incorrect, the fault is usually due to V350 or V351. Make sure that VRAD is okay.

For GSM1800: Measure the control voltage POWLEV on N550:10 (*Fig. 14.1*) using an oscilloscope.

If the control voltage is too low, check the soldering at N800:61. If the soldering is correct, the fault usually depends on N800. It can also depend on D600 or a short circuit in C853 or C854. If the control voltage is correct, measure VREG at N550:16 or N400:4 (type 2 PA 3.5 V, same frequency), N400:7(Type 1 PA).

If VREG is too low, the fault is probably due to N550 or N400.

If VREG is correct, measure the signal Tx at N390:6 (11dBm).

If the signal Tx is correct at N390:6, check the output power from N400:26 (Type 2 PA 30 dBm), C408 (Type 1 PA 28 dBm).

If the output power is too low, replace N400.

If the output power is correct at N400 but low or missing at the antenna connector, the fault is probably due to N203.

If the signal Tx is too low at N390:6, measure the feed voltage at N390:3 using an oscilloscope (3.8 V, 215 Hz).

If the feed voltage is correct, the fault is usually due to N390 or N400.

If the feed voltage is incorrect, the fault is usually due to V350 or V351. Make sure that VRAD is okay.

All the mentioned signal strength levels are approximately, especially when measuring at the signal before the power amplifier, since its output power radiates back to the probe. This has to be considered when comparing measured values with reference values.

14.3.2 The switched output power is correct, but connecting a call is not possible

Turn off switch Tx.

Set the spectrum analyser to: SPAN- 1 MHz, RBW- 10 kHz, VBW- 10 kHz, SWEEP- 30 ms.

Start the transmitter in static mode with modulation on the middle channel (62 for GSM900 and 699 for GSM 1800).

Make sure that the spectra look like the one in *Fig. 14.2*.




Fig. 14.2

If it looks like the one in the figure, but the phone cannot connect a call, is it a logical related fault and usually depends on D600 or N800.

If the spectra does not look like the figure, it is either one of the modulation signals (MODQN, MODQP, MODIN, MODIP) that is missing from D600 or a faulty low pass filter to the modulation signals (R642, R643, R644, R645, C106 and C108). Measure with an oscilloscope on the capacitors. The signals are sinus shaped with the frequency 67.7 kHz and amplitude 3.0 V. Compare the signals with each other. The fault is on the modulation signal that differs from the others. If the modulation signals looks good and are in the right phase (90 degrees turned compared to each other) then the fault could be caused by N202.

14.4 Read the Rx level value from the instrument while the call is still connected

If the Rx level value is at 40- 46 steps, make sure that the output power is 31-35 dBm (GSM900, power level 5) or 28-32 dBm (GSM1800, power level 0).

If the value is correct there is probably nothing wrong with the phone.

Decrease the input signal to -102 dBm (for GSM900) and make sure that the Rx level is at 6- 12 steps and the Rx quality is at 0- 2 steps. For GSM1800 the input signal should be -100.5 dBm, Rx level 7-13 and Rx quality 0-2 steps. If these values are correct, the phone is probably without fault. Try to run the phone through the test again.

If the phone passes the test, but cannot connect a call against the “real” network, make sure that the phone is not *locked out of the system due to theft*. If it is not, replace D600.

If the output power is moving, open the phone and make sure that the antenna connector is not damaged, dirty or badly soldered.

If the output power is too low, go back to section 14.3.1.

If Rx quality is too high, go to chapter 18 (“Sensitivity (Rx quality)”-fault).

If Rx level is too high, go to chapter 19 (“Rx level”-fault).

15 Phase and Frequency Error

15.1 What is "Phase and Frequency Error"

Phase and frequency error is a measurement in the Go/No Go – test where you check how big the phase and frequency variations of the transmitter are during a connected call.

The phase and frequency fault is measured during 20 bursts. For GSM900, use power level 5 and low channel (anyone between 1 and 5). For GSM1800, use power level 0 and low channel (anyone between 512 and 521).

The phase fault is presented as RMS and peak. RMS is the average value during the 20 bursts and peak is the largest phase divergence measured at anyone of the 20 bursts.

The table below shows the limits for phase and frequency fault.

GSM 900/1800

Parameter	Value	Unit
Max RMS phase error	15	deg
Max peak phase error	70	deg
Max frequency error	2000	Hz

Table 15.1

15.2 How to find the fault

Phase and frequency error is a difficult measurement to perform, since the requirements on e.g. instrument, cables and connections are very hard. Therefore the fault is usually due to shabby connections or bad cables at the test site.

If the phone really is faulty, open it and check for water damage.

Make sure that the antenna connector is not damaged or dirty (dust, varnish or oxide).

Replace the frame and try again.

The fault can also depend on a change in the characteristic of the transmitter, due to ageing or an incorrect calibration. Before you start to trouble shoot, perform a new radio calibration in EFRA and test the phone again to eliminate this kind of fault. Notice that the calibration demands test program in the phone while the Go/No Go –test demands signal program.

The few times the fault is electrical, is it usually due to B301, N400 or N390.

16 Output Power

16.1 What is "Output Power"

Output power is a part of the measurement in the Go / No Go – test that checks what output power the transmitter gives at the highest, lowest and middle calibrated power level, at high, low and middle channels. The tables 16.1 and 16.2 shows channel- and power level – definition.

	GSM900	GSM1800
Low channel	Any channel 1..5	Any channel 512..517
Middle channel	Any channel 60..65	Any channel 697..702
High channel	Any channel 120..124	Any channel 880..885

Table 16.1

	GSM900	GSM1800
Lowest Power level	19	15
Middle Power level	Anyone from 10 to 14	Anyone from 6 to 10
Highest Power level	5	0

Table 16.2

Table 16.3 and 16.4 are showing the output power at controlled power level, according to table 16.2.

GSM900

Power level	Output power (dBm)	Tolerance (dBm)
5	33	±2
10	23	±3
11	21	±3
12	19	±3
13	17	±3
14	15	±3
19	5	±5

Table 16.3

GSM1800

Power level	Output power (dBm)	Tolerance (dBm)
0	30	± 2
6	18	± 3
7	16	± 3
8	14	± 3
9	12	± 4
10	10	± 4
15	0	± 5

Table 16.4

If the output power value is higher than in table 16.3, go to section 16.2.

If the output power value is lower than in table 16.3, go to section 16.3.

16.2 The output power is too high

When the output power is too high (usually a few dBm over the limit), it is usually due to a change in characteristic, because of ageing, in some of the components in the power regulation. The same thing happens when you replace e.g. N400, N550 or N800. The only thing necessary to do is a new power calibration (a part of the Radio calibration in EFRA).

16.3 The output power is too low

If the output power is only a little too low (not more than 2 dBm), the fault can be due to a change in characteristic, because of ageing, in some of the components in the power regulation. The fault can also be due to a faulty back cover or antenna connector. Try to perform a new power calibration (a part of the radio calibration in EFRA).

If the power calibration failed or the output power is several dBm too low, open the phone and check for liquid damage. Make sure that the antenna connector (W101) is without fault.

Power up the board and start it in the test program.

Measure the voltage at C853 and C854 (1.1 V). If the voltage is lower, replace the corresponding capacitor.

For GSM900: Start the transmitter in switch mode at middle channel (62) with "DAC 4 value" at FF. Check if there is enough output power (30- 35 dBm) at the antenna plate, use the spectrum analyser. We have been using the following settings on the spectrum analyser while measuring: CF- 902.4MHz, SPAN- 0 Hz, RBW- 300 kHz, VBW- 100 kHz and Sweep- 0.8 ms.

If the output power is correct, the fault was either the back cover or the antenna connector.

If the output power is too low, measure the control voltage POWLEV at N550:10 using an oscilloscope.




Fig. 16.1

If the control voltage is too low, check the soldering at N800:61. If the soldering is correct, the fault usually depends on N800. It can also depend on D600 or a short circuit in C853 or C854. If the control voltage is correct, measure VREG at N550:16 or N400:4 (type 2 PA 3.5 V, same frequency), N400:7 (Type 1 PA).

If VREG is too low, the fault is probably due to N550 or N400.

If VREG is correct, measure the signal Tx at N390:6 (9 dBm).

If the signal Tx is correct at N390:6, check the output power from N400:16 (Type 2 PA 28 dBm), N400:4 (Type 1 PA 31 dBm).

If the output power is too low, replace N400.

If the output power is correct at N400 but low or missing at the antenna connector, the fault is probably due to N203.

If the signal Tx is too low at N390:6, measure the feed voltage at N390:3 using an oscilloscope (3.8 V, 215 Hz).

If the feed voltage is correct, the fault is usually due to N390 or N400.

If the feed voltage is incorrect, the fault is usually due to V350 or V351. Make sure that VRAD is okay.

For GSM1800: Start the transmitter in switch mode at middle channel (699) with "DAC 4 value" at FF. Check if there is enough output power (28- 32 dBm) at the antenna plate, use the spectrum analyser. We have been using the following settings on the spectrum analyser while measuring: CF- 1747.6MHz, SPAN- 0 Hz, RBW- 300 kHz, VBW- 100 kHz and Sweep- 0.8 ms.

If the output power is correct, the fault was either the back cover or the antenna connector.

If the output power is too low, measure the control voltage POWLEV at N550:10 (*Fig. 16.1*) using an oscilloscope.

If the control voltage is too low, check the soldering at N800:61. If the soldering is correct, the fault usually depends on N800. It can also depend on D600 or a short circuit in C853 or C854. If the control voltage is correct, measure VREG at N550:16 or N400:4 (type 2 PA 3.5 V, same frequency), N400:7 (Type 1 PA).

If VREG is too low, the fault is probably due to N550 or N400.

If VREG is correct, measure the signal Tx at N390:6 (11dBm).

If the signal Tx is correct at N390:6, check the output power from N400:26 (Type 2 PA 30 dBm), C408 (Type 1 PA 28 dBm).

If the output power is too low, replace N400.

If the output power is correct at N400 but low or missing at the antenna connector, the fault is probably due to N203.

If the signal Tx is too low at N390:6, measure the feed voltage at N390:3 using an oscilloscope (3.8 V, 215 Hz).

If the feed voltage is correct, the fault is usually due to N390 or N400.

If the feed voltage is incorrect, the fault is usually due to V350 or V351. Make sure that VRAD is okay.

All the mentioned signal strength levels are approximately, especially when measuring at the signal before the power amplifier, since its output power radiates back to the probe. This has to be considered when comparing measured values with reference values.

17 Burst Timing (Power Time Template)

17.1 What is burst timing

The GSM system uses TDMA (Time Division Multiple Access). The radio spectrum is divided into both frequency band and time slots. The frequency band for GSM900 is divided in 124 frequencies (per direction) and the frequency band for GSM1800 is divided in 374 frequencies (per direction). Both of the frequency bands has got eight time slots (channels) per frequency. All information (speech and system information) are encoded and transmitted as a burst in a time slot. Since several channels are sharing the same frequency it is vital for every burst to start and end at the correct time. The GSM specification describes the amplitude/time relation for the burst. The figure below shows the amplitude limits for Power level 5 - 15 (GSM900) and 0 - 15 (GSM1800) during one burst.




Fig. 17.1

Burst timing is a part of the measurement in the Go/ No Go- test. You can get a good look of the burst by checking the amplitude of the burst at some time spots of the raise and fall slope of the burst. This let you know if the burst is within the limit. The tables below show the limits of the timing for all power levels in GSM900 and GSM1800.

GSM900

Parameter	Power level	Max value	
		Relative	Absolute
Power at -28 μ s	5 - 19	-59 dBc	-36 dBm
Power at -18 μ s	5 - 19	-30 dBc	-17 dBm
Power at -10 μ s	5 - 15	-6 dBc	
Power at -10 μ s	16	-4 dBc	
Power at -10 μ s	17	-2 dBc	
Power at -10 μ s	18-19	-1 dBc	
Power at 0 μ s	5-19	-1 dBc	
Power at 542.8 μ s	5-19	-1 dBc	
Power at 552.8 μ s	5-15	-6 dBc	
Power at 552.8 μ s	16	-4 dBc	
Power at 552.8 μ s	17	-2 dBc	
Power at 552.8 μ s	18-19	-1 dBc	
Power at 560.8 μ s	5-19	-30 dBc	-17 dBm
Power at 570.8 μ s	5-19	-59 dBc	-54 dBm

Table 17.1

GSM 1800

Parameter	Power level	Max value	
		Relative	Absolute
Power at -28 μ s	0 - 15	-48 dBc	-48 dBm
Power at -18 μ s	0 - 15	-30 dBc	-20 dBm
Power at -10 μ s	0 - 10	-6 dBc	
Power at -10 μ s	11	-4 dBc	
Power at -10 μ s	12	-2 dBc	
Power at -10 μ s	13-15	-1 dBc	
Power at 0 μ s	0-15	-1 dBc	
Power at 542.8 μ s	0-15	-1 dBc	
Power at 552.8 μ s	0-10	-6 dBc	
Power at 552.8 μ s	11	-4 dBc	
Power at 552.8 μ s	12	-2 dBc	
Power at 552.8 μ s	13-15	-1 dBc	
Power at 560.8 μ s	0-15	-30 dBc	-20 dBm
Power at 570.8 μ s	0-15	-48 dBc	-48 dBm

Table 17.2

17.2 How to find the fault

Usually the fault is due to an incorrect power calibration. The intermediate power level (see separate chapter for further information) is also measured at the power calibration, it has a direct effect on the raise and fall slope of the burst. If the fault is electrical it is usually due to N550 or N400, but it can also be due to C561 or C562.

18 Sensitivity (Rx Quality)

18.1 What is Rx quality- fault

The base-station sends out a pattern of bits which the phone loops back to the base-station. The base-station then compares the original pattern with the one the phone sent back and calculates a percentage on the difference. This percentage is used to measure the Rx quality. This calculation is performed during a call, for GSM900 at -102 dBm RxTx-signal and power level 5 at low, middle and high channel (1, 62 and 124). For GSM1800 at -100 dBm Rx-signal and power level 0 at low, middle and high channel (512, 699 and 885). Rx quality should be 0-2 steps. If it is higher on any of the channels then it is almost always a receiving problem.

18.2 How to find the fault

Generate a signal with a GSM-test instrument and measure the signal path on the board with a spectrum analyser. Then compare the signal strength with earlier measured values (i.e. compare against a reference-board). The signal path is partly different for GSM900 and GSM1800. For GSM900 proceed to section 18.3 and for GSM1800 to section 18.4.

18.3 GSM 900

Open the phone and check for liquid damage.

Attach the board to the fixture and start the test program.

Set Radio in Rx Static mode on channel 62 (*Fig. 18.1*). Static Rx activates when you have clicked on the Apply-button.




Fig. 18.1

Set Rx-amplitude from GSM-test set to 947.4 MHz and -50 dBm. Use a modulated signal (GMSK on), since the Rx signal otherwise has the same frequency as the LO signal, which makes it difficult to measure.

We have used the following settings on the spectrum analyser while measuring Rx: CF- 947.4 MHz, SPAN- 1MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30ms (*Fig. 18.2*).

Make sure that the attenuation on the spectrum analyzer is correct before measuring.




Fig. 18.2

Measure the signal at N203:5 (-53 dBm). (All values in this chapter has an accuracy of +/- 3 dBm)

If the signal is low, the fault is probably due to N203, C225, C227 or L203.

If the signal is missing, check that the pins on N203 has correct voltages (see table below)

N203	pin 2	pin 4	pin 8	pin 10
Rx 900/1800	0 V	3.8 V	3.8 V	0 V

Table 18.1

If the values are correct, the fault is probably due to N203, C225, C227 or L203.

If any of the values are incorrect, there is probably a broken transistor, see schematics.

If the signal is correct at N203:5, continue measuring along the signal path.

At Z200:4 you should have -55 dBm and at Z200:6 -57 dBm.

At N202:10,11 you should have -56 - -58 dBm.

If the Rx signal is okay at N202, find out if the LO signal (947,4 MHz) is correct. Measure at L331 (-7 dBm).

If the LO signal is correct the fault is probably due to N202, see chapter 18.5.

If it is low or missing, follow the signal back to the VCO (N331:1) (0 dBm).

If the signal is low or missing at the VCO, check that the feed voltage, VVCO on N331:7, is correct (3.7 V). Also check the control voltage on N331:5 (1.9 V).

If the control voltage is incorrect, the fault is probably due to N300 or C300.

If the voltages are correct, N331 is probably broken.

18.4 GSM 1800

Open the phone and check for liquid damage.

Attach the board to the fixture and start the test program.

Set Radio in Rx Static mode on channel 699 (*Fig. 18.3*). Static Rx is active after you have clicked on the Apply-button.




Fig. 18.3

Set Rx-amplitude from GSM-test set to 1842.4 MHz and -50 dBm. Use a modulated signal (GMSK on), since the Rx signal otherwise has the same frequency as the LO signal, which makes it difficult to measure.

We have used the following settings on the spectrum analyser while measuring Rx: CF- 1842.4 MHz, SPAN- 1MHz, RBW- 10 kHz, VBW- 10 kHz and Sweep- 30ms (*Fig. 18.4*).

Make sure that the attenuation on the spectrumanalyzer is correct before measuring




Fig. 18.4

The easiest point to first measure the signal is at Z201:1 (-53 dBm). (All values in this chapter has an accuracy of +/- 3 dBm)

If the signal is low, the fault is probably due to N203, C225, C227, L203 or Z201.

If the signal is missing, check that the pins on N203 has correct voltages (see table below)

N203	pin 2	pin 4	pin 8	pin 10
Rx 900/1800	0 V	3.8 V	3.8 V	0 V

Table 18.2

If the values are correct, the fault is probably due to N203, C225, C227, L203 or Z201.

If any of the values are incorrect, there is probably a broken transistor, see schematics.

If the signal is correct at Z201:1, continue measuring along the signal path.

At N201:4,6 you should have -60 dBm.

At N202:7,8 you should have approximately the same.

If the Rx signal is okay at N202, find out if the LO signal (1842.6 MHz) is correct. Measure at N202:40,41.

If the LO signal is correct the fault is probably due to N202, see chapter 18.5

If it is low or missing, follow the signal back to the VCO (N330:1).

If the signal is low or missing at the VCO, check that the feed voltage, VVCO on N330:7, is correct (3.8 V). Also check the control voltage on N330:5 (2.0 V).

If the control voltage is incorrect, the fault is probably due to N300 or C300.

If the voltages are correct, N330 is probably broken.

18.5 No fault in the signal paths

If the attenuates in the signal path are correct, the fault can depend on noise on some of the feed voltages or noise on the control voltage to N330 and 331 (Noise on the control voltage is mainly due to N300 or C313). The fault can also be caused by N800, D600 or N202.

All values are approximate, measure the exact values for your equipment on an operating phone.

19 Rx Level

19.1 What is Rx level fault

The phone receives a signal from the base station. The received signal strength is measured with an ADC. A high input signal gives a high value out from the ADC. The phone is calibrated for input signals between -110 dBm and -40 dBm, for every step (0-255) out from the ADC there is an address in the EEPROM where the calibrated value is stored. The phone compares the measured value and sends back the information about the signal strength to the base station. The base station calculates the Rx-level value by comparing the systems lowest signal strength according to the GSM-specification (-110 dBm) with the value of signal strength that the phone sends back.

$110 - (\text{the absolute value of the value of signal strength from the phone}) = \text{Rx level}$

E.g.: The phone measures the signal strength to -102 dBm.

$\text{Rx level} = 110 - 102 = 8$

When there is an Rx-level fault the calculated value in the EEPROM does not correspond with the input signal, i.e. the phone experience the signal to be stronger or weaker then its real value.

19.2 How to verify an Rx-level fault

For GSM900, connect a call toward the GSM test instrument at an optional channel (1-124) with the input signal at -102 dBm and powerlevel 5.

For GSM1800, connect a call toward the GSM test instrument at an optional channel (512-885) with the input signal at -102 dBm and powerlevel 0.

Read the Rx-level value on the GSM test instrument.

Increase the signal strength to -68.5 dBm.

Read the Rx-level value on the GSM test instrument.

The Rx level value should be as in table below, for each channel.

Rx level	min	max
-102dBm	6	12
-68.5dBm	40	46

Table 19.1

19.3 The Rx level is too high

When the Rx level is too high (some steps above the limit) it is often due to some component in the signal path that has changed characteristics because of ageing. The only thing you have to do is a new RSSI-calibration.

19.4 The Rx level is too low

When the Rx level is too low (some steps under the limit) and the Rx quality is 0, it is often due to some component in the signal path that has changed characteristics because of ageing. It is advisable to do a new RSSI-calibration.

If it is Rx quality problem or if the RSSI-calibration did not help or if it is a big Rx level fault, go to chapter 18 (“Sensitivity (Rx quality)”), section 18.2.

20 Audio

20.1 Measurements in EFRA

The figure below shows a simplified schematic over the paths of the audio signals when measuring.




Fig. 20.1

In the trouble shooting part of EFRA there is several ways to test the audio function. There are five different ways to connect an audio signal.

1. ATMS – Earphone: The input signal is taken from the ATMS pin (pin 2) of the system connector. The signal passes a Tx filter (band pass 300- 3400 Hz) and connects through the side tone switch to the Rx part. In the Rx part the signal passes a Rx filter (band pass 300- 3400 Hz) and is amplified, then it is connected to the earphone connector (J810) through BEARP and BEARM.

2. Mic – AFMS: The input signal is taken from the microphone pads (X830). The signal is amplified, passes a Tx filter (band pass 300- 3400 Hz) and connects through the side tone switch to the Rx part. In the Rx part the signal passes a Rx filter (band pass 300- 3400 Hz), then it is amplified and connected to the AMFS pin (pin 1) of the system connector.
3. Mic – CPU – Earphone: The input signal is taken from the microphone pads (X830). The signal is amplified, passes a Tx filter (band pass 300- 3400 Hz) and is then AD converted in N800. The data is sent as PCM code through PCMULD to D900 where the signal is speech coded. The speech coded information is sent to the processor through DSPULD for further coding. The signal is fed back in reverse order. It is decoded in the processor, sent back to D900 through DSPDLN for speech decoding. Then it is sent to N800, through PCMDLN, for DA conversion in the PCM decoder. The signal is filtered and amplified, then connected to the earphone connector (J810) through BEARP and BEARM.
4. ATMS – CPU – AFMS: The input signal is taken from the ATMS pin (pin 2) of the system connector. The signal passes a Tx filter (band pass 300- 3400 Hz) and is AD converted in N800. The data is sent as PCM code through PCMULD to D900 where the signal is speech coded. The speech coded information is sent to the processor through DSPULD for further coding. The signal is fed back in reverse order. It is decoded in the processor, sent back to D900 through DSPDLN for speech decoding. Then it is sent to N800, through PCMDLN, for DA conversion in the PCM decoder. The signal is filtered and amplified, then connected to the AMFS pin (pin 1) of the system connector.
5. ATMS – PCM – AFMS: The input signal is taken from the ATMS pin (pin 2) of the system connector. The signal passes a Tx filter (band pass 300- 3400 Hz) and is AD converted in N800. The data is sent as PCM code through PCMULD to D900 where the signal is speech coded. The signal is fed back in reverse order, speech decoded in D900, sent back through PCMDLN to be DA converted in a PCM decoder and filtered in N800. The signal is amplified and then connected to the AMFS pin (pin 1) of the system connector.

20.2 How to find the fault

The trouble shooting part assumes that the microphone, with the elastomer, and the earphone are faultless and correctly mounted.

Start the phone (assembled) in the test program.

Go to Audio / Audio.

Test the five different audio paths.

An appropriate signal for the audio signal generator is 1 kHz and 100 mVrms or 280mVp-p sinus.

If you are using a trouble shooting box, make sure that the switch "AUDIO IN" is in position ATMS, the switch "AUDIO SELECT" in position AFMS and the switch "MEAS OUT" in position AUDIO.

At the test "ATMS – Earphone" you should hear the chosen input signal (1 kHz) in the earphone.

At the test "Mic – AFMS", a whistle in the microphone should be seen as a sinus shaped curve on the oscilloscope.

At "ATMS – PCM – AFMS" the chosen input signal should be seen at the oscilloscope (input signal 1 kHz, 100 mVrms or 280mVp-p sinus gives an output signal of 120mVrms or 340mVp-p).

At "ATMS – CPU – AFMS" the chosen input signal should be seen at the oscilloscope (input signal 1 kHz, 100 mVrms or 280mVp-p sinus gives an output signal of 120mVrms or 340mVp-p).

At "Mic – CPU – Earphone" you should hear your self, in the earphone, if you whistle or talk into the microphone.

If only the microphone part is out of order, proceed to section 20.3.

If only the earphone part is out of order, proceed to section 20.4.

If only the ATMS input part is out of order, proceed to section 20.5.

If only the AFMS output part is out of order, proceed to section 20.6.

If only the CPU-loops are out of order, proceed to section 20.7.

If both the CPU-loops and the PCM-loop are out of order, but the side tone (ATMS – Earphone and Mic - AFMS) is working, proceed to section 20.8.

If none of the audio paths is working, proceed to section 20.9.

If all audio paths are working, but both the microphone and the earphone are out of order during a connected call, proceed to section 20.10.

20.3 The microphone part is out of order

When there is a microphone fault it is only the audio paths "Mic – AFMS" and "Mic – CPU – Earphone" that are faulty. The other three audio paths should be working. The trouble shooting below assumes that the microphone has been replaced, but the fault remains.

Open the phone and check for liquid damage.

Power up the board and start it in the test program.

Go to Audio / Audio.

Start Mic – AFMS.

Measure the DC voltage at P800 (2.5 V).

If the voltage at P800 is too low, the fault is probably due to N800, a bad soldering, a break in R812 or R814, a short circuit in C814, or maybe a foil damage.

If the voltage is correct, the fault is in the signal path of the microphone. The levels of the signal (5 mV) are so low it is hard to follow the signals (MICP and MICN) from the microphone to the inputs of N800.

If the resistors R817 and R819 are not missing, the fault is usually due to C818 or C819. The fault can also be due to N800 or bad soldering.

20.4 The earphone part is out of order

When there is an earphone fault it is only the audio paths “AFMS - Earphone” and “Mic – CPU – Earphone” that are faulty. The other three audio paths should be working. The trouble shooting below assumes that the earphone of the phone has been replaced, but the fault remains.

Open the phone and check for liquid damage.

Make sure that the earphone connector (J810) is correctly soldered, undamaged and not dirty. Measure the resistance between N800:24 – J810:1 and N800:26 – J810:2 (both 0 ohm).

If the resistance is too large, it can be due to an incorrectly soldered or damaged earphone connector or a foil damage.

If the resistance is correct, the fault is probably due to N800 or bad soldering.

20.5 The ATMS input part is out of order

When the ATMS input part is out of order it is only the audio paths “ATMS – PCM – AFMS”, “ATMS – CPU – AFMS” and “ATMS – Earphone” that are faulty. The other two should be working. The trouble shooting below assumes that the system connector of the phone has been replaced, but the fault remains.

Open the phone and check for liquid damage.

Make sure that the system connector pads are not oxidised or burned.

Power up the board and start it in the test program.

Go to Audio / Audio.

Start ATMS – PCM – AFMS.

An appropriate signal for ATMS is 1kHz, 100mVrms or 280mVp-p sinus.

Check if the signal exists at N800:20 (75 mVrms or 200 mVp-p sinus).

If the signal exists at N800:20, the fault almost always is due to N800. It can also be due to D600.

If the signal is missing at N800:20, check if it exists at the system connector (J602:2).

If the signal is correct at J602:2, the fault can be due to any of the components in the signal path, or a foil damage.

If the signal is too low or is missing at the system connector, the fault is probably due to bad connections, broken cables, or wrong settings or connection for the signal generator. The fault can also be due to bad contact surfaces at J602.

20.6 The AFMS output part is out of order

When the AFMS output part is out of order it is only the audio paths “Mic – AFMS”, “ATMS – PCM – AFMS” and “ATMS – CPU – AFMS” that are faulty. The other two should be working. The trouble shooting below assumes that the system connector of the phone has been replaced, but the fault remains.

Open the phone and check for liquid damage.

Make sure that the system connector pads are not oxidised or burned.

Power up the board and start it in the test program.

Go to Audio / Audio.

Start ATMS – PCM – AFMS.

An appropriate signal for ATMS is 1kHz, 100mVrms or 280mVp-p sinus.

Check if the signal exists at N800:22 (125 mVrms or 340mVp-p sinus).

If the signal is missing at N800:22, the fault almost always is due to N800. The fault can also be due to D600 or a short circuit in F601.

If the signal exists at N800:22, check if it exists at the system connector (J602:1) (125 mVrms or 340mVp-p sinus).

If the signal is too low or is missing at the system connector the fault can be due to any of the components in the signal path, or a foil damage.

If the signal is correct at the system connector, the fault probably is due to bad connections, broken cables, or wrong settings or connection for the oscilloscope.

20.7 The CPU loops are out of order

When the CPU loops are out of order it is only the audio paths “ATMS – CPU – AFMS” and “Mic – CPU – Earphone” that are faulty. The other three should work.

Open the phone and check for liquid damage.

The fault is usually due to D600, but sometimes D900. The fault can be due to a faulty component, but usually is it due to bad soldering.

20.8 Both the CPU loops and the PCM loops are out of order

When the CPU loops and the PCM loops are out of order it is only the side tone paths (“ATMS – Earphone” and “Mic – AFMS”) that are working.

Open the phone and check for liquid damage.

Power up the board and start it in the test program.

Check the feed voltages VDIG (3.2V) and VCORE (2.5V).

If the feed voltages are correct, make sure R904 is not missing. If the resistor has got correct resistance, the fault is usually due to N800, but sometimes it is due to D600, D900 or bad soldering.

If the feed voltages are too low, measure the resistances of VDIG and VCORE to ground (>25 kohms).

If the resistances are correct, replace the regulator N701 for VDIG or N700 for VCORE.

If the resistance is too low, use the schematics. Remove the components one by one (or lift the pin/pins feeding the circuit), that is fed from the short circuited voltage, and measure the resistance after each removal. You have found the faulty component when the resistance is raising after removal. Do not forget to mount all the components that have been removed. You should also replace the circuits on which you have lifted the pins. The short circuit is usually due to D610, D600 or any of C600, C602-C611, C614, C800, C802-C807, C902, C906 for VDIG and D900 or any of C900, C901, C903-C905 for VCORE.

If the feed voltages are too high, replace N701 respectively V703.

20.9 All audio paths are out of order

Open the phone and check for liquid damage.

Power up the board and start it in the test program.

Check the feed voltages VDIG (3.2V) and VCORE (2.5V).

If any of the voltages are too low, measure the resistance to ground (VDIG > 1 kohm, VCORE > 25 kohms).

If the resistance is correct, replace the corresponding circuit (VDIG - N701, VCORE - N700). If the resistance is too low, use the schematics. Remove the components one by one (or lift the pin/pins feeding the circuit), that is fed from the short circuited voltage, and measure the resistance after each removal. You have found the faulty component when the resistance is raising after removal. Do not forget to mount all the components that have been removed. You should also replace the circuits on which you have lifted the pins. The short circuit is usually due to D610, D600 or any of C600, C602-C611, C614, C800, C802-C807, C902, C906 for VDIG and D900 or any of C900, C901, C903-C905 for VCORE.

If any of the voltages are too high, replace the corresponding circuit.

If the feed voltages are correct, make sure R904 is not missing. If the resistor is mounted and got correct resistance, the fault is usually due to N800, but sometimes it is due to D600, D900 or bad soldering.

20.10 All audio paths are working in EFRA, but both the microphone and the earphone is out of order during a connected call

If any of the signals EXTAUD or PORTHF is too low (short circuit against ground), the phone thinks that there is a handsfree unit connected and switches the audio paths to the system connector instead of the microphone and earphone of the phone. This is only valid during a connected call with signal program (or the signal part of the test program) in the phone. At this type of fault all audio paths will work with test program in EFRA.

Open the phone and check for liquid damage.

Make sure that the switches EXTAUDIO and PORTHF at the trouble shooting box are in position ON.

ON means that the signals EXTAUDIO and PORTHF are high (3.2 V, the actual voltage will be 2.7 V, since there is a load on the signal due to the impedance of the trouble shooting box).

OFF means that the signals EXTAUDIO and PORTHF are low (0 V). Note! The signals are active low, i.e. a connected Handsfree unit is simulated when the switches are in the position OFF.

Power up the board and enter the test program.

Measure the voltage at J602:3, 5 (2.7 V).

If the voltage is low at any of them, the fault is usually due to a short circuit caused by dirt around F600 and F602. Clean them using alcohol and a brush. The fault can also be due to a short circuit in F602 or F603, a break in R635 or R636 or an incorrect VDIG.

If both voltages are correct, the fault can be due to D600, N800, D900 or bad soldering. F602 or F603 are sometimes broken even if the voltages seems to be okay.

21 Keyboard

21.1 How does the keyboard work

The figure below shows the schematic for the keyboard at A1018s.




Fig. 21.1

The function of the keyboard is built of nine signals connected as a matrix with five rows and four columns. The rows are called KEYROW 0 – 4 and the columns KEYCOL 0 – 3. Each crossing between a row and a column can be used as an identification of a key.

The rows are fed by a voltage directly from D600 giving the rows a voltage of 3.2V. Pressing one of the keys on the keyboard turns one of the KEYROW 0 – 4 low. By doing so the processor knows that a key is pressed and it should start the scanning of the keyboard to identify which key is being pressed. If the scanning cannot find an active column it means that the button being pressed is the No key (ONSRQ grounds ONOFF through V701).

21.2 How to find the fault

Start the phone in the test program.

Go to MMI/Keyboard.

Press all keys to find which is faulty.

Open the phone and check for liquid damage, especially around the faulty keys.

Clean the pads of the keyboard thoroughly using alcohol.

Power up the board and enter the test program. Try the function of the keyboard.

If the fault is okay, it was due to the plastic keyboard or dirt at the pads of the keyboard.

If the fault remains, check in the schematics how the faulty keys are connected, i.e. if there is a connection in a row or a column between the faulty keys.

If all keys are faulty (in EFRA is one button shown as pressed all the time and the rest as faulty), the fault usually is due to a short circuit, caused by dirt, of the faulty key (according to EFRA).

If all keys of a column are faulty, the fault is due to D600, the soldering at D600 or a foil damage.

If all keys of a row are faulty, the fault is due to D600, the soldering at D600 or a foil damage.

If one or more keys, but not all, of a row or a column is faulty, the fault usually is due to a foil damage (if the pads have been thoroughly cleaned). You can verify this by measuring the foil between the faulty key and the pin at the processor corresponding to the row or the column of the faulty key. If only the No key is faulty, the fault can be due to V701.

22 Display

22.1 Control signals to the display

The display is controlled by the processor with serial data through an I²C-buss (Inter IC). The I²C-buss consists of two lines, I2CDAT for data and I2CCLK for clocking.

To get as good readability as possible of the display in different angles and to get clear contrast, the display has to be regulated exactly. The contrast is controlled by a voltage, VLCD. It is achieved with two PWM signals (Pulse Width Modulation) from the processor and some discrete components.




Fig. 22.1

By varying the pulse width of the PWM signal, the level of VLCD can be regulated. To be able to regulate VLCD exactly, it is voltage divided (to fit the ADC range 0-3.2 V) to VLCDMEAS and fed back to an ADC transformer in N800.

VLCD is compensated using values from EEPROM, since the LCD display is temperature sensitive.

22.2 Type of fault

Attach a dummy or a fully charged battery, connect the system connector and start the phone in the test program.

Go to MMI \ Display / Top.

Click on "Chess pattern" to see the test pattern in the display.

Click on "Inv. Chess pattern" to invert the pattern.

If the display shows all segments in both cases mentioned above and the contrast is correct, the display probably is without fault.

If the phone does not start, proceed to chapter 2 ("Enter test program").

If the display misses one or more segments, proceed to section 22.3.

If the display does not show anything at all, proceed to section 22.4.

If the display has got bad contrast or is completely black (all segments are lit), proceed to section 32.5.

22.3 One or more segments are missing

Open the phone and check for liquid damage.

Replace the display.

Try the phone again according to section 22.2.

22.4 The display does not show anything at all

Open the phone and check for liquid damage.

Exchange the display and the LCD contact to one you know is okay.

Test the phone again according to section 22.2.

If the display still does not show anything, proceed to section 32.5.

22.5 The display has got bad contrast or is completely black

Enter the test program with the phone assembled.

Go to Logic \ Read ADC.

Read the values for VLCD measure.

Compare to the values in table 22.1.

VLCD meas	Min	Max
Hex	8C	A5
Dec	140	165

Table 22.1

NOTE! The values in the table are with the display mounted.

Open the phone and check for liquid damage.

The VLCD-measure value is directly proportional to the VLCD value, that means if the value is not between the limits, the fault is due to a faulty VLCD voltage. If that is the case, check the voltages at the diodes V608 and V611. The voltages must correspond to the values in table 22.2.

Pin placement	V608	V611
Pin 1	5.0 V	3.8 V
Pin 2	4.6 V	5.0 V
Pin 3	4.6 V	3.5 V

Table 22.2

All values in table 22.2 have the tolerance $\pm 0,2$ V.

An incorrect voltage can be due to a fault in the signals PWM 0 or PWM 1 (D600, incorrect program in the phone or wrong phone model in EFRA), a short circuit in the capacitors between the PWM generators and the diodes (C634 or C636), faulty diodes (V608 or V611) or a short circuit in the capacitor that filtrates VLCD (C633).

The PWM 0 signal is shown in the figure below. Notice that the PWM signals for a phone with signal program and a phone with test program does not look the same.




Fig. 22.2

A fault in the PWM signals is usually due to incorrect soldering at D600, a short circuit in the capacitors between the PWM generators and the diodes and sometimes just a faulty D600.

If the VLCD voltage is within the limits in table 2, but VLCD-meas is not, the fault can be due to a short circuit in C824, C826 or in the voltage divider R807 and R808.

If VLCD-meas (and VLCD) is within the limits, the fault can be due to one of the DC voltages or digital signals at the pads of the display (H623).

Table 22.3 shows the voltages at the pads of the display.

	Signals and levels at H623	
Pin 5	I2C-CLOCK	3.2 V
Pin 4	GND	0 V
Pin 3	I2C-DATA	3.2 V
Pin 2	VDIG	3.2 V
Pin 1	VLCD	4.5 V

Table 22.3

If I2C-DATA and/or I2C-CLOCK is missing, the fault can be due to R619 or R620. The fault can also be due to incorrect soldering at D600:3,4 or a fault in D600. Sometimes the fault can be due to the feed voltage VDIG.

If VLCD is incorrect, go back to the beginning of this section.

Measure the resistance between GND at H623 and battery GND. If the resistance is larger than 1 ohm, there might be a foil damage.

23 Buzzer

23.1 How to find the fault

Start the phone in the test program.
Go to Audio\Audio/Buzzer
Activate the buzzer with "Buzzer ON".




Fig. 23.1

Measure the voltage on activated buzzer according to Fig. 23.2.




Fig. 23.2

If the voltage on pin 1 is too low, check VBATT on both sides of R606. If VBATT is too low at R606, the card might be foil damaged, or one of R606, R611 and V605 is faulty.

If the voltage on pin 4 is wrong, measure the voltage on R651 (1.5V on the side toward the processor and 0.4V on the other side).

If the voltage is incorrect on the side toward the processor, the fault can be due to bad soldering or D600.

If the voltage is correct on D600, the fault can be due to R651, V606 or V605, but usually it is H600 (the buzzer).

24 Illumination

24.1 The background light to the keyboard or to the display does not work

Start the phone in the test program.

Go to MMI\Display/Top indicator test)

Activate background light with "Disp./Keyb. led on " .




Fig. 24.1

Check which of the LED's that are working.

If one or more LED's at the display are not working, proceed to section 24.2.

If one or more LED's at the keyboard are not working, proceed to section 24.3.

If no LED's are working, proceed to section 24.4.

24.2 LED's at the display H651-H654 are not working

If one LED does not work, it is almost always that one that is faulty. It is also possible that there is a foil damage, caused by liquid damage.

If a replacement of a LED did not help or if two or more LED's do not work, measure the voltage over one of them (4.8 V (VBATT) on one side and 2.8 V on the other side).
If the voltages are correct then the LED's are faulty.

If VBATT is missing there is a foil damage, possibly caused by liquid damage.
If VBATT occurs on both sides of the LED's, then it is most likely a short circuit in one of the LED's or a foil damage between the LED's cathodes and V613:3. It can also be caused by a damage in V613 or R609.

24.3 LED's at the keyboard H655-H660 are not working

If one LED does not work, it is almost always that one that is faulty. It is also possible that there is a foil damage, caused by liquid damage.
If a replacement of a LED did not help or if two or more LED's do not work, measure the voltage over one of them (4.8 V (VBATT) on one side and 2.8 V on the other side).

If the voltages are correct then the LED's are faulty.
If VBATT is missing there is a foil damage, possibly caused by liquid damage.
If VBATT occurs on both sides of the LED's, then it is most likely a short circuit in one of the LED's or a foil damage between the diodes cathodes and V614. It can also be caused by a damage in V614 or R610.

24.4 No LED is working

If no LED works, measure the voltage on R608 (1.7 V).
If the voltage is incorrect it can depend on either D600 (no signal LED3K, 3.1), R608, damage in R607 or a possible foil damage.
If the voltage is correct the fault can be due to missing VBATT at all the LED's (foil damage) or at least two of the following components are damaged: R609, R610, V613 and V614.

25 Top Indicator

25.1 Green or red top indicator does not work

Start the phone in the test program.

Go to MMI(Display/Top indicator test)

Activate the half of the diode that does not work with “Green top indicator” or “Red top indicator”. If both diodes are faulty, you have to check one at the time. This is because EFRA does not allow you to activate more than one at the time.




Fig. 25.1

Check the voltages on the diode, H650, according to the table 25.1



Fig. 25.2 - H650 pin configuration

PIN	Unactivated	Red LED activated	Green LED activated
1	3.2 V	0.1 V	3.2 V
2	3.2 V	1.7 V	2.0 V
3	3.2 V	3.2 V	0.1 V
4	3.2 V	1.7 V	2.0 V

Table 25.1

If the voltage are to low on pin 2 and 4, check VDIG (3.2V) on R646.

If the voltage VDIG is incorrect it can be due to N701, foil damage toward R646 or a short circuit on VDIG.

If the voltages on pin 1 or 3 are incorrect, check the voltage on D600:93 or D600:94.

If the voltage is incorrect on D600, then the fault can be due to the soldering or the circuit.

If the voltage is correct on D600, then the fault can be due to foil damage toward H650.

26 SIM Problems (“Insert card”)

26.1 What is SIM fault

Attach a fully charged battery and an adequate SIM card to the phone.

If the phone shows “Wrong card” or “Insert correct card” when started, then the phone is SIM locked and cannot be repaired at this repair level.

If the phone shows “Phone lock”, then it is locked by the customer with a personal code. The phone will be unlocked in the reset program in the normal repair flow.

If the phone shows “PIN:” or “Enter PIN”, the SIM card is locked with a personal code.

Only if the phone shows “Insert card” or “card error”, there is a SIM fault.

26.2 How to find the fault

Perform a visual check of the board.

Make sure that the SIM connector is clean and correctly soldered and that the pins are not mechanically damaged.

Check for liquid damage around the SIM connector and the system connector.

Start the board using the test program.

Go to Logic\Logic/SIM.




Fig. 26.1

Fig. 26.2 shows the SIM connector.




Fig. 26.2

Set SIM VCC high using the button “SIM VCC”.
Measure the voltage on J603:1 (5 V).
If the voltage is missing, proceed to section 26.2.

NOTE! SIMVCC must be activated when measuring SIMCONRST, SIMCONDAT and SIMCONCLK.

Set SIMCONRST high using the button “SIM Reset”.
Measure the voltage on J603:2 (5 V).
If the voltage is missing, proceed to section 26.3.

Set SIMCONDAT high using the button “SIM Data”.
Measure the voltage on J603:7 (5 V).
If the voltage is missing, proceed to section 26.4.

Set SIMCONCLK high using the button “SIM Clock”.
Measure the voltage on J603:3 (5 V).
If the voltage is missing, proceed to section 26.5.
If all voltages are correct, proceed to section 26.6.

26.3 SIMVCC is missing

Make sure that D901 gives correct output voltage on pin 14 (5 V).
If the output voltage is incorrect, check the feed voltage (VVIC) on pin 1 (3.2 V).

If VVIC is incorrect, the fault can be due to R920, C910 or D901.

If VVIC is correct, check that the control signal SIMPOW exists on D901:4 (3,2 V).

If it is missing, it can be due to bad soldering at D600:72, D600 or a foil damage.

If it is correct, D901 is probably faulty. It can also be C909.

If the output voltage (pin 14) is correct on D901, make sure that there is not a foil damage toward J603:1.

26.4 SIMCONRST is missing

Measure SIMCONRST on D901:8 (5 V). To be able to put SIMCONRST high, SIMVCC must be high (and correct).

If SIMCONRST is missing, measure SIMRST from D600 on D901:7 (3,2 V).

If SIMRST is missing, it can depend on a bad soldering at D600:73, D600 or a foil damage.

If it is correct, D901 is probably faulty.

If SIMCONRST is correct, measure the resistance of R600 and make sure that there is not a foil damage along the path.

26.5 SIMCONDAT is missing

Measure SIMCONDAT on D901:11 (5 V). To be able to put SIMCONDAT high, SIMVCC must be high (and correct).

If SIMCONDAT is missing, measure SIMDAT from D600 on D901:5 (3,2 V).

If SIMDAT is missing, it can be due to a bad soldering at D600:74, D600 or a foil damage.

If it is correct, D901 is probably faulty.

If SIMCONDAT is correct, measure the resistance of R628 and make sure that there is not a foil damage along the path.

26.6 SIMCONCLK is missing

Measure SIMCONCLK on D901:9 (5 V). To be able to put SIMCONCLK high, SIMVCC must be high (and correct).

If SIMCONCLK is missing, measure SIMCLK from D600 on D901:6 (3,2 V).

If SIMCLK is missing, it can be due to a bad soldering at D600:75, D600 or a foil damage.

If it is correct, D901 is probably faulty.

If SIMCONCLK is correct, measure the resistance of R627 and make sure that there is not a foil damage along the path.

26.7 All signals are correct

Measure the resistance on J603:5 against ground (0 ohm).

If the resistance is correct, the fault can be due to D600 or bad soldering at any of the components mentioned in this chapter.

27 Selftest

27.1 What is selftest

Selftest is a part of the test program, which tests the communication or a limited part of the function, and also the revision on certain circuits. The tests that selftest performs are:

Checking the revision of the CPU (D600), DSP (D900) and analogue/digital ASIC (N800).

Check if it is possible to write in and read from the EEPROM (D630).

Check the communication between the CPU and the DSP.

Analogue ASIC measures the battery voltage (VTRACK) with a ADC.

The CPU tests the RTC by setting the clock and then check it twice to make sure it works. The phone must have been powered up at least 10 s before performing SELF TEST.

A correctly performed test should look like *Fig. 27.1*




Fig. 27.1

27.2 Chip revision (CPU, SDSP and AASIC)

This selftest does not detect faults. The test is only for checking the revisions of D600, D900 and N800.

27.3 Check EEPROM

Open the phone and check for liquid damage.

Check the soldering at D600:3, 4.

Check R619, R620.

Make sure that there is no short circuit against ground at I2CCLK or I2CDAT (mainly at the display).

Power up the board and check VDIG (3.2 V).

D630 is a CLASS D-component and cannot be replaced because it demands advanced equipment and comprehensive calibration of the board that cannot be performed at this level. Sometimes it can help to replace D600.

27.4 Check SpeechDSP (Speech coding)

Open the phone and check for liquid damage.
Power up the board and check VDIG (3.2 V) and VCORE (2.5 V).
If the voltages are correct , replace D900 or D600 .

27.5 Check AASIC (Analogue ASIC)

Open the phone and check for liquid damage.
Power up the board and check VDIG (3.2 V).
Measure VTRACK on N550:2 (1.0 V at 4.8 V VBATT).
If the voltage is lower, replace N550 and perform a new selftest. Sometimes there is a short circuit against ground on the VTRACK-input on N800. Measure the resistance at C854, C855, C853 and C833 and compare with a reference board.
If the voltage is correct, replace N800. If that did not help, replace D600.

27.6 Check RTC (Real time clock)

Open the phone and check for liquid damage.
Power up the board and check VDIG (3.2 V) and VRTC (2.5 V).
Check on B600 to see if it oscillate (32.76 kHz). The signals amplitude is to low for most frequency counters to measure. Some oscilloscope has such a high impact on the signal that it can be lost.
Mainly it is B600 that is faulty, but sometimes it is C690, C691 or D600.

28 ADC Values

28.1 What is ADC

The processor cannot use analogue information, therefore it has to be converted from analogue to digital configuration. The conversion is done in an 8-bits A/D converter. All of the analogue signals mentioned in the figure use the same ADC. It is possible since there is an 8-channel multiplexer on the input of the A/D-converter.




Fig. 28.1

The A/D-converted information is sent to the processor as serial data through RADDAT and RADCLK. The processor controls the process of converting using three control signals.

28.2 How to check the ADC function

Some faults that are hard to detect in the functions of the phone are due to incorrect presentation of information such as battery voltage or the temperature of the phone. This can make the phone turn it self off even though the battery is fully charged or there is too large frequency fault due to incorrect temperature compensation. Such faults can be due to a fault in the A/D conversion.

You can use EFRA to read the digital values on four of the ADC channels: VTRACK, TEMP and VLCDMEAS.

Start the phone in the test program and go to Logic\Read ADC.
The values are shown in a window as the one below.




Fig. 28.2

You can choose to read the values once or continuously.
 If two or more values are incorrect, proceed to section 28.3.
 If only one value is incorrect, proceed to the corresponding section below.

28.3 Two or more values are incorrect

If all ADC values are incorrect, the fault is usually due to the ADC itself in N800 or possibly the control signals from D600. Though, it is always suitable to check the feed voltages VANA and VDIG first.

28.4 VTRACK

The ADC limits for VTRACK is shown in the table below.

Battery voltage	min	max	
6.5 V	D2	FF	hex
	210	255	dec
4.5 V	32	5F	hex
	50	95	dec

Table 28.1

If VTRACK is not correct according to the table, start the phone in the test program.
 Set the battery voltage to 6.5 V.
 Measure the exact voltage of VBATT (N550:17) and VRAD (N450:13).

Calculate VTRACK according to following formula:

$$0.7 * (VBATT - VRAD) = VTRACK$$

For example: VBATT= 6.5 V, VRAD= 3.8 V gives VTRACK 1.9 V

Measure the voltage VTRACK on N550:2.

If the voltage VTRACK is incorrect, the fault is due to the feed voltage VRAD or N550.

If the voltage VTRACK is correct, the fault is usually due to the feed voltage VDIG or N800, but sometimes D600.

28.5 TEMP

ADC limits for TEMP is shown in the table below.

	min.	max	
TEMP	6A	88	hex
	106	136	dec

Table 28.2

The values in the table are valid for a temperature of the surroundings between 15°C and 35°C. If TEMP is not correct according to the table, the fault usually is due to R101, but sometimes to R831 or N800.

28.6 VLCDMEAS

The ADC value for the VLCD voltage is presented in a hexadecimal mode. The value can be used when trouble-shooting display fault. Explanations on how to find VLCD related faults are shown in chapter 22 (“Display”-fault).

29 Revision History

Rev.	Date	Changes / Comments
A	1999-10-01	
B	1999-10-26	The document is applicable also for A1028sc
C	2000-03-24	The document is applicable also for GM 518. Troubleshooting with Signalprogram removed. Document title and layout changed.