SUBJECT : Firmware Updating of Touch Key

1. Purpose :
  - **In order to inform repair engineers of technical information.**

2. Symptom :
 - Improvement of Touch Key sensitivity

3. Change:
  - Touch Version : 1.0 -> 2.0 (to improve the level of recognition)

3. The way to check the existing Touch Version:
  1. Input Key String *#0206*8376263#
  2. Check whether the Touch Version is 1.0 or 2.0. (Ver 2.0 is the most optimized version currently)

4. Repair Instruction :
  In case of Touch Version 1.0,
  Engineer might make the improvement by touch key firmware update.
  But, mostly the touch key sensetivity depends on the feeling & condition of individual user.

---

1. Download the latest SW Version released after 28.May
  (Touch Version 2.0 applied to SW from after GE3)

2. Input Key String *#9998*86824# to update of Touch Version 2.0
  (It needs about 10~20sec to complete downloading)

3. The message "Touch Code Download Completed!" will appear after completing update

4. Check the Touch Version be changed 1.0 into 2.0 after Inputting Key String *#0206*8376263#

Message of Completion