AX2/7 SYSTEM DIAGRAM

AMD Smarter Choice

01

DDR3-SODIMM1 PAGE 6

DDR3-SODIMM2 PAGE 7

DDR3 channel A

DDR3 channel B

AMD Champlain
35mm X 35mm
S1G4 Processor
638P (PGA)35W/25W
PAGE 3,4,5

CPU THERMAL SENSOR PAGE 5

HT3

PCI-E

PCI-Express 16X

NORTH BRIDGE
RS880M A12
21mm X 21mm, 528pin BGA
PAGE 8,9,10,11

X1

LAN
Realtek
PCIE-LAN
RTL8103E
(10/100)
PAGE 30

RJ45 PAGE 30

X1

Mini PCI-E Card
(Wireless LAN)
PAGE 33

HDMI PAGE 25

CRT PAGE 24

LVDS PAGE 23

ATI PARK-LP
23mm X 23mm
PAGE 17,18,19 20,21

DDR3

VRAM PAGE 22

Side port

DDR3 RAM for UMA only PAGE 8

ALINK X4

SYSTEM CHARGER(ISL6251) PAGE 40

SYSTEM POWER ISL6237 PAGE 34

DDR II SMDDR_VTERM 1.8V/1.8VSUS(RT8207) PAGE 37

VCCP +1.1V AND +1.2V(RT8204) PAGE 35

VGACORE(1.1V~1.2V)Oz8118 PAGE 38

CPU CORE ISL6265HRTZ-T PAGE 36

SATA - HDD PAGE 29

SATA0 150MB

SATA - CD-ROM PAGE 29

SATA4 150MB

SOUTH BRIDGE
SB820 A12
21mm X 21mm, 605pin FCBGA
4.5W(Ext)
4.3W(Int)
PAGE 12,13,14,15,16

USB2.0

0,5,8 USB2.0 Ports X3 PAGE 29

15 BT softbreeze PAGE 29

2 Webcam X1 PAGE 23

3 Flash Media RTS5159 PAGE 26

10 PCI-E WLAN Card x1 PAGE 33

Azalia

MDC CONN PAGE 28

RJ11

Realtek ALC270-GR PAGE 27

Ang MIC PAGE 27

AUDIO CONN (Phone/ MIC) PAGE 28

LPC

ENE KBC
KB3926 Dx
PAGE 32

Keyboard PAGE 31
Touch Pad PAGE 31

FAN PAGE 28

SPI PAGE 31

SMBUS TABLE		
SB--SCL0/SD0	Clock gen/Robson/TV tuner /DDR2/DDR2 thermal/Accelerometer	+3V
	epress card Wlan Card	+3VS5
EC --SCL/SD	Battery charge/discharge	+3VPCU
EC--SCL2/SD2	VGA thermal/system thermal	+3V

NDS/ND2

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	Block Diagram	1A

Date: Thursday, December 24, 2009 | Sheet 1 of 42

PV,delete all external clock GEN reserve material


03
VLDT use 1.5A Max current
+1.1V
+1.1V_VLDT
R164 *0_6/S
+1.1V
+1.1V_VLDT_R
R83 *0_6/S
BLM21PG221SN1D(220,100M,2A)_8
L34
W/S= 15 mil/20mil
+2.5V
+CPUVDDA
C418 4.7U/6.3V_6
LS0805-100M-N
C392 4.7U/6.3V_6
C302 0.22U/25V_6
C304 3300P/50V_4
U21A
HT LINK
SOCKET_638_PIN
CPU CLK
Keep trace from resisor to CPU within 0.6"
keep trace from caps to CPU within 1.2"
CPUCLKP
CPUCLKN
CPUCLKIN
CPUCLKIN#
R149 169/F_4
C402 3900P/25V_4
C401 3900P/25V_4
H_THRMDC
H_THRMDA
CPU_PWRGD
CPU_LDT_RST#
CPU_LDT_STOP#
CPU_LDT_REQ# CPU
R146
R148
R166
R144
*300/F_4
+1.5V
250mA
U21D
SideBand Temp sense I2C
CPU_SIC
CPU_SID
CPU_ALERT
R114 44.2/F_4
R115 44.2/F_4
CPU_HTREF0
CPU_HTREF1
place them to CPU within 1.5"
CPU_VDD0_RUN_FB_H
CPU_VDD0_RUN_FB_L
CPU_VDD1_RUN_FB_H
CPU_VDD1_RUN_FB_L
CPU_DBRDY
CPU_TMS
CPU_TCK
CPU_TRST#
CPU_TDI
CPU_TDO
CPU_DBREQ#
CPUTEST23
CPUTEST18
CPUTEST19
CPUTEST25H
CPUTEST25L
CPUTEST21
CPUTEST20
CPUTEST24
CPUTEST22
CPUTEST12
CPUTEST27
CPUTEST17
CPUTEST16
CPUTEST15
CPUTEST14
CPUTEST29H
CPUTEST29L
R130 80.6/F_4
R156 *300/F_4
+1.1V_VLDT
R157 *0_4/S
THERMTRIP_L
PROCHOT_L
MEMHOT_L
THERMDC
THERMDA
VDDIO_FB_H
VDDIO_FB_L
VDDNB_FB_H
VDDNB_FB_L
Route as 80ohm, diff
R163 510/F_4
R162 510/F_4
R172 300/F_4
R338 1K/F_4
R339 *300/F_4
FOX PZ63826-284R-41F
DG0^8000004 IC SOCKET SMD 638P S1(P1.27,H3.2)
MLX 47296-4131
DG0^8000003 IC SOCKET SMD 638P S1(P1.27,H3.2)
TYC 4-1903401-2
DG0^8000005 IC SOCKET SMD 638P S1(P1.27,H3.2)
MV can remove reserve for debug
R207 10K/F_4
CNTR_VREF
Q19 MMBT3904
R186 1K/F_4
CPU_LDT_RST#
CPU_LDT_RST_HTPA#
Serial VID
R170 *1K/F_4
R171 *1K/F_4
R176 0_4
R175 0_4
R177 0_4
R189 1K/F_4
R190 1K/F_4
CPU_SVC_R
CPU_SVD_R
CPU_PWRGD
CPU_SVC
CPU_SVD
CPU_PWRGD_SVID_REG
R184 *220_4
R183 *220_4
R185 *220_4
VFIX MODE
VID Override table (VDD)
SVC SVD Output Voltage
0 0 1.1V
0 1 1.0V
1 0 0.9V
1 1 0.8V
CPUTEST20 R340 1K/F_4
CPUTEST21 R81 1K/F_4
CPUTEST22 R80 1K/F_4
CPUTEST24 R69 1K/F_4
HDT Connector
CPUTEST12 R70 1K/F_4
CPUTEST19 R124 1K/F_4
CPUTEST18 R125 1K/F_4
C74 *0.1U/10V_4
KEY
SM_CHIP_CONN
R224 10K/F_4
R225 300_4
CPU_PROCHOT_L#
R205 0_4
R219 0_4
Q22 MMBT3904
CPU_PROCHOT#
CPU_PROCHOT_R#
EC new option
R181 10K/F_4
R180 1K/F_4
Q18 MMBT3904
CPU_THERMTRIP_L#
CPU_THERMTRIP#
SI , add R205 for P-state implement
PROJECT : AX2/7
Quanta Computer Inc.
Size Custom
Document Number S1G4 HT,CTL I/F 1/3
Rev 1A
Date: Thursday, December 24, 2009
Sheet 3 of 42
NB5/XD
http://laptop-motherboard-schematic.blogspot.com/

Processor Memory Interface

04

PLACE THEM CLOSE TO CPU WITHIN 1"

VDDR = 0.9V for 25W & 35W CPU

VDDR = 1.05V for 35V & 45W CPU

PV,change to short pad

SI , change from 0.01u to 0.1u from AMD recommand

Place close to socket

Reserved for AMD suggest



PROJECT : AX2/7	
Quanta Computer Inc.	
NB5/RD2	
Size: Custom	Document Number: S1G4 DDRII MEMORY I/F 2/3
Rev: 1A	
Date: Thursday, December 24, 2009	Sheet 4 of 42

PROCESSOR POWER AND GROUND















PV,add for EMI suggest



PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	S1G4 PWR & GND 3/3	1A

Date: Thursday, December 24, 2009 | Sheet 5 of 42





SO-DIMM BYPASS PLACEMENT :

Place these Caps near So-Dimm1.

No Vias Between the Trace of PIN to CAP.



DE-COUPLING FOR DIMM1(ONE CAP PER POWER PIN)

SI , add C226 from EMI suggest



PV,add from EMI suggestion

SI , remove C100 , C136
. add C100 , C136 C843
Reserve C901

DE-COUPLING FOR DIMM1







PV,change
to short pad

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	DDR3 SODIMMS: A/B CHANNEL	1A
NB5/RD2	Date: Thursday, December 24, 2009	Sheet 6 of 42



SO-DIMM BYPASS PLACEMENT :

Place these Caps near So-Dimm1.

No Vias Between the Trace of PIN to CAP.

DE-COUPLING FOR DIMM2(ONE CAP PER POWER PIN)



DE-COUPLING FOR DIMM2



SI , remove C165 , C236
add C845 , C846 ,C844
Reserve C902





PV,change
to short pad

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	DDR3 SODIMMS TERMINATIONS	1A

Date: Thursday, December 24, 2009 | Sheet 7 of 42

NB5/RD2

HT_CPU_NB_CAD_H[15..0] — HT_CPU_NB_CAD_H[15..0] 3
HT_CPU_NB_CAD_L[15..0] — HT_CPU_NB_CAD_L[15..0] 3
HT_CPU_NB_CLK_H[1..0] — HT_CPU_NB_CLK_H[1..0] 3
HT_CPU_NB_CLK_L[1..0] — HT_CPU_NB_CLK_L[1..0] 3
HT_CPU_NB_CTL_H[1..0] — HT_CPU_NB_CTL_H[1..0] 3
HT_CPU_NB_CTL_L[1..0] — HT_CPU_NB_CTL_L[1..0] 3
HT_NB_CPU_CAD_H[15..0] — HT_NB_CPU_CAD_H[15..0] 3
HT_NB_CPU_CAD_L[15..0] — HT_NB_CPU_CAD_L[15..0] 3
HT_NB_CPU_CLK_H[1..0] — HT_NB_CPU_CLK_H[1..0] 3
HT_NB_CPU_CLK_L[1..0] — HT_NB_CPU_CLK_L[1..0] 3
HT_NB_CPU_CTL_H[1..0] — HT_NB_CPU_CTL_H[1..0] 3
HT_NB_CPU_CTL_L[1..0] — HT_NB_CPU_CTL_L[1..0] 3

U22A

HYPER TRANSPORT CPU I/F — PART 1 OF 6

HT_CPU_NB_CAD_H0	Y25	HT_RXCAD0P	HT_TXCAD0P	D24	HT_NB_CPU_CAD_H0
HT_CPU_NB_CAD_L0	Y24	HT_RXCAD0N	HT_TXCAD0N	D25	HT_NB_CPU_CAD_L0
HT_CPU_NB_CAD_H1	V22	HT_RXCAD1P	HT_TXCAD1P	E24	HT_NB_CPU_CAD_H1
HT_CPU_NB_CAD_L1	V23	HT_RXCAD1N	HT_TXCAD1N	F25	HT_NB_CPU_CAD_L1
HT_CPU_NB_CAD_H2	V25	HT_RXCAD2P	HT_TXCAD2P	F24	HT_NB_CPU_CAD_H2
HT_CPU_NB_CAD_L2	V24	HT_RXCAD2N	HT_TXCAD2N	F25	HT_NB_CPU_CAD_L2
HT_CPU_NB_CAD_H3	U24	HT_RXCAD3P	HT_TXCAD3P	F23	HT_NB_CPU_CAD_H3
HT_CPU_NB_CAD_L3	U25	HT_RXCAD3N	HT_TXCAD3N	F22	HT_NB_CPU_CAD_L3
HT_CPU_NB_CAD_H4	T25	HT_RXCAD4P	HT_TXCAD4P	H23	HT_NB_CPU_CAD_H4
HT_CPU_NB_CAD_L4	T24	HT_RXCAD4N	HT_TXCAD4N	H22	HT_NB_CPU_CAD_L4
HT_CPU_NB_CAD_H5	P22	HT_RXCAD5P	HT_TXCAD5P	J25	HT_NB_CPU_CAD_H5
HT_CPU_NB_CAD_L5	P23	HT_RXCAD5N	HT_TXCAD5N	J24	HT_NB_CPU_CAD_L5
HT_CPU_NB_CAD_H6	P25	HT_RXCAD6P	HT_TXCAD6P	K24	HT_NB_CPU_CAD_H6
HT_CPU_NB_CAD_L6	P24	HT_RXCAD6N	HT_TXCAD6N	K25	HT_NB_CPU_CAD_L6
HT_CPU_NB_CAD_H7	N24	HT_RXCAD7P	HT_TXCAD7P	K23	HT_NB_CPU_CAD_H7
HT_CPU_NB_CAD_L7	N25	HT_RXCAD7N	HT_TXCAD7N	K22	HT_NB_CPU_CAD_L7
HT_CPU_NB_CAD_H8	AC24	HT_RXCAD8P	HT_TXCAD8P	F21	HT_NB_CPU_CAD_H8
HT_CPU_NB_CAD_L8	AC25	HT_RXCAD8N	HT_TXCAD8N	G21	HT_NB_CPU_CAD_L8
HT_CPU_NB_CAD_H9	AB25	HT_RXCAD9P	HT_TXCAD9P	G20	HT_NB_CPU_CAD_H9
HT_CPU_NB_CAD_L9	AB24	HT_RXCAD9N	HT_TXCAD9N	H21	HT_NB_CPU_CAD_L9
HT_CPU_NB_CAD_H10	AA24	HT_RXCAD10P	HT_TXCAD10P	J20	HT_NB_CPU_CAD_H10
HT_CPU_NB_CAD_L10	AA25	HT_RXCAD10N	HT_TXCAD10N	J21	HT_NB_CPU_CAD_L10
HT_CPU_NB_CAD_H11	Y22	HT_RXCAD11P	HT_TXCAD11P	J18	HT_NB_CPU_CAD_H11
HT_CPU_NB_CAD_L11	Y23	HT_RXCAD11N	HT_TXCAD11N	K17	HT_NB_CPU_CAD_L11
HT_CPU_NB_CAD_H12	W21	HT_RXCAD12P	HT_TXCAD12P	L19	HT_NB_CPU_CAD_H12
HT_CPU_NB_CAD_L12	W20	HT_RXCAD12N	HT_TXCAD12N	J19	HT_NB_CPU_CAD_L12
HT_CPU_NB_CAD_H13	V21	HT_RXCAD13P	HT_TXCAD13P	M19	HT_NB_CPU_CAD_H13
HT_CPU_NB_CAD_L13	V20	HT_RXCAD13N	HT_TXCAD13N	L18	HT_NB_CPU_CAD_L13
HT_CPU_NB_CAD_H14	U20	HT_RXCAD14P	HT_TXCAD14P	M21	HT_NB_CPU_CAD_H14
HT_CPU_NB_CAD_L14	U21	HT_RXCAD14N	HT_TXCAD14N	P21	HT_NB_CPU_CAD_L14
HT_CPU_NB_CAD_H15	U19	HT_RXCAD15P	HT_TXCAD15P	P18	HT_NB_CPU_CAD_H15
HT_CPU_NB_CAD_L15	U18	HT_RXCAD15N	HT_TXCAD15N	M18	HT_NB_CPU_CAD_L15
HT_CPU_NB_CLK_H0	T22	HT_RXCLK0P	HT_TXCLK0P	H24	HT_NB_CPU_CLK_H0
HT_CPU_NB_CLK_L0	T23	HT_RXCLK0N	HT_TXCLK0N	H25	HT_NB_CPU_CLK_L0
HT_CPU_NB_CLK_H1	AB23	HT_RXCLK1P	HT_TXCLK1P	L21	HT_NB_CPU_CLK_H1
HT_CPU_NB_CLK_L1	AA22	HT_RXCLK1N	HT_TXCLK1N	L20	HT_NB_CPU_CLK_L1
HT_CPU_NB_CTL_H0	M22	HT_RXCTL0P	HT_TXCTL0P	M24	HT_NB_CPU_CTL_H0
HT_CPU_NB_CTL_L0	M23	HT_RXCTL0N	HT_TXCTL0N	M25	HT_NB_CPU_CTL_L0
HT_CPU_NB_CTL_H1	R21	HT_RXCTL1P	HT_TXCTL1P	P19	HT_NB_CPU_CTL_H1
HT_CPU_NB_CTL_L1	R20	HT_RXCTL1N	HT_TXCTL1N	R18	HT_NB_CPU_CTL_L1
		HT_RXCALP	HT_TXCALP	B24	HT_TXCALP
		HT_RXCALN	HT_TXCALN	B25	HT_TXCALN

RS880

R412 301/F_4 HT_RXCALP — HT_RXCALN
R411 301/F_4 HT_TXCALP — HT_TXCALN

signals	RS880	RX880
HT_TXCALP	R430 301 ohm 1%	R430 1.21k ohm 1%
HT_TXCALN		
HT_RXCALP	R434 301 ohm 1%	R434 1.21k ohm 1%
HT_RXCALN		

U18

SPM_VREF1	M9	VREFCA	DQL0	E4	SPM_DQ2
SPM_VREF2	H2	VREFDQ	DQL1	F8	SPM_DQ1
			DQL2	F3	SPM_DQ5
SPM_A0	N4	A0	DQL3	F9	SPM_DQ3
SPM_A1	P8	A1	DQL4	H4	SPM_DQ7
SPM_A2	P4	A2	DQL5	H9	SPM_DQ0
SPM_A3	N3	A3	DQL6	G3	SPM_DQ4
SPM_A4	P9	A4	DQL7	H8	SPM_DQ6
SPM_A5	P3	A5			
SPM_A6	R9	A6			
SPM_A7	R3	A7	DQU0	D8	SPM_DQ13
SPM_A8	T9	A8	DQU1	C4	SPM_DQ8
SPM_A9	R4	A9	DQU2	C9	SPM_DQ10
SPM_A10	L8	A10/AP	DQU3	C3	SPM_DQ12
SPM_A11	R8	A11	DQU4	A8	SPM_DQ15
SPM_A12	N8	A12/BC	DQU5	A3	SPM_DQ11
SPM_A13	T4	A13	DQU6	B9	SPM_DQ14
	T8	A14	DQU7	A4	SPM_DQ9
	M8	A15			
SPM_BA0	M3	BA0	VDD#B3	B3	+1.5V_MEM_VDDQ
SPM_BA1	N9	BA1	VDD#D10	D10	
SPM_BA2	M4	BA2	VDD#G8	G8	
			VDD#K3	K3	
SPM_CLKP	J8	CK	VDD#K9	K9	
SPM_CLKN	K8	CK	VDD#N2	N2	
SPM_CKE	K10	CKE	VDD#N10	N10	
			VDD#R2	R2	
			VDD#R10	R10	
SPM_ODT	K2	ODT	VDDQ#A2	A2	+1.5V_MEM_VDDQ
SPM_CS#	L3	CS	VDDQ#A9	A9	
SPM_RAS#	J4	RAS	VDDQ#C2	C2	
SPM_CAS#	K4	CAS	VDDQ#C10	C10	
SPM_WE#	L4	WE	VDDQ#D3	D3	
			VDDQ#E10	E10	
SPM_DQS0P	F4	DQSL	VDDQ#F2	F2	
SPM_DQS1P	C8	DQSU	VDDQ#H3	H3	
			VDDQ#H10	H10	
SPM_DM0	E8	DML	VSS#A10	A10	
SPM_DM1	D4	DMU	VSS#B4	B4	
			VSS#E2	F2	
SPM_DQS0N	G4	DQSL	VSS#G9	G9	
SPM_DQS1N	B8	DQSU	VSS#J3	J3	
			VSS#J9	J9	
			VSS#M2	M2	
			VSS#M10	M10	
			VSS#P2	P2	
	T3	RESET	VSS#P10	P10	
			VSS#T2	T2	
VMA_ZQ2	L9	ZQ	VSS#T10	T10	
			VSSQ#B2	B2	
			VSSQ#B10	B10	
			VSSQ#D2	D2	
			VSSQ#D9	D9	
			VSSQ#E3	E3	
			VSSQ#E9	E9	
	J2	NC#J2	VSSQ#F10	F10	
	L2	NC#L2	VSSQ#G2	G2	
	J10	NC#J10	VSSQ#G10	G10	
	L10	NC#L10			

100-BALL SDRAM DDR3
*H5TQ1G63AFR-14C

SI,exchange net name

R95 *100_4 — SPM_CLKP, SPM_CLKN, SPM_CKE

+1.5V_MEM_VDDQ
R343 *10K/F_4
13 SP_DDR3_RST#
R91 *243/F_4

This block is for UMA only , DIS can remove all component

U22D

MEM/DVO_I/F — PAR 4 OF 6

SPM_A0	AB12	MEM_A0(NC)	MEM_DQ0/DVO_VSYNC(NC)	AA18	SPM_DQ0
SPM_A1	AE16	MEM_A1(NC)	MEM_DQ1/DVO_HSYNC(NC)	AA20	SPM_DQ1
SPM_A2	V11	MEM_A2(NC)	MEM_DQ2/DVO_DE(NC)	AA19	SPM_DQ2
SPM_A3	AE15	MEM_A3(NC)	MEM_DQ3/DVO_D0(NC)	Y19	SPM_DQ3
SPM_A4	AA12	MEM_A4(NC)	MEM_DQ4(NC)	V17	SPM_DQ4
SPM_A5	AB16	MEM_A5(NC)	MEM_DQ5/DVO_D1(NC)	AA17	SPM_DQ5
SPM_A6	AB14	MEM_A6(NC)	MEM_DQ6/DVO_D2(NC)	AA15	SPM_DQ6
SPM_A7	AD14	MEM_A7(NC)	MEM_DQ7/DVO_D4(NC)	Y15	SPM_DQ7
SPM_A8	AD13	MEM_A8(NC)	MEM_DQ8/DVO_D3(NC)	AC20	SPM_DQ8
SPM_A9	AD15	MEM_A9(NC)	MEM_DQ9/DVO_D5(NC)	AD19	SPM_DQ9
SPM_A10	AC16	MEM_A10(NC)	MEM_DQ10/DVO_D6(NC)	AE22	SPM_DQ10
SPM_A11	AE13	MEM_A11(NC)	MEM_DQ11/DVO_D7(NC)	AC18	SPM_DQ11
SPM_A12	AC14	MEM_A12(NC)	MEM_DQ12(NC)	AB20	SPM_DQ12
SPM_A13	Y14	MEM_A13(NC)	MEM_DQ13/DVO_D9(NC)	AD22	SPM_DQ13
T21			MEM_DQ14/DVO_D10(NC)	AC22	SPM_DQ14
SPM_BA0	AD16	MEM_BA0(NC)	MEM_DQ15/DVO_D11(NC)	AD21	SPM_DQ15
SPM_BA1	AE17	MEM_BA1(NC)			
SPM_BA2	AD17	MEM_BA2(NC)			
			MEM_DQS0P/DVO_IDCKP(NC)	Y17	SPM_DQS0P
			MEM_DQS0N/DVO_IDCKN(NC)	W18	SPM_DQS0N
SPM_RAS#	W12	MEM_RASb(NC)	MEM_DQS1P(NC)	AD20	SPM_DQS1P
SPM_CAS#	Y12	MEM_CASb(NC)	MEM_DQS1N(NC)	AE21	SPM_DQS1N
SPM_WE#	AD18	MEM_WEb(NC)			
SPM_CS#	AB13	MEM_CSb(NC)	MEM_DM0(NC)	W17	SPM_DM0
SPM_CKE	AB18	MEM_CKE(NC)	MEM_DM1/DVO_D8(NC)	AE19	SPM_DM1
SPM_ODT	V14	MEM_ODT(NC)			
			IOPLLVDD18(NC)	AE23	+1.8V_IOPLLVDD18
SPM_CLKP	V15	MEM_CKP(NC)	IOPLLVDD(NC)	AE24	+1.1V_IOPLLVDD
SPM_CLKN	W14	MEM_CKN(NC)			
			IOPLLVSS(NC)	AD23	
R357 *40.2/F_4 SPM_COMPP	AE12	MEM_COMPP(NC)		AE18	SPM_VREF
R352 *40.2/F_4 SPM_COMPN	AD12	MEM_COMPN(NC)	MEM_VREF(NC)		

RS880

+1.5V_MEM_VDDQ

40mils wdith or more

+1.5V_MEM_VDDQ — R341 *0_6 — +1.5V

C86 *1U/10V_4 — C71 *10U/6.3V_8 — C66 *10U/6.3V_8
C84 *0.1U/10V_4 — C92 *0.1U/10V_4 — C87 *1U/10V_4

*PBY160808T-221Y-N L54 — +1.8V
*PBY160808T-221Y-N L16 — +1.1V

C630 *2.2U/6.3V_6 — C146 *2.2U/6.3V_6

R356 *1K/F_4 — R355 *1K/F_4
C619 *0.1U/10V_4 — C620 *0.1U/10V_4 — +1.5V_MEM_VDDQ

SPM_VREF1: R73 *1K/F_4 — R75 *1K/F_4 — C85 *0.1U/10V_4 — C77 *0.1U/10V_4 — +1.5V_MEM_VDDQ

SPM_VREF2: R100 *1K/F_4 — R101 *1K/F_4 — C121 *0.1U/10V_4 — C138 *0.1U/10V_4 — +1.5V_MEM_VDDQ

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	RS880-HT LINK I/F 1/5	1A

Date: Thursday, December 24, 2009 | Sheet 8 of 42

GFX_RX can remove
at next stage for MUXLESS

SI , for routing smooth
GFX_TX 0/1/3/9/10/11

UMA can remove all GFX_TX CAP

SI remove C711,C713,C710,
C712,C708,C709,C703,C704
for MUXLESS

U22B

PART 2 OF 6

PCIE I/F GFX

PCIE I/F GPP

PCIE I/F SB

RS880

PV,change to reserve
for MUXLESS

Close to North Bridge

To HDMI CONN

TO WLAN

TO PCIE-LAN

RS880 Display Port Support (muxed on GFX)

DP0	GFX_TX0,TX1,TX2 and TX3 AUX0 and HPD0
DP1	GFX_TX4,TX5,TX6 and TX7 AUX1 and HPD1

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	RS880-PCIE I/F 2/5	1A

Date: Thursday, December 24, 2009 Sheet 9 of 42







STRAP_DEBUG_BUS_GPIO_ENABLEb

Enables the Test Debug Bus using GPIO.

RS880M	
1 Disable	
0 Enable	

VSYNC_INT R422 3K_4 +3V

RS880M: Enables Side port memory

RS880M:HSYNC#

Selects if Memory SIDE PORT is available or not
1 = Memory Side port Not available
0 = Memory Side port available
Register Readback of strap: NB_CLKCFG:CLK_TOP_SPARE_D[1]

HSYNC_INT R418 3K_4 +3V
R419 *3K_4

For external EEPROM Debug only

RS780/RX780

DYN_PWR_EN R426 2K/F_4

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	RS880-SYSTEM I/F 3/5	1A

Date: Thursday, December 24, 2009 Sheet 10 of 42

RS880M POWER TABLE

PIN NAME	RS880M	PIN NAME	RS880M
VDDHT	+1.1V	IOPLLVDD	+1.1V
VDDHTRX	+1.1V	AVDD	+3.3V
VDDHTTX	+1.2V	AVDDDI	+1.8V
VDDA18PCIE	+1.8V	AVDDQ	+1.8V
VDDG18	+1.8V	PLLVDD	+1.1V
VDD18_MEM	+1.8V	PLLVDD18	+1.8V
VDDPCIE	+1.1V	VDDA18PCIEPLL	+1.8V
VDDC	+1.1V	VDDA18HTPLL	+1.8V
VDD_MEM	+1.8V/1.5V	VDDLTP18	+1.8V
VDDG33	+3.3V	VDDLT18	+1.8V
IOPLLVDD18	+1.8V	VDDLT33	NC





PROJECT : AX2/7 Quanta Computer Inc.		
Size: Custom	Document Number: RS880-POWER5/5	Rev: 1A
Date: Tuesday, December 22, 2009	Sheet 11 of 42	

U29A

SB800 Part 1 of 5

PLACE THESE PCIE AC COUPLING CAPS CLOSE TO SB

To RS880

PCI EXPRESS INTERFACES

PCI CLKS

PCI INTERFACE

CLOCK GENERATOR

LPC

CPU

RTC

SB820M A12

All the PCI bus has build-in Pull-UP/Down resistors

SI , C404 change to reserve only

SI , add AND gate for the reset input of PCIE devices from AMD recommand

Place within 0.5" of SB

SI , remove R483,R286 from AMD recommand

SI , change pull high from +3V_VGA to +3V_DELAY

SI,add R616 for CR CLK

SI , change from VGA_RSTA to A_RST#_R

SI , change to 27P

PV,change to short pad

PV,add for 1.05V control

PV, change from 22p to 18p from vendor update

SI add R615 for reserve VGA_PWROK to BIOS

SI , change CN14 to BT1

H=4.2 footprint: "BAT-23_2-4_2"

footprint check ok

EMI suggestion

INTRUDER_ALERT# Left not connected (Southbridge has 50 kohm internal pull-up to VBAT).

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	SB820-PCIE/PCI/CPU/LPC 1/4	1A

Date: Thursday, December 24, 2009 | Sheet 12 of 42


13
NC,no install by default
R253 *2.2K_4 SB_TEST0
R470 *2.2K_4 SB_TEST1
R245 *2.2K_4 SB_TEST2
remove pull hi
(chip internal
have pull hi)
SCL1/SDATA1 is 3V/S5 tolerance
AMD datasheet define it
R459 2.2K_4 SB_SMBCLK1
R460 2.2K_4 SB_SMBDATA1
SI , Add SB_GPIO_RST#
form AMD recommand
SCL0/SDATA0 is 3V tolerance
AMD datasheet define it
R312 2.2K_4 PCLK_SMB
R311 2.2K_4 PDAT_SMB
Clock gen/Robson/TV
tuner
/DDR2/DDR2
thermal/Accelerometer
R561 10K/F_4
RB501V-40 D38
VGA_REQ
SI , add R561,D38 for VGA_CLK_REQ
SCL2/SDATA2 is 3V/S5 tolerance
AMD datasheet define it
R296 2.2K_4 SB_SCLK2
R292 2.2K_4 SB_SDATA2
R576 *10K_4 SYS_RST#
PV,Reserve for system stable
R458 2.2K_4 DNBSWON#
R457 4.7K_4 SUS_STAT#
SI , add from HP request
R332 8.2K_4 WLAN_CLKREQ#
R334 8.2K_4 LAN_CLKREQ#
To Azalia
ACZ_SDOUT R247 33_4 ACZ_SDOUT_AUDIO 27
C478 *10P/50V_4
ACZ_SYNC R251 33_4 ACZ_SYNC_AUDIO 27
C484 *10P/50V_4
PV, change to 27P
from EMI suggest
ACZ_BCLK R254 33_4 C479 27P/50V_4 BIT_CLK_AUDIO 27
ACZ_RST# R242 33_4 ACZ_RST#_AUDIO 27
ACZ_SDIN0 ACZ_SDIN0 27
Remove short pad
To Modem Board
ACZ_SDOUT R246 33_4 ACZ_SDOUT_AUDIO_MDC 28
C477 *10P/50V_4
ACZ_SYNC R248 33_4 ACZ_SYNC_AUDIO_MDC 28
C473 *10P/50V_4
ACZ_BCLK R256 33_4 C486 27P/50V_4 BIT_CLK_AUDIO_MDC 28
PV, change to 27P
from EMI suggest
ACZ_RST# R249 33_4 ACZ_RST#_AUDIO_MDC 28
ACZ_SDIN1 ACZ_SDIN1 28
Remove short pad
EMI suggestion
HD audio
interface is
3.3S5 voltage
R255 *10K/F_4
R455 *10K/F_4
R453 *10K/F_4
R454 *10K/F_4
R452 *10K/F_4
PV,change from pull
high to pull low from
AMD update
SI , add pull up resistor
from AMD recommend
R483 10K/F_4
R505 10K/F_4
R509 10K/F_4
R511 10K/F_4
R545 10K/F_4
SB JTAG
CN32
C833 10P/50V_4
*SWJTAG RESERVE
U29D
SB800
Part 4 of 5
SB820M A12
PCI_PME#/GEVENT4#
RI#/GEVENT22#
SPI_CS3#/GBE_STAT1/GEVENT21#
SLP_S3#
SLP_S5#
PWR_BTN#
PWR_GOOD
SUS_STAT#
TEST0
TEST1/TMS
TEST2
GA20IN/GEVENT0#
KBRST#/GEVENT1#
LPC_PME#/GEVENT3#
LPC_SMI#/GEVENT23#
GEVENT5#
SYS_RESET#/GEVENT19#
WAKE#/GEVENT8#
IR_RX1/GEVENT20#
THRMTRIP#/SMBALERT#/GEVENT2#
NB_PWRGD
RSMRST#
CLK_REQ4#/SATA_IS0#/GPIO64
CLK_REQ3#/SATA_IS1#/GPIO63
SMARTVOLT1/SATA_IS2#/GPIO50
CLK_REQ0#/SATA_IS3#/GPIO60
SATA_IS4#/FANOUT3/GPIO55
SATA_IS5#/FANIN3/GPIO59
SPKR/GPIO66
SCL0/GPIO43
SDA0/GPIO47
SCL1/GPIO227
SDA1/GPIO228
CLK_REQ2#/FANIN4/GPIO62
CLK_REQ1#/FANOUT4/GPIO61
IR_LED#/LLB#/GPIO184
SMARTVOLT2/SHUTDOWN#/GPIO51
DDR3_RST#/GEVENT7#
GBE_LED0/GPIO183
GBE_LED1/GEVENT9#
GBE_LED2/GEVENT10#
GBE_STAT0/GEVENT11#
CLK_REQG#/GPIO65/OSCIN
BLINK/USB_OC7#/GEVENT18#
USB_OC6#/IR_TX1/GEVENT6#
USB_OC5#/IR_TX0/GEVENT17#
USB_OC4#/IR_RX0/GEVENT16#
USB_OC3#/AC_PRES/TDO/GEVENT15#
USB_OC2#/TCK/GEVENT14#
USB_OC1#/TDI/GEVENT13#
USB_OC0#/TRST#/GEVENT12#
AZ_BITCLK
AZ_SDOUT
AZ_SDIN0/GPIO167
AZ_SDIN1/GPIO168
AZ_SDIN2/GPIO169
AZ_SDIN3/GPIO170
AZ_SYNC
AZ_RST#
GBE_COL
GBE_CRS
GBE_MDCK
GBE_MDIO
GBE_RXCLK
GBE_RXD3
GBE_RXD2
GBE_RXD1
GBE_RXD0
GBE_RXCTL/RXDV
GBE_RXERR
GBE_TXCLK
GBE_TXD3
GBE_TXD2
GBE_TXD1
GBE_TXD0
GBE_TXCTL/TXEN
GBE_PHY_PD
GBE_PHY_RST#
GBE_PHY_INTR
PS2_DAT/SDA4/GPIO187
PS2_CLK/SCL4/GPIO188
SPI_CS2#/GBE_STAT2/GPIO166
FC_RST#/GPO160
PS2KB_DAT/GPIO189
PS2KB_CLK/GPIO190
PS2M_DAT/GPIO191
PS2M_CLK/GPIO192
ACPI / WAKE UP EVENTS
USB 1.1 USB MISC
USB 2.0
GPIO
USB OC
HD AUDIO
GBE LAN
EMBEDDED CTRL
USBCLK/14M_25M_48M_OSC
USB_RCOMP
USB_FSD1P/GPIO186
USB_FSD1N
USB_FSD0P/GPIO185
USB_FSD0N
USB_HSD13P
USB_HSD13N
USB_HSD12P
USB_HSD12N
USB_HSD11P
USB_HSD11N
USB_HSD10P
USB_HSD10N
USB_HSD9P
USB_HSD9N
USB_HSD8P
USB_HSD8N
USB_HSD7P
USB_HSD7N
USB_HSD6P
USB_HSD6N
USB_HSD5P
USB_HSD5N
USB_HSD4P
USB_HSD4N
USB_HSD3P
USB_HSD3N
USB_HSD2P
USB_HSD2N
USB_HSD1P
USB_HSD1N
USB_HSD0P
USB_HSD0N
SCL2/GPIO193
SDA2/GPIO194
SCL3_LV/GPIO195
SDA3_LV/GPIO196
EC_PWM0/EC_TIMER0/GPIO197
EC_PWM1/EC_TIMER1/GPIO198
EC_PWM2/EC_TIMER2/GPIO199
EC_PWM3/EC_TIMER3/GPIO200
KSI_0/GPIO201
KSI_1/GPIO202
KSI_2/GPIO203
KSI_3/GPIO204
KSI_4/GPIO205
KSI_5/GPIO206
KSI_6/GPIO207
KSI_7/GPIO208
KSO_0/GPIO209
KSO_1/GPIO210
KSO_2/GPIO211
KSO_3/GPIO212
KSO_4/GPIO213
KSO_5/GPIO214
KSO_6/GPIO215
KSO_7/GPIO216
KSO_8/GPIO217
KSO_9/GPIO218
KSO_10/GPIO219
KSO_11/GPIO220
KSO_12/GPIO221
KSO_13/GPIO222
KSO_14/GPIO223
KSO_15/GPIO224
KSO_16/GPIO225
KSO_17/GPIO226
PV,remove workaround
PV,delete R272
R291 11.8K/F_6
SI,add R272 for PARK LP 14M CLK source
BLUETOOTH
USB card reader
WLAN Min-Card
USB Connector
USB Connector
Carama USB
USB Connector
SPI/LPC define
C509 *2.2P/50V_4
for EMI
PROJECT : AX2/7
Quanta Computer Inc.
Size Custom
Document Number SB820-ACPI/GPIO/USB 2/4
Rev 1A
Date: Thursday, December 24, 2009 Sheet 13 of 42
http://laptop-motherboard-schematic.blogspot.com/

SATA PORT 0,1,2,3 can support AHCI mode

PLACE SATA AC COUPLING CAPS CLOSE TO SB820

IF THERE IS NO IDE, TEST POINTS FOR DEBUG BUS IS MANDATORY

SI define side port ID

SIDE_PORT_ID2	SIDE_PORT_ID1	SIDE_PORT_ID0	
1	0	0	Samsung
1	0	1	Hynix
0	0	0	No support side port

SATA1

SATA ODD

PLVDD_SATA-- SATA PLL POWER

XTLVDD_SATA-- SATA crystal power

PLACE SATA_CAL RES VERY CLOSE TO BALL OF SB820

NOTE:
R361 IS 1K 1% FOR 25MHz
XTAL, 4.99K 1% FOR 100MHz
INTERNAL CLOCK

SB800 Part 2 of 5

SERIAL ATA

FLASH

HW MONITOR

SPI ROM

SI , remove test point from AMD recommand

PV,change to short pad

SI , change to reserve only

For blue tooth & wireless merge card

SI define board ID

ID4	ID3	ID2	ID1	ID0	
0	0	0	0	0	AX2 UMA DF
0	0	0	0	1	AX7 UMA DF
0	0	0	1	0	AX2 PARK DF
0	0	0	1	1	AX7 PARK DF
0	0	1	0	0	AX2 UMA FF
0	0	1	0	1	AX7 UMA FF
0	0	1	1	0	AX2 PARK FF
0	0	1	1	1	AX7 PARK FF
0	1	0	1	0	AX2 M93 DF
0	1	0	1	1	AX7 M93 DF
0	1	1	1	0	AX2 M93 FF
0	1	1	1	1	AX7 M93 FF

PV define for M93

PROJECT : AX2/7
Quanta Computer Inc.

Size: Custom | Document Number: SB820-ACPI/GPIO/USB 2/4 | Rev: 1A
Date: Thursday, December 24, 2009 | Sheet 14 of 42

PLACE ALL THE DECOUPLING CAPS ON THIS SHEET CLOSE TO SB AS POSSIBLE.

SB800 Part 3 of 5 — U29C — SB820M A12

VDDQ--3.3V I/O power 131mA
VDD33_18--3.3V IDE I/O power
1.8V flash memory I/O power
VDDIO_18_FC 71mA
Delete Cap and change +1.8V to pull low from AMD command , due to no IDE & flash mode
1.8V : FLASH MEMORY MODE(DEFAULT)
3.3V: IDE MODE
PV,change to short pad

POWER

VDDPL_3.3V_PCIE 43mA
PCIE_VDDR--PCIE I/O power 600mA
VDDPL_3.3V_SATA 93mA
AVDD_SATA--SATA phy power 567mA
AVDDTX--USB Phy Analog I/O power 658mA
VDDAN_1.1V_USB TBDmA
For support USB wakeup-->3V_S5

CORE S0: 510mA
CKVDD_1.1V--Internal clock Generator I/O power TBDmA
CLKGEN I/O
FLASH I/O
PCI/GPIO I/O
GBE LAN
PCI EXPRESS
SERIAL ATA
3.3V_S5 I/O: S5_3.3--3.3v standby power 32mA
CORE S5: S5_1.1V--1.1V standby power 113mA
USB I/O
PLL: 197mA
VDDXL_3.3V 32mA

VDD-- S/B CORE power
PV,change to short pad

GROUND — U29E — SB820M A12 — Part 5 of 5

SI , remove R272 from AMD recommand

To meet SB800 SCL1.02:
Separate ferrite bead is not required for VDDPL_33_USB_S, Del B603/600ohm bead.

SI , remove L48

PROJECT : AX2/7
Quanta Computer Inc.
Size: Custom | Document Number: SB820-PWR/DECOUPLING 4/4 | Rev: 1A
Date: Tuesday, December 22, 2009 | Sheet 15 of 42

OVERLAP COMMON PADS WHERE POSSIBLE FOR DUAL-OP RESISTORS.

internal have pull
Hi 10K , confirm AMD
ward this pull Hi
not need

REQUIRED STRAPS



REQUIRED STRAPS

	AZ_SDOUT	PCI_CLK1	PCI_CLK2	PCI_CLK3	PCI_CLK4	LPC_CLK0	LPC_CLK1	GPIO200 GPIO199
PULL HIGH	LOW POWER MODE	ALLOW PCIE Gen2 DEFAULT	Watchdog Timer Enabled	USE DEBUG STRAP	non_Fusion CLOCK MODE DEFAULT	EC ENABLED	CLKGEN ENABLED DEFAULT	H,H = Reserved H,L = SPI ROM
PULL LOW	PERFORMANCE MODE DEFAULT	FORCE PCIE Gen1	Watchdog Timer Disabled DEFAULT	IGNORE DEBUG STRAP DEFAULT	FUSION CLOCK MODE	EC DISABLED DEFAULT	CLKGEN DISABLED	L,H = LPC ROM (Default) L,L = FWH ROM

DEBUG STRAPS

SB800 HAS 15K INTERNAL PU FOR PCI_AD[27:23]



	PCI_AD27	PCI_AD26	PCI_AD25	PCI_AD24	PCI_AD23
PULL HIGH	USE PCI PLL DEFAULT	DISABLE ILA AUTORUN DEFAULT	USE FC PLL DEFAULT	USE DEFAULT PCIE STRAPS DEFAULT	DISABLE PCI MEM BOOT DEFAULT
PULL LOW	BYPASS PCI PLL	ENABLE ILA AUTORUN	BYPASS FC PLL	USE EEPROM PCIE STRAPS	ENABLE PCI MEM BOOT

NB_PWRGD_IN:
RS780/RX780 = 1.8V; RS740 = 3.3V
Do NOT share it with SB_PWRGD when use Internal Clk Gen
(Need SB PLL initialize firstly)



AL17SZ17000	IC(5P) NL17SZ17DFT2G(SOT-353)	SOT-353
ALUC1G17000	IC OTHER(5P) SN74AUC1G17DBVR(SOT23-5)	SOT23-5

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	SB820-STRAPS	1A
Date: Thursday, December 24, 2009	Sheet 16 of 42	



MEM_ID[3:0]	Vendor	Type	Vendor P/N
0000	Samsung- E die	64*16-800MHZ	K4W1G1646E-HC12
0001	Hynix - Orion	64*16-800MHZ	H5TQ1G63BFR-12C
0010	Reserved		
0011	Reserved		
0100	Reserved		
0101	Reserved		
0110	Reserved		
0111	Reserved		
1000	Reserved		
1001	Reserved		
1010	Reserved		
1011	Reserved		
1100	Reserved		
1101	Reserved		
1110	Reserved		
1111	Reserved		

	PWRCNTL1	PWRCNTL0	V-CORE
L	0	0	0.9V
M	0	1	0.96V
H	1	0	1.06V
TBD	1	1	1.12V

GPIO22(ROMCS#)
PD without external VBIOS ROM

PV,change to reserv only for delete workaround

SI, R128 change to reserve only for MUXLESS

SI , add R409 , R543 from AMD update

SI , provide 14M CLK source to slove Park JTAG test block intermittently fails to initialize correctly issue

SI , AMD Document Update change PU to PD

SI , reserve EEPROM to slove Park JTAG test block intermittently fails to initialize correctly issue

PV,delete workaround EEPROM

SI , add R103 , remove R165 from AMD update

PV,change to pull low for delete workaround

PV,change to short pad

PV,add it from AMD nda update If no contact this pin to LVDS need pull low

For M93-S3: Use 150 Ohms Pull Down
For M92-S2: Use 0R to VDDR4
For Park-S3: NC

SI,change to reserve only for MUXLESS

SI , reserve R46,R48 for MUXLESS

SI , reserve R321 , R331 for MUXLESS

PV,reserve for M93

SI , need pull high near chip side for MUXLESS change to reserve only

Pure DIS need install

For Int Clk 27Mhz

I2C ADDRESS: 9AH

w/s 10/10

PROJECT : AX2/7
Quanta Computer Inc.

N85/RD2

Size: Custom | Document Number: PARK_Main | Rev: 1A

Date: Thursday, December 24, 2009 | Sheet 18 of 42



SI, R119,R381 change to reserve only for MUXLESS





CONFIGURATION STRAPS

ALLOW FOR PULLUP PADS FOR THESE STRAPS AND IF THESE GPIOS ARE USED, THEY MUST NOT CONFLICT DURING RESET

RECOMMENDED SETTINGS
0= DO NOT INSTALL RESISTOR
1 = INSTALL 10K RESISTOR
X = DESIGN DEPENDANT
NA = NOT APPLICABLE

STRAPS	PIN	DESCRIPTION OF DEFAULT SETTINGS	
TX_PWRS_ENB	GPIO0	**Transmitter Power Savings Enable** 0: 50% Tx output swing for mobile mode 1: full Tx output swing (Default setting for Desktop)	1
TX_DEEMPH_EN	GPIO1	**PCI Express Transmitter De-emphasis Enable** 0: Tx de-emphasis disabled for mobile mode 1: Tx de-emphasis enabled (Default setting for Desktop)	1
BIF_GEN2_EN_A	GPIO2	Enable CLKREQ# Power Management 0 - CLKREQ# power management capability is disabled 1 - CLKREQ# power management capability is enabled	0
RSVD BIF_VGA_DIS RSVD	GPIO8 GPIO9 GPIO21	VGA ENABLED	0 0 0
BIOS_ROM_EN	GPIO_22_ROMCSB	ENABLE EXTERNAL BIOS ROM	0
ROMIDCFG(2:0)	GPIO[13:11]	SERIAL ROM TYPE OR MEMORY APERTURE SIZE SELECT	0 0 1
VIP_DEVICE_STRAP_ENA	V2SYNC	IGNORE VIP DEVICE STRAPS	0
RSVD AUD[1] AUD[0]	GENERICC HSYNC VSYNC	AUD[1] AUD[0] 0 0 No audio function 0 1 Audio for DisplayPort and HDMI if dongle is detected 1 0 Audio for DisplayPort only 1 1 Audio for both DisplayPort and HDMI	0 0 11

AMD RESERVED CONFIGURATION STRAPS

ALLOW FOR PULLUP PADS FOR THESE STRAPS AND IF THESE GPIOS ARE USED, THEY MUST NOT CONFLICT DURING RESET

H2SYNC GENERICC

PULLUP PADS ARE NOT REQUIRED FOR THESE STRAPS BUT IF THESE GPIOS ARE USED, THEY MUST NOT CONFLICT DURING RESET

GPIO21_BB_EN

Power Up/Down Sequence



Memory Aperture size

GPIO9 BIOSROM		GPIO13 ROMIDCFG2	GPIO12 ROMIDCFG1	GPIO11 ROMIDCFG0
0	128M	0	0	0
0	256M	0	0	1
0	64M	0	1	0
0	32M	0	1	1
0	512M	1	0	0
0	1G	1	0	1
0	2G	1	1	0
0	4G	1	1	1

It is a shared pin strap with CONFIG[2:0] if BIOS_ROM_EN is set to 0.



NB5/RD2

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	PARK_GND / LVDS/ Straps	1A
Date: Thursday, December 24, 2009	Sheet 19 of 42	

PCIE_VDDR--PCI-E I/O power. 1.8 V ± 5%



VDDCI--Isolated (clean) core power for the I/O logic. Voltage level should match that of VDDC. POWER Same as VDDC

VDDC--Dedicated core power, provides power to the internal logic. 0.9 V - 1.2 V (± 5%)

PCIE_VDDC--PCI-E Digital Power Supply (Either 1.0 V or 1.1 V) 1.0 V -5% to 1.1 V +5%

VDDRH_1 & VDDRH_2 --Dedicated power pins for memory clock pads for each channel. Should have the same voltage level as VDDR1.

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	PARK_Power_and_NC	1A

Date: Thursday, December 24, 2009 | Sheet 20 of 42



Designator	M9X-S2 and M93-S3	Park-S3
Ra	DNI	10K
Rb	0R/Short	51R
Rc	2.2K	DNI
Ca	2.2nF	68pF

Note 1 :Do not Install for M9X-S2/S3, Install 240 Ohms 0.5% Resistor for PARK-S3.
Note 2 :For M9X-S2/S3,J8 Pin Connect to VSS through 240 Ohms(0.5%) resistor.
For Park-S3,J8 Pin Connect to VSS through 150 Ohms(1%) resistor for DPC_CALR
Note 3 :For M9X-92/93, K7 Pin (NC_MEM_CALRP1) is Not connected.
For PARK-S3, K7 Pin (TESTEN#2) connect to TEST_EN Signal At AF24

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	PARK/MEM_Interface	1A

Date: Thursday, December 24, 2009 | Sheet 21 of 42

512MB DDR3

21 VMA_MA[13..0]
21 VMA_DM[7..0]
VMA_MA[13..0]
21 VMA_DQ[63..0]
21 VMA_WDQS[7..0]
21 VMA_RDQS[7..0]

U13 / U26 / U12 / U27 — K4W1G1646E-HC12 (100-BALL SDRAM DDR3)

Should be 240 Ohms +-1%

R223 243/F_4 (U13) · R435 243/F_4 (U26) · R210 243/F_4 (U12) · R432 243/F_4 (U27)

+1.5V_VGA

R439 4.99K/F_4 · R438 4.99K/F_4 · VREFC_VMA1 · C738 .1U/10V_4
R188 4.99K/F_4 · R192 4.99K/F_4 · VREFD_VMA1 · C434 .1U/10V_4
R437 4.99K/F_4 · R440 4.99K/F_4 · VREFC_VMA2 · C744 .1U/10V_4
R191 4.99K/F_4 · R197 4.99K/F_4 · VREFD_VMA2 · C727 .1U/10V_4
R231 4.99K/F_4 · R230 4.99K/F_4 · VREFC_VMA3 · C447 .1U/10V_4
R216 4.99K/F_4 · R227 4.99K/F_4 · VREFD_VMA3 · C443 .1U/10V_4
R434 4.99K/F_4 · R436 4.99K/F_4 · VREFC_VMA4 · C734 .1U/10V_4
R429 4.99K/F_4 · R433 4.99K/F_4 · VREFD_VMA4 · C726 .1U/10V_4

VMA_CLK0 · R206 56.2/F_4 · VMA_CLK0_COMM · C440 .01U/16V_4
VMA_CLK0# · R213 56.2/F_4
VMA_CLK1 · R199 56.2/F_4 · VMA_CLK1_COMM · C431 .01U/16V_4
VMA_CLK1# · R208 56.2/F_4

C429 C430 C456 C444 C438 C428 C425 C747 1U/6.3V_4
C721 C719 C745 C424 C748 C739 C718 C716 1U/6.3V_4
C751 C749 C741 C448 C451 C454 C742 C746 1U/6.3V_4
C724 C722 C720 C729 C730 C735 C446 C450 1U/6.3V_4
C743 C723 C459 C461 C458 10U/6.3V_6S
C725 C737 C740 C728 C457 C460 C452 10U/6.3V_6S

	QCI PN
SAMSUNG	AKD5LGGT502
HYNIX	AKD5LZGTW00

NB5/RD2

PROJECT : AX2/7
Quanta Computer Inc.

Size: Custom | Document Number: PARK VRAM(DDR3 BGA96) | Rev: 3A
Date: Thursday, December 24, 2009 | Sheet 22 of 42

1. If LCD connector near GPU, then place these series Resistors near GPU
2. If LCD connector near N/B, then place these series Resistors near N/B







SI, new option for MUXLESS

SI , add C21 from EMI suggest



SI, R34,R35 change to reserve only and add R33,R37 for MUXLESS





PV, add Q9 for BIOS check



CAMERA







Reserve for EMI

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	LCD CONN	1A

Date: Thursday, December 24, 2009 | Sheet 23 of 42

CRT PORT

PV , change footprint to F3_2X1_65-2_8

PV , change footprint to dsub-dsd-15aebb-15p-v-smt

R20 for UAM & MUXLESS use 140 ohm
for DIS use 150 ohm (AMD)

+5V F1 40 mils +5VCRT
FUSE1A6V_POLY

+5VCRT C6 0.1U/10V_4

40 MIL

CRT_R L3 BK1608LL680(0.2A,68)_6 CRT_R1
CRT_G L2 BK1608LL680(0.2A,68)_6 CRT_G1
CRT_B L1 BK1608LL680(0.2A,68)_6 CRT_B1

R20 140/F_4 R16 150/F_4 R11 150/F_4 C13 5.6P/50V_6 C10 5.6P/50V_6 C7 5.6P/50V_6 C8 5.6P/50V_6 C11 5.6P/50V_6 C12 5.6P/50V_6

close conn within 600mils

EMI

CRT CONN CN17

10,18 CRT_R CRT_R
10,18 CRT_G CRT_G
10,18 CRT_B CRT_B

+5V C3 0.1U/10V_4

U1 AHCT1G125DCH
U2 AHCT1G125DCH

10,18 VSYNC_COM
10,18 HSYNC_COM

PR_VSYNC R5 33_4 CRTVSYNC
PR_HSYNC R6 33_4 CRTHSYNC
R1 *0_4/S CRTDDCCLK2
R8 *0_4/S CRTDDCDAT2

C1 *470P/50V_4 C2 *47P/50V_4 C4 *47P/50V_4 C5 *47P/50V_4

+3V_DELAY R4 *4.7K_4
+3V R3 4.7K_4
10,18 DDCCLK DDCCLK
Q1 2N7002E
DDCCLK2

+3V_DELAY R10 *4.7K_4
+3V R9 4.7K_4
10,18 DDCDATA DDCDATA
Q2 2N7002E
DDCDAT2

SI, R4,R10 change to reserve only and add R3,R9 for MUXLESS

R2 6.81K_4 R7 6.81K_4

+5VCRT +5VCRT CH501H-40PT D3 +5V_CRT2

+3V
D9 BAV99W CRT_R1
D7 BAV99W CRT_G1
D5 BAV99W CRT_B1
D1 BAV99W DDCCLK2
D2 BAV99W CRTVSYNC
D4 BAV99W CRTHSYNC
D6 BAV99W DDCDAT2

PV,add for ESD

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	CRT	1A

Date: Thursday, December 24, 2009 Sheet 24 of 42

UMA/DISCRETE select for HDMI

From RS880M

SI , all add for MUXLESS

for Layout concern ,placement close north bridge

for Layout concern ,placement close HDMI conn

From PARK

PV,add for EMI

SI , change to reserve only for MUXLESS

for Layout concern ,placement close HDMI conn





UMA RS780M
上 715 ohm CS17152FB17

DIS M92-S
上 499 ohm CS14992FB24

Close to HDMI Connector

HDMI HPD SENSE

SI, remove R72 and change R85 , Q12 to reserve for MUXLESS

UMA use +3V for the detect pin
Dis use +3V_DELAY for the detect pin



Pure DIS : Add R85 , Q12

UMA / MUXLESS : Add R64 , R59 , Q11

SI , add R64,R59,Q11 for MUXLESS

UMA DDC4 is 5V tolerance , the MOSFET level shifter no need
Discrete DDC is 3V tolerance,the MOSFET level shifter is need

UMA AND DISCRETE HDMI I2C SELECT

Close to HDMI Connector



SI, remove R93 , R350 . Add RP30 R94,R351,Q14,Q15 change to reserve only for MUXLESS

HDMI PORT



	PROJECT : AX2/7 Quanta Computer Inc.	
Size Custom	Document Number HDMI	Rev 1A
Date: Thursday, December 24, 2009	Sheet 25 of 42	

PIN 13	CLK source	Remark
Floating	12M Hz	Xtal
Pull high	48M Hz	Input to RTS5159 pin48

SI , change CLK source from SB internal CLK GEN

AL005158B10 -->RTS5158E
AL005159B00 -->RTS5159GR

Note:

	SD/MMC	MS	XD
SP1			XD_CD#
SP2	SD_WP		
SP3	SD_CD#		
SP4	SD_DAT1		XD_D4
SP5		MS_BS	XD_D5
SP6		MS_D1	XD_D3
SP7	SD_DAT0	MS_D0	XD_D6
SP8	SD_DAT7	MS_D2	XD_D2
SP9		MS_INS#	
SP10	SD_DAT6	MS_D3	XD_D7
SP11	SD_CLK	MS_SCLK	XD_D1
SP12	SD_DAT5		XD_D0
SP13	SD_DAT4		XD_WP#
SP14			XD_R/B#
SP15	SD_DAT3		XD_WE#
SP16	SD_DAT2		XD_RE#
SP17			XD_ALE
SP18			XD_CE#
SP19			XD_CLE

PV,change to short pad

SP7	R517	*0_4/S	MS-D0_SD-D0_XD-D6
SP6	R515	*0_4/S	MS-D1_XD-D3_SD_D1
SP8	R520	*0_4/S	MS-D2_XD-D2
SP16	R535	*0_4/S	XD-RE#_SD-D2
SP5	R513	*0_4/S	MS-BS_XD-D5
SP15	R539	*0_4/S	SD-D3_XD-WE
SP11	R527	*0_4/S	SD_CLK_MS_CLK
SP2	R504	*0_4/S	SD_WP
SP13	R533	*0_4/S	XD-WP#
SP19	R541	*0_4/S	XD-CLE
SP4	R507	*0_4/S	XD-D4
SP10	R521	*0_4/S	MS-D3_XD-D7
SP14	R534	*0_4/S	XD-RB#
SP12	R528	*0_4/S	XD-D0
SP17	R540	*0_4/S	XD-ALE
SP18	R536	*0_4/S	XD-CE#
SD_CMD_R	R529	*0_4/S	SD-CMD

SI , change to 22P then change to reserve only

SI , Add R537 from vendor suggestion

Internal have pull Hi 200K

Realtek RTS5159

RTS5159 max output current for ..
XD card 250mA
SD/MMC 250mA
MS/MSPRO 250mA

SI, change power source from +3VSUS to +3V

Close to Chipset

Can not more than 10p

PV, change to short pad

*RB501V-40

Add diode for 5158E cardreader driver lost issue

PV , change footprint to 4in1-cm4s-125-36p-r-v-smt

CARD READER SOCKET

5 IN1 CARD-READER (PUSH-PUSH)

Support SD/SD PRO/MMC/MS/MS PRO/xD Cards

SI , update foortprint to spad-ax2-1np

VGA Hole

CPU Hole

SI, add CPU & VGA hold pad from EMI request

SI , add for ESD testing

PV,add new pad for new outline

CLOSE CONN

PROJECT : AX2/7
Quanta Computer Inc.

NB5/RD2

Size	Document Number	Rev
Custom	RTS5159 & CR SOCKET &HOLE	1A

Date: Thursday, December 24, 2009 | Sheet 26 of 42

PV , change to short pad

+3V R519 *0_6/S C830 1U/6.3V_4

+3V_DVDD C819 1U/10V_4 C821 10U/6.3V_8 — Close to Pin1
C816 10U/6.3V_8 C817 1U/10V_4 — Close to Pin9

+5V C812 10U/6.3V_8 C810 .1U/10V_4 — Close to Pin46
C822 10U/6.3V_8 C809 .1U/10V_4 — Close to Pin39

+5VAVDD C782 10U/6.3V_6 C780 1U/10V_4 — AGND AGND — Close to Pin25
C784 10U/6.3V_8 C786 1U/10V_4 — AGND AGND — Close to Pin38

PV,delete C824
ACZ_SDIN0_R C815 *27P/50V_4
FOR EMI

PV, change to reserve only
+5V L74 *PBY201209T-221Y-N
+5VAVDD C772 10U/6.3V_6 C774 4.7U/6.3V_6 C775 1U/6.3V_4 C783 .1U/10V_4 — 1.3A
AGND

PV , change from 220 to 47

PV, change footprint and value

MIC1-VERFL MIC1-VERFR MIC2-VERFO
28 EARP_L R489 47/F_4 HP-L
28 EARP_R R488 47/F_4 HP-R
AGND C777 2.2U/6.3V_6 CPVEE
269CBN C776 2.2U/6.3V_6 269CBP
C778 10U/6.3V_6 AGND
C781 .1U/10V_4 C779 1U/10V_4 — Close to Pin27
AGND
+5VAVDD

PV , add LDO
+5VAVDD U33 Vout Vin BYP GND EN G9191-475T1U
C842 1U/6.3V_4 AGND
R571 10K/F_4 C847 0.047U/25V_4 +5V

SI , remove L79,L80,L83,L84

Place near CODEC
SPKR- C802 *180p/50V_4 C806 *1U/16V_6
C808 *180p/50V_4 SPKR+
SPKL- C798 *180p/50V_4 C796 *1U/16V_6
C794 *180p/50V_4 SPKL+

SI , change L6,L7,L8,L9 to CX5AG601001 from EMI suggest

SPEAKER

Place near SPEAKER CONN
L9 L7 L6 L8 BLM15AG601SS1D
C45 C42 C46 C47 220P/50V_6
CN3 INT SPEAKER CONN

SI , add C42,C45,C46,C47 from EMI suggestion

U32 ALC270A-GR

AVSS2 AVDD2 PVDD1 SPK-L+ SPK-L- PVSS1 PVSS2 SPK-R- SPK-R+ PVDD2 EAPD SPDIFO PGND
CBP CBN CPVEE HP-OUT-R HP-OUT-L MIC1-VREFO-L MIC1-VREFO-R MIC2-VREFO LDO-CAP VREF AVSS1 AVDD1
LINE1-R LINE1-L MIC1-R MIC1-L MONO-OUT JDREF Sense-B MIC2-R MIC2-L LINE2-R LINE2-L Sense A
DVDD1 GPIO0 GPIO1 PD# SDATA-OUT BIT-CLK DVSS2 SDATA-IN DVDD-IO SYNC RESET# PCBEEP

Ditigal Analog

MIC1-VERFL R497 4.7K_4 MIC1-VERFR R491 4.7K_4
EXT_MIC1-R_C C789 4.7U/6.3V_6 EXT_MIC1-R_R R495 1K/F_4 EXT_MIC_R 28
EXT_MIC1-L_C C795 4.7U/6.3V_6 EXT_MIC1-L_R R496 1K/F_4 EXT_MIC_L 28
R498 20K/F_4 AGND — Place near CODEC
INT_MIC_R C801 4.7U/6.3V_6 INT_MIC
INT_MIC_L C803 4.7U/6.3V_6

Place near CODEC
SENSEA R502 39.2K/F_4 R501 20K/F_4 SA_A# SA_B#
SA_A# 28
SA_B# 28

SA_A# -->EXT Ear Phone
SA_B# -->EXT MIC

+3V_DVDD T169 T170 PD#
13 ACZ_SDOUT_AUDIO
13 BIT_CLK_AUDIO
PCBEEP
ACZ_RST#_AUDIO 13
ACZ_SYNC_AUDIO 13
+3V_DVDD
ACZ_SDIN0_R R512 33_4 ACZ_SDIN0 13

SI, remove R511
C814 *27P/50V_4
SI , change to reserve only

Place near CODEC
+5VAVDD +INTMIC_BIAS R485 *10K/F_4 R484 *10K/F_4 C768 *1U/6.3V_4 AGND
U31 *TLV2461IDBVRG4
INT_MIC C762 *100P/50V_4 INT_MIC_IN_C_R R481 *10K/F_4
R480 *10K/F_4 C763 *270P/25V_4 AGND
C761 *100P/50V_4 AGND
INT_MIC_IN_C C540 *.22U/25V_6
MIC2-VERFO R302 3K_4 R301 *3K_4 R300 *3K_4 C541 *1U/6.3V_4 AGND
INT_MIC_IN L79 BLM15AG601SS1D CN10 88266-020L
C165 *220P/50V_6 AGND AGND
+5VAVDD
PV, change to reserve only
PV,add for EMI
R427 0_6
PV , add R427
TO Internal Mic

SI , update foortprint to 88266-020L-2P-R-SMT

PV,add for test
R328 0_6 RC0603
R315 *0_6/S short0603
R261 *0_6/S short0603
R473 *0_6/S short0603
R313 *0_6/S short0603
R482 *0_6/S short0603
R506 *0_6/S short0603
Place Under CODEC
AGND

PC-BEEP
+5VAVDD
AGND C825 *0.047U/10V
C835 close to C820 and C820 close to chip
PV , remove U33,C825,C811 C820,R523,R524 R510,R514
Add this circuit same as AX1/3
R566 10K/F_4
C811 .1U/10V_4 PCBBEP_R2 R546 47K_4 PCBBEP_L C820 .1U/10V_4 PCBEEP
Q36 2N7002E
13 ACZ_SPKR
R549 4.7K_4 C835 .1U/10V_4
R549 close to R546
AGND AGND

+3V_DVDD R516 *10K_4
SI,remove U35,C681 , add D40 for audio function not stable
EAPD# ACZ_RST#_AUDIO R522 R518 0_4 *0_4 EAPD# R
32 VOLMUTE#
D40 BAT54A PD#

PROJECT : AX2/7
Quanta Computer Inc.
Size Custom | Document Number Azalia 92HD75B2X5 | Rev 1A
Date: Thursday, December 24, 2009 | Sheet 27 of 42

Line out



SA_A# -->EXT Ear Phone

SA_B# -->EXT MIC

MIC



CPU FAN



Modem CONN

MDC





Nut PN:MBCA6002013

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	AMP_TPA6017/MDC1.5/CPU FAN	1A

Date: Thursday, December 24, 2009 | Sheet 28 of 42

BLUETOOTH



LEFT SIDE USBX2



TOUCH PAD CONN



To TOUCH PAD SW board





SATA HDD CONNECTOR



Right SIDE USBX1



PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	BT/USBX3/TP/HDD	1A

Date: Thursday, December 24, 2009 | Sheet 29 of 42

+CTRL12DVDD R40 *0_6/S

Power trace Layout 寬度> 30mil

+DVDD12

C54 .1U/10V_4 C52 .1U/10V_4 C107 .1U/10V_4 C88 .1U/10V_4

CLOSE to Pin 10, 13, 30, 36

+EVDD12

C67 1U/10V_4 C76 1U/10V_4

LAN-AGND

close to pin 19

SI , remove EEPROM
U5,C48,R42,R50

Power trace Layout 寬度> 30mil

+3VLANVCC

LANVCC
1.2W
364mA

C53 4.7U/6.3V_6 C109 .1U/10V_4

+3V_LAN

C56 .1U/10V_4 C55 .1U/10V_4

CLOSE to Pin 29,37

+3V_A_LAN

C604 .1U/10V_4 C601 *.1U/10V_4

CLOSE to Pin 1

+CTRL12DVDD

C97 10U/6.3V_8 C83 .1U/10V_4

R97 2.49K/F_4 LANRSET

+CTRL12A

C111 10U/6.3V_8 C108 .1U/10V_4

XTAL2 XTAL1 Y2 25MHZ C62 33P/50V_4 C69 33P/50V_4

LAN_WLED# +3V_LAN

U7

RTL8103EL

+3V_A_LAN MDI0+ MDI0- MDI1+ MDI1- +DVDD12

AVDD33 MDIP0 MDIN0 NC/FB12 MDIP1 MDIN1 GND1 NC/MDIP2 NC/MDIN2 DVDD12/AVDD12 NC/MDIP3 NC/MDIN3

VCTRL12A/SROUT12 GND4 RSET VCTR12DVDDR NCVDDSR NC/ENSWREG CKTAL2 CKTAL1 NC/AVDD33 NC/LV_PLL LED0 VDD33B

DVDD12B LED1/EESK LED2/EEDI LED3/EEDO EECS GND3 DVDD12A VDD33A ISOLATEB PERSTB LANWAKEB CLKREQB

EESK_LED100# EEDI_LED10# EECS ISOLATEB LAN_REST_R# PCIE_WAKE#

R333 3.6K_4 R350 1K/F_4 +3V_LAN

PV , add R333 pull high and R350 pull low to fix LAN LED behavior abnormal

R45 *0_4 R569 0_4

LAN_REST# 32 PCIE_WAKE# 13,33 LAN_CLKREQ# 13

PV, add for debug SI , add from HP request

SI , add for DSM

DVDD12 GND2 HSIP HSIN REFCLK_P REFCLK_N LDO12 HSOP HSON EGND NC/SMCLK NC/SMDATA

+DVDD12 LAN-AGND LAN CABLE DETECT 32

9 PCIE_TXP2_LAN 9 PCIE_TXN2_LAN

12 PCIE_LAN_CLKP 12 PCIE_LAN_CLKN

PCIE_LAN_CLKP PCIE_LAN_CLKN

PCIE_RXN2_LAN_L PCIE_RXP2_LAN_L C70 .1U/10V_4 C78 .1U/10V_4

PCIE_RXN2_LAN 9 PCIE_RXP2_LAN 9

+EVDD12

SI , change to AL08103EB01 for support DSM chip

+3V

Delete R261 and add D38 as current loss issue

R55 *1K/F_4 R51 15K/F_4 ISOLATEB R44 100/F_4 D13 *RB501V-40 LAN_DISABLE# 13,32

if ISOLATEB pin pull-low,the LAN chip will not drive it's PCI-E outputs (excluding PCIE_WAKE# pin)

12 LAN_PLTRST#

U6 TC7SH08FU

+3V_LAN C64 0.1U/10V_4

LAN_REST_R#

R60 *0_6/S R57 *0_6/S LAN-AGND

DB modified to short-pad

HP request reserve white LED driver circuit

LAN_WLED# Q31 *DTC144EUA R404 *10K/F_4 +3VLANVCC Q32 *DTC144EUA LAN_WLED# Q

LAN_WLED# R413 *0_4/S

PV, change to short pad

SI , rotate 180 degree for EMI suggestion

Symbol	Type	Pin No (64-Pin)	Pin No (48-Pin)	Description				
LED0	O	57	38	LEDS1-0	00	01	10	11
LED1	O	56	35	LED0	Tx/Rx	Tx/Rx	Tx	Tx
LED2	O	55	34	LED1	LINK100	LINK	LINK	LINK100
LED3	O	54	33	LED2	LINK10	FULL	Rx	LINK10
				LED3	NA	NA	NA	NA

LAN_Transformer

U20 NS681684

LAN_MX1- LAN_MX1+ LAN_MCT1 LAN_MX0- LAN_MX0+ LAN_MCT0

RD+ RD- CT TD+ TD- CT

RX+ CT RX- TX- CMT TX+

MDI1- V_DAC_2 MDI1+ MDI0+ V_DAC_1 MDI0-

75/F_4 R112 LAN_MCT0_2 C161 0.01U/100V_0603

75/F_4 R111 LAN_MCT0_1 C159 0.01U/100V_0603

C610 1000P/3KV_1808

C117 .01U/16V_4 C118 .01U/16V_4

SI , change footprint to CC1808

Bios need change

EEDI_LED10# R392 *0_6 EESK_LED100# R391 *0_6/S

LAN_WLED# LAN_AMLED# C668 *.01U/16V_4 C699 *.01U/16V_4

EMI suggestion C663 .1U/10V_4

RJ45 CN25

+3V_LAN R387 330_4 LAN_AMLED LAN_AMLED#

LED_AMBER_P LED_AMBER_N

LAN_MX1- LAN_MX1+ LAN_MX0- LAN_MX0+

RX1- RX1+ RX0- TX1- TX1+ RX0+ TX0- TX0+ GND1 GND

+3V_LAN R403 330_4 LAN_WLED LAN_WLED# Q

LED_WHITE_P LED_WHITE_N

RJ45_CONN

Fixed RJ45 Pin define (0829)

Link

C697 .1U/10V_4

EMI suggestion

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	RTL8102EL/RJ45	1A

Date: Thursday, December 24, 2009 Sheet 30 of 42

POWER BUTTON CONNECTOR



1. +3VPCU(LIDSWITCH PWR)
2. LEDVCC(+3VPCU)
3. LIDSWITCH
4. POWERON#
5. PWRLED#
6. GND

KEYBOARD CONN

PV,update footprint to bl135h-32rla-tand-32p-l-smt



SI , update P/N

32 MY[0..17] MY[0..17]

32 MX[0..7] MX[0..7]

KEYBOARD PULL-UP



SI , reserve Q34,Q35,R499,R500 for dual_LED on keyboard



SATA CD-ROM

SI , delete CN13 change to ANT CONN







PV, change to reserve only





	PROJECT : AX2/7 Quanta Computer Inc.	
Size Custom	Document Number KEYBOARD/SW_BOARD/ODD	Rev 1A
Date: Thursday, December 24, 2009	Sheet 31 of 42	

U8

SERIRQ LFRAME# LAD0 LAD1 LAD2 LAD3 PCICLK PCIRST#/GPIO5 CLKRUN SCI#/GPIOE GA20/GPIO0 KBRST#/GPIO1 ECRST

KSI0/GPIO30 KSI1/GPIO31 KSI2/GPIO32 KSI3/GPIO33 KSI4/GPIO34 KSI5/GPIO35 KSI6/GPIO36 KSI7/GPIO37

KSO0/GPIO20 KSO1/GPIO21 KSO2/GPIO22 KSO3/GPIO23 KSO4/GPIO24 KSO5/GPIO25 KSO6/GPIO26 KSO7/GPIO27 KSO8/GPIO28 KSO9/GPIO29 KSO10/GPIO2A KSO11/GPIO2B KSO12/GPIO2C KSO13/GPIO2D KSO14/GPIO2E KSO15/GPIO2F KSO16/GPIO48 KSO17/GPIO49

PSCLK1/GPIO4A PSDAT1/GPIO4B PSCLK2/GPIO4C PSDAT2/GPIO4D PSCLK3/GPIO4E PSDAT3/GPIO4F

RD WR SELMEM/SPICS SELIO/GPIO50

AD5/GPI43 D0/GPXD0 D1/GPXD1 D2/GPXD2 D3/GPXD3 D4/GPXD4 D5/GPXD5 D6/GPXD6 D7/GPXD7

A0/GPXA0 A1/GPXA1 A2/GPXA2 A3/GPXA3 A4/GPXA4 A5/GPXA5 A6/GPXA6 A7/GPXA7 A8/GPXA8 A9/GPXA9 A10/GPXA10 A11/GPXA11

V18R

VCC1 VCC2 VCC3 VCC4 VCC5 VCC6 AVCC

GND1 GND2 GND3 GND4 GND5 AGND

XCLKO XCLKI

AD0/GPI38 AD1/GPI39 AD2/GPI3A AD3/GPI3B

DA0/GPO3C DA1/GPO3D DA2/GPO3E DA3/GPO3F

PWM1/GPIOF PWM2/GPIO10

FANPWM1/GPIO12 FANPWM2/GPIO13 FANFB1/GPIO14 FANFB2/GPIO15

SCL1/GPIO44 SDA1/GPIO45 SCL2/GPIO46 SDA2/GPIO47

GPIO4 GPIO7 GPIO8 GPIOA GPIOB GPIOC GPIOD GPIO11 GPIO16 GPIO17 GPIO18 GPIO19 GPIO1A GPIO40 GPIO41 AD4/GPI42 GPIO52 GPIO53 GPIO54 GPIO55 GPIO56 GPIO57 GPIO58 GPIO59

KB3926

+3VPCU +3VPCU_EC

C584 4.7U/6.3V_6
C143 0.1U/10V_4
C590 0.1U/10V_4
C592 0.1U/10V_4
C589 0.1U/10V_4
C586 0.1U/10V_4
C591 0.1U/10V_4
C131 4.7U/6.3V_6

TEMP_MBAT 40
AD_TYPE
AD_AIR 40
SYS_I 40
CC-SET 40
CELL_SLT 40
FAN1ON 28
D/C# 40
PWM_VADJ 23
KEY_BEEP (1KHz) T91

CV-SET 40
EC_ACLIM 40
FAN1SIG 28
ODD_PD 31

MBCLK 5,40
MBDATA 5,40
MBCLK2 5,18
MBDATA2 5,18

SUSB# 13
HWPG 23,34,35,37,39
CPU_PROCHOT# 3
SUSC# 13
T5
NBSWON1# 31
LAN_REST# 30
EC_DEBUG1 33
EMU_LID 23
KBSMI#1
VRON 35,36,37,39
NUMLED# 31
EJECT# 31
T9
T10
OP_FAN_SEL
DNBSWON#1
CAPSLED# 31
PWR_LED# 31
ECPWROK 5,16
RSMRST# 13
VOLMUTE# 27
SPI_CLK
LID_EC# 23,31

CRY2 CRY1
C57 27P/50V_4
C50 27P/50V_4
32.768KHZ
Y1

C585 0.1U/10V_4
C587 4.7U/6.3V_6
For KB3926 C version

PV, change from 18p to 27p from vendor update

SI , change package

SI , add for DSM

R61 *0_4/S

SERR# VGA_ON_SB VGA_PWROK T1 T2 RF_LINK# BLUELED LAN CABLE DETECT T8 ACIN TPCLK TPDATA SLPBTN# Vari_ON BIOS_RD# BIOS_WR# BIOS_CS#

USBPW_ON# SUSON MAINON LAN_POWER S5_ON VR2.5_ON VGACOREON MBATLED0# AC_LED_ON# WIRELESS_ON WIRELESS_OFF

MX0 MX1 MX2 MX3 MX4 MX5 MX6 MX7

MY0 MY1 MY2 MY3 MY4 MY5 MY6 MY7 MY8 MY9 MY10 MY11 MY12 MY13 MY14 MY15 MY16 MY17

SERIRQ LFRAME# LAD0 LAD1 LAD2 LAD3 PCLK_LPC_KB3920 PCIRST# CLKRUN#

SCI1# GATEA20 RCIN# 3920_RST#

+3V R71 10K/F_4 HWPG

+3VPCU R78 10K/F_4 NBSWON1#
R74 10K/F_4 SLPBTN#
R346 4.7K_4 MBCLK
R345 4.7K_4 MBDATA

RSMRST# RSMRST# 13
+3VPCU R336 *8.2K_4 C588 2.2U/6.3V_6

PV , change to test point

Battery charge/discharge Cap button

VGA thermal system thermal

M93_STRP R552 *1K/F_4

PV,reserve for identify M93-LP VGA chip

+3VPCU R65 *10K/F_4 Vari_ON R68 10K/F_4

SI , enable Vari-bright need pull low

+3VPCU C80 0.1U/10V_4

U17 MX25L1605DM2I-12G
BIOS_CS# SPI_CLK R89 33_4 BIOS_WR# BIOS_RD#
CE# SCK SI SO WP# HOLD# VDD VSS
+3VPCU R84 10K/F_4 SPI_3P
R76 10K/F_4 SPI_7P

MAX AKE38FP0Z00 2M byte
WINBOND AKE38FP0N01 SPI
EON AKE38ZA0Q00 BIOS
SOCKET DG008000031

Project Model	GPIO42
AX 14"	High
AX 15.6"	Low
AX 17.3"	Middle (1.5V)

GPIO42 control fan table

OP_FAN_SEL R90 *10K/F_4 +3VPCU R79 10K/F_4

+3VPCU R105 47K_4 3920_RST# C144 0.1U/10V_4 3920_RST# 5

29,33 BLUELED BLUELED R41 100K/F_4

SCI1# D25 CH501H-40PT SCI# 13

DNBSWON#1 D12 RB500V-40 DNBSWON# 13

KBSMI#1 D27 RB500V-40 KBSMI# 13

Change D12, D16 to RB500 for current loss

MAINON C464 2200P/50V_4

PV,add for EMI

+3VPCU_EC +3VPCU L13 *SBK160808T-680Y-N(0.3A,68)

U19 TPS73133
VOUT VIN SHDN NR/FB GND
C114 4.7U/6.3V_6
C130 *1U/6.3V_4
C613 *1U/6.3V_4
+5VPCU

+3VPCU D26 1SS355

AD_TYPE R109 100/F_4 AD_ID 40

C147 0.1U/10V_4 R108 24.3K/F_4

PROJECT : AX2/7
Quanta Computer Inc.

Size: Custom | Document Number: KB3926/ROM/TP | Rev 1A
Date: Thursday, December 24, 2009 | Sheet 32 of 42

Mini PCI-E Card 1 WLAN





SI , change footprint to led1-s110kgct-3p-nb5

PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	Mini CARD/LED	1A

Date: Thursday, December 24, 2009 | Sheet 33 of 42

DC/DC +3V_ALW/+5V_ALW/+5V_ALW2 /+15V_ALW



PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	+5V/+3V (RT8206B)	1A

Date: Thursday, December 24, 2009 | Sheet 34 of 42



DYN_PWR_EN	High	Low
+1.1V_DYN	0.95	1.1

ISL6265 Pin1	OFS	VFIXEN
1.2V	V	X
3.3V	X	V
5V	X	X

VFIXEN VID Codes

SVC	SVD	Output
0	0	1.4
0	1	1.2
1	0	1.0
1	1	0.8



PROJECT : AX2/7
Quanta Computer Inc.
Size C | Document Number CPU_CORE(ISL6265) | Rev 1A
NB5/RD2
Date: Thursday, December 24, 2009 | Sheet 36 of 42



NB5/RD2	PROJECT : AX2/7 Quanta Computer Inc. SANTOS INTEL	
Size	Document Number DDR3 (RT8207)	Rev 1A
Date: Thursday, December 24, 2009	Sheet 37 of 42	

VGA Core



	PWRCNTL1	PWRCNTL0	V-CORE
L	0	0	0.9V
M	0	1	0.96V
H	1	0	1.06V
TBD	1	1	1.12V





PROJECT : AX2/7
Quanta Computer Inc.

Size	Document Number	Rev
Custom	CHARGER (ISL6251)	1A

Date: Thursday, December 24, 2009 | Sheet 40 of 42

NB5/RD2

CPU Power 1



CPU Power 2







1 S5_ON, S5_OND, RSMRST# → 2 SUSON, SUSD → 3 MAINON, MAIND → 4 HWPG, VCORE_PG, VRM_PWRGD → EC Pin76 ECPWROK, Delay 600ms → SB_PWRGD_IN 3.3V → NB_PWRGD_IN 1.8V

NB5/RD2	PROJECT : AX2/7 Quanta Computer Inc.		
	Size: Custom	Document Number: Power control	Rev: 3A
	Date: Thursday, December 24, 2009	Sheet 41 of 42	

Power & Ground

Label	ACTIVE	Description	Control Signal
+VIN	S0, S3, S4, S5	AC ADAPTER (19V)	
+3VPCU	S0, S3, S4, S5	ALWAYS POWER (3V)	
+3V	S0		MAINON
+3VSUS	S0, S3		SUSON
+3VS5	S0, S3, S4, S5		S5_ON
+3VLANVCC	S0		LAN_POWER
+5VPCU	S0, S3, S4, S5	ALWAYS POWER (5V)	
+5V	S0		MAINON
+5V_VCC1			
+5VALW			
+10VALW			
+15VALW			
+1.8V	S0		+1.5_ON
+1.8VSUS	S0, S3		
+1.5V	S0		MAINON
+1.5VSUS	S0, S3	DDR CORE POWER	SUSON
+1.5VSUS_1			
+1.5V_VGA	S0	VGA , VRAM POWER	+1.5_ON
+1.2V	S0		VRON
+1.2VSUS	S0, S3		SUSON
+1.1V	S0	VDDPCIE - PCIE-E MAIN POWER	VRON
+1.1VS5	S0, S3, S4, S5	STANDBY POWER	S5_ON
+1.1V_DYN	S0	NB VDDC - CORE LOGIC POWER	DYN_PWR_EN
+1.05V	S0	HT POWER (1.05V)	VRON
+1.0V_VGA	S0	PARK DPX_VDD10 POWER	VRON
+2.5V	S0	CPU VDDA POWER	VR2.5_ON
+VCORE0	S0	CPU CORE POWER (?V)	VRON
+VCORE1	S0	CPU CORE POWER (?V)	VRON
+CPUVDDNB	S0	CPU VDDNB POWER	VRON
+0.75_DDR_VTT	S0	DDR COMMAND & CONTROL PULL UP POWER	SUSON
DDR_VTTREF	S0, S3	DDR REFERENCE POWER	SUSON
+VGA_CORE	S0	VGA CORE POWER	MAINON
+AVBAT	S0, S3, S4, S5	RTC & KBC POWER (3_3V)	

SMBUS

DEVICE	ADDRESS	BUS
CLOCK GENERATOR		
DDR3		
CPU THERMAL SENSOR		
CHARGER		

PCB STACK UP

LAYER 1 : TOP
LAYER 2 :GND
LAYER 3 : IN1
LAYER 4 : IN2
LAYER 5 : VCC
LAYER 6 : BOT

PCI DEVICES IRQ ROUTING

DEVICE	IDSEL #	REQ/GNT #	PCI_INT

PROJECT : AX2/7
Quanta Computer Inc.

Custom<Doc> MB/NB

Size	Document Number	Rev
		1A

Date: Wednesday, December 23, 2009 Sheet 42 of 42