Page	Title of schematic page	Rev.	Date
01	Page List	2A	12/24
02	Block Diagram	2A	12/24
03	CPU-Champlain HT/CONTROL (1/3)	2A	01/04
04	CPU-Champlain MEMORY (2/3)	1B	12/16
05	CPU-Champlain POWER/GND (3/3)	1B	12/08
06	NB-RS880M HT/SP-MEM (1/4)	1B	12/08
07	NB-RS880M GFX/PCIE (2/4)	1A	09/24
08	NB-RS880M SYSTEM (3/4)	1A	09/24
09	NB-RS880M POWER (4/4)	1A	09/24
10	SB-SB820M PCI/CLK/LPC (1/4)	1A	09/24
11	SB-SB820M AUDIO/USB (2/4)	1A	09/24
12	SB-SB820M SATA (3/4)	1B	12/08
13	SB-SB820M POWER (4/4)	1A	09/24
14	DDR3 SODIMM* 2 (5.2mm+9.2mm)	2A	12/24
15	ATI-Madison LP PCIE/LVDS (1/5)	2A	12/24
16	ATI-Madison LP MAIN I/O (2/5)	2A	12/24
17	ATI-Madison LP POWER/GND (3/5)	2A	12/24
18	ATI-Madison LP Display POWER (4/5)	2A	12/24
19	ATI-Madison LP MEM I/F (5/5)	2A	12/24
20	ATI-Madison LP (DDR3 V-ram a)	2A	12/24
21	ATI-Madison LP (DDR3 V-ram b)	1B	12/08
22	CRT/LVDS	2A	12/24

Page	Title of schematic page	Rev.	Date
23	HDMI	1B	12/09
24	WLAN/HDD/ODD	1B	12/08
25	Card Reader RTS5186	1B	12/08
26	Express Card/BT/LED	1B	12/08
27	Codec-ALC269Q VB5 GR	1B	12/08
28	LAN RTL8111E	1B	12/08
29	NPCE781	1B	12/08
30	KB/USB/FAN/PS	1B	12/09
31	VCORE(ISL6265A)	1A	09/24
32	3VPCU&5VPCU(PM6686)	1A	09/24
33	1.5VSUS/VTT_MEM	1A	09/24
34	DYN_VCC1.1(OZ8116LN)	1A	09/24
35	VCC1.1(OZ8116LN)-7A	1A	09/24
36	VGA_CORE(OZ8116)-16A	1A	09/24
37	VCC1.8/0.9/2.5/1.0	1A	09/24
38	POWER(BAT IN / ADA IN/ UL)	1A	09/24
39	CHARGER (ISL6252A)	1A	09/24
40	Small board connector	1A	09/24
41	Power Sequence		
42	CHANGE LIST		

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	AMD Danube	2A
Date: Wednesday, January 27, 2010	Sheet 1 of 42	

Danube Block Diagram

02



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	Danube - Block Diagram	2A
Date: Wednesday, January 27, 2010	Sheet 2 of 42	

VCC1.1 — 1.5A(1.8W)

C328 4.7U/6.3V_6 | C324 4.7U/6.3V_6 | C335 4.7U/6.3V_6 | C323 0.22U/6.3V_4 | C336 0.22U/6.3V_4 | C341 180p_4 | C333 180p_4

U37A — HT LINK — SOCKET_638_PIN

VLDT_A0 D1, VLDT_A1 D2, VLDT_A2 D3, VLDT_A3 D4 — VLDT_B0 AE2, VLDT_B1 AE3, VLDT_B2 AE4, VLDT_B3 AE5 — VCC1.1

L0_CADIN		L0_CADOUT	
HT_CADIN_H0	E3	AD1	HT_CADOUT_H0
HT_CADIN_L0	E2	AC1	HT_CADOUT_L0
HT_CADIN_H1	E1	AC2	HT_CADOUT_H1
HT_CADIN_L1	F1	AC3	HT_CADOUT_L1
HT_CADIN_H2	G3	AB1	HT_CADOUT_H2
HT_CADIN_L2	G2	AA1	HT_CADOUT_L2
HT_CADIN_H3	G1	AA2	HT_CADOUT_H3
HT_CADIN_L3	H1	AA3	HT_CADOUT_L3
HT_CADIN_H4	J1	W2	HT_CADOUT_H4
HT_CADIN_L4	K1	W3	HT_CADOUT_L4
HT_CADIN_H5	L3	V1	HT_CADOUT_H5
HT_CADIN_L5	L2	U1	HT_CADOUT_L5
HT_CADIN_H6	L1	U2	HT_CADOUT_H6
HT_CADIN_L6	M1	U3	HT_CADOUT_L6
HT_CADIN_H7	N3	T1	HT_CADOUT_H7
HT_CADIN_L7	N2	R1	HT_CADOUT_L7
HT_CADIN_H8	E5	AD4	HT_CADOUT_H8
HT_CADIN_L8	F5	AD3	HT_CADOUT_L8
HT_CADIN_H9	F3	AD5	HT_CADOUT_H9
HT_CADIN_L9	F4	AC5	HT_CADOUT_L9
HT_CADIN_H10	G5	AB4	HT_CADOUT_H10
HT_CADIN_L10	H5	AB3	HT_CADOUT_L10
HT_CADIN_H11	H3	AB5	HT_CADOUT_H11
HT_CADIN_L11	H4	AA5	HT_CADOUT_L11
HT_CADIN_H12	K3	Y5	HT_CADOUT_H12
HT_CADIN_L12	K4	W5	HT_CADOUT_L12
HT_CADIN_H13	L5	V4	HT_CADOUT_H13
HT_CADIN_L13	M5	V3	HT_CADOUT_L13
HT_CADIN_H14	M3	V5	HT_CADOUT_H14
HT_CADIN_L14	M4	U5	HT_CADOUT_L14
HT_CADIN_H15	N5	T4	HT_CADOUT_H15
HT_CADIN_L15	P5	T3	HT_CADOUT_L15
HT_CLKIN_H0	J3	Y1	HT_CLKOUT_H0
HT_CLKIN_L0	J2	W1	HT_CLKOUT_L0
HT_CLKIN_H1	J5	Y4	HT_CLKOUT_H1
HT_CLKIN_L1	K5	Y3	HT_CLKOUT_L1
HT_CTLIN_H0	N1	R2	HT_CTLOUT_H0
HT_CTLIN_L0	P1	R3	HT_CTLOUT_L0
HT_CTLIN_H1	P3	T5	HT_CTLOUT_H1
HT_CTLIN_L1	P4	R5	HT_CTLOUT_L1

HT_CADIN_H[0..15] (6) — HT_CADOUT_H[0..15] (6)
HT_CADIN_L[0..15] (6) — HT_CADOUT_L[0..15] (6)
HT_CLKIN_H[0..1] (6) — HT_CLKOUT_H[0..1] (6)
HT_CLKIN_L[0..1] (6) — HT_CLKOUT_L[0..1] (6)
HT_CTLIN_H[0..1] (6) — HT_CTLOUT_H[0..1] (6)
HT_CTLIN_L[0..1] (6) — HT_CTLOUT_L[0..1] (6)

VCC3 — C378 0.1u/10V_4 — U25 G780P81U

(11) TS_ALERT# — ALERT
(32) SHDN# — T_CRIT_A
VCC — SMBCLK — SMB_CLK — SMB_CLK (16)
ALERT — SMDATA — SMB_DAT — SMB_DAT (16)
D+ — THERMDA
GND — D- — C368 220P_4 — THERMDC

VCC2.5 — C326 4.7U/6.3V_6 | C339 1u/6.3V_4 | C330 0.1u/10V_4

T61 — HCLK_CPU_C — R224 169/F_4 — HCLK_CPU# — T57

(10) CLK_CPU_HTP — C372 3900p_4 — HCLK_CPU_C
(10) CLK_CPU_HTN — C369 3900p_4 — HCLK_CPU# C

(10) CPU_LDT_RST# — R470 0_4 — R_CPU_LDT_RST#
(10,31) CPU_LDT_PWRGD — CPU_LDT_PWRGD
(8,10) CPU_LDT_STOP# — CPU_LDT_STOP#
CPU_LDT_REQ# CPU

2A Guam for debug

(11) CPU_SIC — SIC
(11) CPU_SID — SID
CPU_ALERT — ALERT_L

VCC1.1 — R218 44.2/F_4 — HT_REF0 — R6
R219 44.2/F_4 — HT_REF1 — P6

1.5VSUS — R350 1K/F_4 — CPU_SIC
R349 1K/F_4 — CPU_SID
R348 1K/F_4 — CPU_ALERT

(31) CPU_VDD0_FB_H — F6
(31) CPU_VDD0_FB_L — E6
(31) CPU_VDD1_FB_H — Y6
(31) CPU_VDD1_FB_L — AB6

TDI、TDO、TCK、TMS、TRST_L：for ICT

T62 CPU_DBRDY — G10
T58 CPU_TMS — AA9
T55 CPU_TCK — AC9
T83 CPU_TRST# — AD9
T82 CPU_TDI — AF9
T42 CPUTEST23 — AD7

R228 1K/F_4 — CPUTEST18 — H10
R186 1K/F_4 — CPUTEST19 — G9

1.5VSUS — R241 510/F_4 — CPUTEST25H — E9
R189 510/F_4 — CPUTEST25L — E8

T44
R199 1K/F_4 — CPUTEST21 — AB8
R201 1K/F_4 — CPUTEST20 — AF7
R200 1K/F_4 — CPUTEST24 — AE7
R202 1K/F_4 — CPUTEST22 — AE8
R197 1K/F_4 — CPUTEST12 — AC8
R206 1K/F_4 — CPUTEST27 — AF8

1.5VSUS

R351 0_4 — C2
AA6
A3, A5, B3, B5, C1

U37D — SOCKET_638_PIN

VDDA1	F8	VSS	M11
VDDA2	F9	RSVD11	W18
CLKIN_H	A9	SVC	A6 — CPU_SVC_R
CLKIN_L	A8	SVD	A4 — CPU_SVD_R
RESET_L	B7		
PWROK	A7		
LDTSTOP_L	F10	THERMTRIP_L	AF6 — CPU_THERMTRIP# L
LDTREQ_L	C6	PROCHOT_L	AC7 — CPU_PROCHOT# L
		MEMHOT_L	AA8 — CPU_MEMHOT# L
SIC	AF4		
SID	AF5		
ALERT_L	AE6	THERMDC	W7 — THERMDC
		THERMDA	W8 — THERMDA
HT_REF0	R6		
HT_REF1	P6		
VDD0_FB_H	F6	VDDIO_FB_H	W9
VDD0_FB_L	E6	VDDIO_FB_L	Y9
VDD1_FB_H	Y6	VDDNB_FB_H	H6 — CPU_VDDNB_FB_H (31)
VDD1_FB_L	AB6	VDDNB_FB_L	G6 — CPU_VDDNB_FB_L (31)
DBRDY	G10		
TMS	AA9	DBREQ_L	E10 — CPU_DBREQ#
TCK	AC9		301/F_4 — R240 — 1.5VSUS
TRST_L	AD9	TDO	AE9 — CPU_TDO — T45
TDI	AF9		
TEST23	AD7	TEST28_H	J7 — T54
		TEST28_L	H8 — T63
TEST18	H10	TEST17	D7 — T40
TEST19	G9	TEST16	E7 — T59
TEST25_H	E9	TEST15	E7 — R188 *301/F_4
TEST25_L	E8	TEST14	C7 — R194 *301/F_4
TEST21	AB8	TEST7	C3
TEST20	AF7	TEST10	K8
TEST24	AE7		
TEST22	AE8	TEST8	C4 — CPUTEST29H
TEST12	AC8		
TEST27	AF8		R195 80.6/F_4
		TEST29_H	C9
TEST9	C2	TEST29_L	C8 — CPUTEST29L
TEST6	AA6		
RSVD1	A3	RSVD10	H18
RSVD2	A5	RSVD9	H19
RSVD3	B3	RSVD8	AA7
RSVD4	B5	RSVD7	D5
RSVD5	C1	RSVD6	C5

Q14 — 2N7002DW

SMB_CLK — 1 — 6 — BATT_SCK (29,38)
VCC3 — R237 10K_4 — 2 — VCC3
SMB_DAT — 4 — 3 — BATT_SDA (29,38)
VCC3 — R238 10K_4 — 5 — VCC3

For AMD Debug only

CON26 — *HDT_CONN — KEY

CPU_DBREQ# 1
CPU_DBRDY 2
CPU_TCK 3
CPU_TMS 4
CPU_TDI 5
CPU_TRST# 6
CPU_TDO 7
1.5VSUS 8
CPU_LDT_RST# 9
C289 0.1u_4
C452 *33p
2A Guam for debug

T50 CPU_LDT_RST# — 301/F_4 — R464 — VCC1.5
T41 CPU_LDT_REQ# CPU — *301/F_4 — R192
CPU_LDT_PWRGD — 301/F_4 — R193
C338 *0.1u/10V_4
CPU_LDT_STOP# — 301/F_4 — R227 — VCC1.5

2A shut down issue

1.5VSUS — R157 10K_4 — RVCC3
1.5VSUS — R183 1K/F_4 — Q12 MMBT3904 — R158 10K_4
CPU_THERMTRIP# L — CPU_THERMTRIP# (11)
C305 *0.1u/10V_4

to external thermal sensor

1.5VSUS — R173 1K/F_4
CPU_PROCHOT# L — R468 0_4 — CPU_PROCHOT# (10)

1.5VSUS — R160 *10K_4
1.5VSUS — R159 *1K/F_4 — Q10 *MMBT3904
CPU_MEMHOT# — MEMHOT# (10,14)
C288 *0.1u/10V_4

S1g4 does not support MEMHOT#

VFIX MODE — VID Override Circuit

SVC	SVD	Voltage Output
0	0	1.1V
0	1	1.0V
1	0	0.9V
1	1	0.8V

VCC1.5 — R176 1K/F_4 — R182 1K/F_4
CPU_SVC_R — R191 0_4 — CPU_SVC (31)
CPU_SVD_R — R190 0_4 — CPU_SVD (31)
R177 *301/F_4 — R175 *301/F_4

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	CPU HT/CONTROL(1/3)	2A
Date: Wednesday, January 27, 2010	Sheet 3 of 42	

Processor Memory Interface

04

CPU_VDDR : 35W->0.9V
45W->1.05V







1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	CPU MEMORY(2/3)	2A
Date: Wednesday, January 27, 2010	Sheet 4 of 42	

Socket Type	QCI P/N
Normal	DG0^8000018
90 degree	DG0^8000023











1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	CPU POWER/GND(3/3)	2A
Date: Wednesday, January 27, 2010	Sheet 5 of 42	



This block is for Side Port only , others can remove some components



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	RS880M HT/SPMEM(1/4)	2A
Date: Wednesday, January 27, 2010	Sheet 6 of 42	



GLAN

WLAN

Close NB within 1"

Layout Swap
TX11, TX10, TX9,
TX8,TX7,TX6, TX5,
TX4, TX3, TX2, TX0

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	RS880M GFX/PCIE(2/4)	2A
Date: Wednesday, January 27, 2010	Sheet 7 of 42	



Enables Debug Bus acess
through memory I/O pads and GPIO.
0 : Enable RS880M , Default
1 : Disable RS880M



Discrete：Connect
A11, B11

Indicates if memory Side port
is available or not
1: Disable side port memory
0: Enable side port memory

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	RS880M SYSTEM(3/4)	2A

Date: Wednesday, January 27, 2010 Sheet 8 of 42



RS880M/RX881 POWER DIFFERENCE TABLE

PIN NAME	RX881	RS880M	PIN NAME	RX881	RS880M
VDDHT	+1.1V	+1.1V	IOPLLVDD	NC	+1.1V
VDDHTRX	+1.1V	+1.1V	AVDD	NC	+3.3V
VDDHTTX	+1.1V	+1.1V	AVDDDI	NC	+1.8V
VDDA18PCIE	+1.8V	+1.8V	AVDDQ	NC	+1.8V
VDDG18	+1.8V	+1.8V	PLLVDD	NC	+1.1V
VDD18_MEM	NC	+1.8V	PLLVDD18	NC	+1.8V
VDDPCIE	+1.1V	+1.1V	VDDA18PCIEPLL	+1.8V	+1.8V
VDDC	+1.1V	+1.1V	VDDA18HTPLL	+1.8V	+1.8V
VDD_MEM	NC	+1.5V	VDDLTP18	NC	+1.8V
VDDG33	NC	+3.3V	VDDLT18	NC	+1.8V
IOPLLVDD18	NC	+1.8V	VDDLT33	NC	NC



VDD18_MEM For UMA RS880 only
Not applicable to RX881
memory I/O transform

	VDD_MEM
W Side-Port	VCC1.5
W/O Side-Port	GND

	VDD18_MEM
W Side-Port	VCC1.8
W/O Side-Port	GND

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	RS880M POWER(4/4)	2A
Date: Wednesday, January 27, 2010	Sheet 9 of 42	

Strap Table

PCI_CLK1	PCI_CLK2	PCI_CLK3	PCI_CLK4
ALLOW PCIE Gen2	Watchdog Timer Enable	USE DEBUG STRAPS	non_Fusion CLOCK MODE DEFAULT
FORCE PCIE Gen1 DEFAULT	Watchdog Timer Disable DEFAULT	IGNORE DEBUG STRAPS DEFAULT	Fusion CLOCK MODE

RTC

PCI Strap

SB820M PD

12/17 Eric R145/R143/R139/R148 DNI

SB8xx only supports 2 GPP port 2 &3 is not supported.

GPP4、5 used for NB PCIE

BB Rework

2A：check R247 mount or not?

Low=0.9V, High=1.05V

add for AMD test

add for AMD test

1B Adding

1B adding for EC 781

INTRUDER_ALERT# Southbridge has 50-k ohm internal pull-up to VBAT

LPCLK0	LPCLK1
H=Enable embedded EC	H=Enable Internal CLK Gen.
L=Disable embedded EC	L=Disable Internal CLK Gen.

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	SB820 PCI/CLK/LPC(1/4)	2A
Date: Thursday, January 28, 2010	Sheet 10 of 42	

U40D

SB820
Part 4 of 5

PCI_PME#/GEVENT4#
R#/GEVENT22#
SPI_CS3#/GBE_STAT1/GEVENT21#
SLP_S3#
SLP_S5#
PWR_BTN#
PWR_GOOD
SUS_STAT#
TEST0
TEST1/TMS
TEST2
GA20IN/GEVENT0#
KBRST#/GEVENT1#
LPC_PME#/GEVENT3#
LPC_SMI#/GEVENT23#
GEVENT5#
SYS_RESET#/GEVENT19#
WAKE#/GEVENT8#
IR_RX1/GEVENT20#
THRMTRIP#/SMBALERT#/GEVENT2#
NB_PWRGD
RSMRST#

ACPI / WAKE UP EVENTS

USBCLK/14M_25M_48M_OSC
USB_RCOMP
USB_FSD1P/GPIO186
USB_FSD1N
USB_FSD0P/GPIO185
USB_FSD0N

USB 1.1 USB MISC

USB_HSD13P
USB_HSD13N
USB_HSD12P
USB_HSD12N
USB_HSD11P
USB_HSD11N
USB_HSD10P
USB_HSD10N
USB_HSD9P
USB_HSD9N
USB_HSD8P
USB_HSD8N
USB_HSD7P
USB_HSD7N
USB_HSD6P
USB_HSD6N
USB_HSD5P
USB_HSD5N
USB_HSD4P
USB_HSD4N
USB_HSD3P
USB_HSD3N
USB_HSD2P
USB_HSD2N
USB_HSD1P
USB_HSD1N
USB_HSD0P
USB_HSD0N

USB 2.0

CLK_REQ4#/SATA_IS0#/GPIO64
CLK_REQ3#/SATA_IS1#/GPIO63
SMARTVOLT1/SATA_IS2#/GPIO50
CLK_REQ0#/SATA_IS3#/GPIO60
SATA_IS4#/FANOUT3/GPIO55
SATA_IS5#/FANIN3/GPIO59
SPKR/GPIO66
SCL0/GPIO43
SDA0/GPIO47
SCL1/GPIO227
SDA1/GPIO228
CLK_REQ2#/FANIN4/GPIO62
CLK_REQ1#/FANOUT4/GPIO61
IR_LED#/LLB#/GPIO184
SMARTVOLT2/SHUTDOWN#/GPIO51
DDR3_RST#/GEVENT7#
GBE_LED0/GPIO183
GBE_LED1/GEVENT9#
GBE_LED2/GEVENT10#
GBE_STAT0/GEVENT11#
CLK_REQG#/GPIO65/OSCIN

GPIO

BLINK/USB_OC7#/GEVENT18#
USB_OC6#/IR_TX1/GEVENT6#
USB_OC5#/IR_TX0/GEVENT17#
USB_OC4#/IR_RX0/GEVENT16#
USB_OC3#/AC_PRES/TDO/GEVENT15#
USB_OC2#/TCK/GEVENT14#
USB_OC1#/TDI/GEVENT13#
USB_OC0#/TRST#/GEVENT12#

USB OC

AZ_BITCLK
AZ_SDOUT
AZ_SDIN0/GPIO167
AZ_SDIN1/GPIO168
AZ_SDIN2/GPIO169
AZ_SDIN3/GPIO170
AZ_SYNC
AZ_RST#

HD AUDIO

GBE_COL
GBE_CRS
GBE_MDCK
GBE_MDIO
GBE_RXCLK
GBE_RXD3
GBE_RXD2
GBE_RXD1
GBE_RXD0
GBE_RXCTL/RXDV
GBE_RXERR
GBE_TXCLK
GBE_TXD3
GBE_TXD2
GBE_TXD1
GBE_TXD0
GBE_TXCTL/TXEN
GBE_PHY_PD
GBE_PHY_RST#
GBE_PHY_INTR

GBE LAN

PS2_DAT/SDA4/GPIO187
PS2_CLK/SCL4/GPIO188
SPI_CS2#/GBE_STAT2/GPIO166
FC_RST#/GPO160

PS2KB_DAT/GPIO189
PS2KB_CLK/GPIO190
PS2M_DAT/GPIO191
PS2M_CLK/GPIO192

EMBEDDED CTRL

SCL2/GPIO193
SDA2/GPIO194
SCL3_LV/GPIO195
SDA3_LV/GPIO196
EC_PWM0/EC_TIMER0/GPIO197
EC_PWM1/EC_TIMER1/GPIO198
EC_PWM2/EC_TIMER2/GPIO199
EC_PWM3/EC_TIMER3/GPIO200

KSI_0/GPIO201
KSI_1/GPIO202
KSI_2/GPIO203
KSI_3/GPIO204
KSI_4/GPIO205
KSI_5/GPIO206
KSI_6/GPIO207
KSI_7/GPIO208

KSO_0/GPIO209
KSO_1/GPIO210
KSO_2/GPIO211
KSO_3/GPIO212
KSO_4/GPIO213
KSO_5/GPIO214
KSO_6/GPIO215
KSO_7/GPIO216
KSO_8/GPIO217
KSO_9/GPIO218
KSO_10/GPIO219
KSO_11/GPIO220
KSO_12/GPIO221
KSO_13/GPIO222
KSO_14/GPIO223
KSO_15/GPIO224
KSO_16/GPIO225
KSO_17/GPIO226

EMBEDDED CTRL

SB820M A12

Blue Tooth
Card Reader
WiMAX
Camera
USB_PORT #3(Small board)
USB_PORT #2(Samll Board)
USB_PORT #1(Samll Board)
USB_PORT #0(M/B)

add for AMD tes
1B : Bear adding
UMA : SP only
add for AMD test
For EMI
2A : Remove Express
2A change value
1B: 12/2 AMD commend
add for AMD test

AZ_SDOUT
H=Low performance mode
L=High performance mode

	GPIO200, GPIO199
PULL HIGH	H, H=Reserved H, L=SPI ROM
PULL LOW	L, H=LPC ROM(Default) L, L=FWH ROM

Reserved for RSMRST#
20ms Dealy?

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	SB820 AUDIO/USB(3/4)	2A
Date: Wednesday, January 27, 2010	Sheet 11 of 42	



GPIOD[150:128] are open drain GPIO pins where as GPO160 is an open drain GPO pin. These pins are not programmed to GPIO mode by default.

ID2	ID1	ID0	
0	0	0	Danube UMA
0	0	1	Danube UMA+Side port
0	1	0	Danube+Park XT
0	1	1	Danube+Madison LP
1	0	0	Danube+M92 XTX
1	0	1	
1	1	0	
1	1	1	

	NON	SAMSUNG	HYNIX	
SP ID0	0	1	0	1
SP ID1	0	0	1	1



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	SB820 SATA(2/4)	2A

Date: Wednesday, January 27, 2010 Sheet 12 of 42





1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	SB820 POWER(4/4)	2A
Date: Wednesday, January 27, 2010	Sheet 13 of 42	

(H=9.2mm)

CN7

PC3-XXXX DDR3 SDRAM SO-DIMM (204P)

DDR3-DIMM1

LTK DDRRK-20401-TP8D

(H=5.2mm)

CN8

PC3-XXXX DDR3 SDRAM SO-DIMM (204P)

DDR3-DIMM0

LTK DDRRK-20401-TP4B

BB Rework

12/17 Eric Cost down cap

Place these Caps near So-Dimm1.

Place these Caps near So-Dimm0.

12/17 Eric Cost down cap

1A: Eric 1006 add MEMHOT event

8mm : DGMK4000087
9.2mm : DGMK4000029

4mm : DGMK4000005
5.2mm : DGMK4000028

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	DDR3 SODIMMX2	2A
Date: Wednesday, January 27, 2010	Sheet 14 of 42	





1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	ATI PCIE/LVDS	2A
Date: Wednesday, January 27, 2010	Sheet 15 of 42	

MEMID[3:0]	Vendor	Type	Vendor P/N	
0000				
0001	Hinyx	64*16-800MHZ	H5TQ1G63BFR-12C	AKD5LZGTW00
0010	Samsung	64*16-800MHZ	K4W1G1646E-HC12	AKD5LGGT502
0011	Ati	64*16-800MHZ	23EY2387MA-12	AKD5LGGT701
0100			Reserved	
0101			Reserved	
0110			Reserved	
0111			Reserved	
1000			Reserved	
1001			Reserved	
1010			Reserved	
1011			Reserved	
1100			Reserved	
1101			Reserved	
1110			Reserved	
1111			Reserved	
	Samsung	64*16-900MHZ	K4W1G1646E-HC11	

GPIO0 : PCIE FULL TX OUTPUT SWING
GPIO1 : PCIE TRANSMITTER DE-EMPHASIS ENABLED
GPIO2 : BIF_GEN2_EN_A
GPIO8 : RESERVED
GPIO9 : VGA ENABLED
GPIO[13:11] : SERIAL ROM TYPE OR MEMORY APERTURE SIZE SELECT
V2SYNC : IGNORE VIP DEVICE STRAPS
H2SYNC : 0
GENERICC : 0
HSYNC : 1 （AUDIO FOR BOTH DP AND HDMI）
VSYNC : 1 （AUDIO FOR BOTH DP AND HDMI）









1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	ATI Park MAIN IO	2A
Date: Wednesday, January 27, 2010	Sheet 16 of 42	

M@ for Madison level

(For Park&DDR3, VDDR = 1.5V@2.0A)

layout issue remove R387

U3006E

MEM I/O

POWER

CORE

PCIE

LEVEL TRANSLATION

I/O

PLL

VOLTAGE SENESE

Madison M2

(1.8V@110mA VDD_CT)

(1.8V@40mA PCIE_PVDD)

(MPV18 = 1.8V@75mA)

(Madison = 1.8V@150mA)

(1.8V@75mA SPV18)

(1.0V@120mA SPV10)

M9x : L3001、L3002 -> NC

(For M9x : VGA_CORE for SPV10)

M9x : R3084 Mount

VCORE_SEN/RTN and VDDCI_SEN/RTN route as differetial pair

	M92	M96	Manhattan
R3060	X	0	X
R3075	X	0	X
R3081	0	0	X
R3083	0	0	X

(1.8V@504mA PCIE_VDDR)

(1.0V@2A PCIE_VDDC)

(M9x : 1.1V@2A PCIE_VDDC)

(0.95V-1.1V@11 A (RMS) / 16 A (Peak) VDDC)

(0.95V-1.1V@2A VDDCI)

(0.95V-1.1V@2A Madison)

GND

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.

PROJECT : NE8

Size	Document Number	Rev
	ATI POWER/GND	2A

Date: Wednesday, January 27, 2010 Sheet 17 of 42



(1.8V@130mA DPC_VDD18)

(1.0V@110mA DPC_VDD10)

(M9x : VCC1.1 for DPx_VDD10)

(1.8V@130mA DPD_VDD18)

(1.0V@110mA DPD_VDD10)

LVDS mode (1.8V@200mA DPE_VDD18)

LVDS mode (1.0V@120mA DPE_VDD10)

LVDS mode (1.8V@200mA DPF_VDD18)

LVDS mode (1.0V@120mA DPF_VDD10)

(1.8V@130mA DPA_VDD18)

(1.0V@110mA DPB_VDD10)

(1.8V@130mA DPB_VDD18)

(1.0V@110mA DPB_VDD10)

(1.8V@20mA DPA_PVDD)

(1.8V@20mA DPB_PVDD)

(1.8V@20mA DPC_PVDD)

(1.8V@20mA DPD_PVDD)

(1.8V@20mA DPE_PVDD)

(1.8V@20mA DPF_PVDD)

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.

PROJECT : NE8

Size	Document Number	Rev
	ATI MEM/IF/DP	2A
Date: Wednesday, January 27, 2010	Sheet 18 of 42	

Use this option ONLY
for Park-S3


Park Use Channel B
Memory Interface Only
19
U3006C
U3006D
MEMORY INTERFACE A
MEMORY INTERFACE B
DDR2
GDDR3/GDDR5
DDR3
GDDR5/DDR2/GDDR3
(20) MDA[0..63]
(20) MAA[0..13]
(20) DQMA#[0..7]
(20) QSA[0..7]
(20) QSA#[0..7]
(20) ODTA[0..1]
(20) CKEA[0..1]
(21) MDB[0..63]
(21) MAB[0..13]
(21) DQMB#[0..7]
(21) QSB[0..7]
(21) QSB#[0..7]
(21) ODTB[0..1]
(21) CKEB[0..1]
MVREFDA
MVREFSA
MVREFDB
MVREFSB
MEM_CALRN0
MEM_CALRN1
MEM_CALRN2
MEM_CALRP1
MEM_CALRP0
MEM_CALRP2
TESTEN
CLKTESTA
CLKTESTB
DRAM_RST
Madison M2
Madison M2
VCC1.5
VCC3
Ra
Rb
R3068 40.2/F_4
R3067 100/F_4
R3069 40.2/F_4
R3070 100/F_4
R3000 40.2/F_4
R3002 100/F_4
R3001 40.2/F_4
R3005 100/F_4
R3006 240/F_4
R3003 240/F_4
R3015 240/F_4
R3004 240/F_4
R3044 240/F_4
R3037 240/F_4
R3059 *10K_4
R3057 1K
C3041 *0.01U/25V_4
C3036 *0.01U/25V_4
R3022 *51_4
R3021 *51_4
CLKA0
CLKA0#
R3032 56_4
C3294 0.01U/25V_4
R3091 56_4
CLKB0
CLKB0#
R3092 56_4
C3295 0.01U/25V_4
R3114 56_4
R3009 *2.2K_4
R3012 51_4
R3014 10K_4
C3024 68P/50V_4
M9x : Only Mount R3004
route 50ohms single-ended/100ohms diff
and keep short
Debug only, for clock observation, if not needed, DNI
DDR3
MEM_CALR 1.5V
Ra 40.2R
Rb 100R
1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.
Quanta Computer Inc.
PROJECT : NE8
Size
Document Number
ATI MEM IF
Rev 2A
Date: Wednesday, January 27, 2010
Sheet 19 of 42
Use this option ONLY
for Park-S3



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8
Size: Document Number: ATI VRAM DDR3 Rev: 2A
Date: Wednesday, January 27, 2010 Sheet 20 of 42



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8
Size | Document Number: ATI VRAM DDR3 | Rev: 2A
Date: Wednesday, January 27, 2010 | Sheet 21 of 42

CRT



LVDS



2A: Change to 87142-4014 (vertical)

for 17.3 panel change 3VPCU is ok?!



Display On



1C: 12/17 add RVCC5 for optional power source



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	CRT/LVDS	2A
Date: Wednesday, January 27, 2010	Sheet 22 of 42	

1B: share power with CRT port

VCC5_HDMI

VCC5 — F8 1206L025YR — D8 CH411DPT — VCC5_HDMI — C8 0.1u/10V_4

For EMI

EXT_HDMI_TXDP0 R420 *100/F_4 EXT_HDMI_TXDN0
EXT_HDMI_TXDP1 R418 *100/F_4 EXT_HDMI_TXDN1
EXT_HDMI_TXDP2 R419 *100/F_4 EXT_HDMI_TXDN2
HDMI_TXCP R417 *100/F_4 HDMI_TXCN

(16) EXT_HDMI_TXCP — RP46 0X2 — HDMI_TXCP
(16) EXT_HDMI_TXCN — HDMI_TXCN

ATI Suggestion close to Con24

Q33 2N7002DW

VCC5 R368 4.7K_4 — (16) EXT_HDMI_SCL — HDMI_SCL
VCC5 R369 4.7K_4 — (16) EXT_HDMI_SDA — HDMI_SDA

1B: add diode for HDMI test

VCC5 — D30 *RB501V-40
VCC5 — D29 *RB501V-40

R416 *1.5K/F_4
R415 *1.5K/F_4

HDMI_SCL
HDMI_SDA

12/17 Eric D29/D30/R416/R415 DNI

(16) EXT_HDMI_TXDP2 — C675 0.1u/10V_4 — EXT_HDMI_TXDP2_C
(16) EXT_HDMI_TXDN2 — C676 0.1u/10V_4 — EXT_HDMI_TXDN2_C
(16) EXT_HDMI_TXDP1 — C677 0.1u/10V_4 — EXT_HDMI_TXDP1_C
(16) EXT_HDMI_TXDN1 — C678 0.1u/10V_4 — EXT_HDMI_TXDN1_C
(16) EXT_HDMI_TXDP0 — C679 0.1u/10V_4 — EXT_HDMI_TXDP0_C
(16) EXT_HDMI_TXDN0 — C680 0.1u/10V_4 — EXT_HDMI_TXDN0_C
HDMI_TXCP — C681 0.1u/10V_4 — EXT_HDMI_TXCP_C
HDMI_TXCN — C688 0.1u/10V_4 — EXT_HDMI_TXCN_C

VCC5_HDMI (55mA)
HPD_HDMI
R7 100K/F_4

CON24 HDMI_AOP(C12815-119A5-L)

1	D2+	SHELL1	20
2	D2 Shield		
3	D2-		
4	D1+		
5	D1 Shield		
6	D1-	SHELL2	21
7	D0+		
8	D0 Shield		
9	D0-		
10	CK+		
11	CK Shield		
12	CK-		
13	CE Remote	SHELL3	23
14	NC		
15	DDC CLK		
16	DDC DATA		
17	GND		
18	+5V		
19	HP DET		
		SHELL4	22

0115 change connector, need update P/N

VCC3
Q32 MMBT3904
R8 150K/F_4 HPD_HDMI
(16) EXT_HDMI_HPD — R411 0_4
R410 10K_4

ATI Suggestion close to Con24 For ESD

VCC5
Q7 2N7002E
R22 *100K/J_4

R13	499/F_4	EXT_HDMI_TXDP2	C765	*10P/50V_4	
R14	499/F_4	EXT_HDMI_TXDN2	C766	*10P/50V_4	
R12	499/F_4	EXT_HDMI_TXDP1	C764	*10P/50V_4	
R11	499/F_4	EXT_HDMI_TXDN1	C763	*10P/50V_4	
R15	499/F_4	EXT_HDMI_TXDP0	C767	*10P/50V_4	
R16	499/F_4	EXT_HDMI_TXDN0	C768	*10P/50V_4	
R10	499/F_4	HDMI_TXCP	C762	*10P/50V_4	
R9	499/F_4	HDMI_TXCN	C761	*10P/50V_4	

BB BOM Error
100K ohm
12/17 Eric R22 DNI

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	HDMI	2A

Date: Wednesday, January 27, 2010 Sheet 23 of 42



Win7 didn't support wake WLAN

2A need check TOP or BOT again



BTM Side , Right==>ON



2A：deleted VCC1.5_MINI

SATA ODD



2.5 inch SATA HDD

1B: change FP
from SATA-C166M8-12205-L-22P-R
to HDD-SATA-C166L4-12205-L-22P-R



Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	WLAN/HDD/ODD	2A

Date: Wednesday, January 27, 2010 Sheet 24 of 42



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.		
PROJECT : NE8		
Size	Document Number: CARD Reader	Rev: 2A
Date: Wednesday, January 27, 2010	Sheet 25 of 42	

EXPRESS CARD

2A : Remove Express card

Bluetooth



RF LED



Card LED



HDD LED



Battery LED







2A: Change to 87213-0600L (SN)
P1.0, H2.9



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	Express Card/LED/TP	2A

Date: Wednesday, January 27, 2010 Sheet 26 of 42


ALC269Q-VB
ALC269Q-VB-GR
Analog
Digital
5V/4.75V
SPEAKER CON.
For EMI
2A: Change to 0 ohm
DVT change to Vertical
SPK_ACS(85205-0400L)
Quanta Computer Inc.
PROJECT : NE8
Codec ALC269Q
Rev 2A
Thursday, January 28, 2010
Sheet 27 of 42
1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	LAN RTL8111E	2A
Date: Wednesday, January 27, 2010	Sheet 28 of 42	

I/O Address		
BADDR1-0	Index	Data
* 1 0	2E	2F
1 1	4E	4F
0 0	(HCFGBAH, HCFGBAL)	(HCFGBAH, HCFGBAL)+1
0 1	XOR-TREE TEST	

SHMB: SHBM(If = 0 Enable share host BIOS memory)

DOCK_RST# : BADDR0
T?: BADDR1

1A: issue after RVCCON 20-25ms
Power step3
Power step1

Reserved for more EC wake up function
BB Rework
12/17 Eric R306 mount

1B: Delete diode but need to check EC driving timing
Not connect

KBSIN[0...7] SET internal PU

Power step2
Power step4
Power step5
Adding for ICT

EC must implement Wake function for ACIN & HOLD#
1B: Reserved for NPC781

High-active
35001 Not-I2C

EC SDI-> EEprom DO
EC SDO-> EEprom DI

NPCE781

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	NPCE781 & FLASH	2A
Date: Wednesday, January 27, 2010	Sheet 29 of 42	

KEYBOARD



USB Port + e-SATA(USB)



Current limit need to check



12/17 Eric correct part name

Current limit = ~1.5A
(For port0 and Camera)



Current limit = ~3A



FAN



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	KB/USB/FAN/PS	2A
Date: Wednesday, January 27, 2010	Sheet 30 of 42	

ISL6265 Pin1	OFS	VFIXEN
1.2V	V	X
3.3V	X	V
5V	X	X

VFIXEN VID Codes

SVC	SVD	Output
0	0	1.4
0	1	1.2
1	0	1.0
1	1	0.8



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	VCORE(ISL6265A)	2A
Date: Wednesday, January 27, 2010	Sheet 31 of 42	

3.3V & 5V



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	3VPCU&5VPCU(PM6686)	2A
Date: Wednesday, January 27, 2010	Sheet 32 of 42	

1.5VSUS & VTT_MEM



VCC1.5



MODE	DISCHARGE MODE
+5V	No discharge
+1.8V	Tracking discharge
GND	Non-tracking discharge

VDDQSET	VDDQ(V)	VTTREF & VTT	NOTE
GND	1.5 fixed	VDDQSNS/2	DDR3
5V	1.8 fixed	VDDQSNS/2	DDR2
FB-Resistor	Adjustable	VDDQSNS/2	1.5V<VDDQ<3V

VTT = VTTREF = VDDQSNS/2 = 0.75V

STATE	S3	S5	1.5VSUS	VTTREF	VTT
S0	1	1	on	on	on
S3	0	1	on	on	off
S4/S5	0	0	off	off	off

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	1.5VSUS/VTT_MEM	2A

Date: Wednesday, January 27, 2010 Sheet 33 of 42

DYN_VCC1.1 /7.6A



DYN_PWR_EN	High	Low
DYN_VCC1.1	0.95V	1.1V

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	DYN_VCC1.1(OZ8116LN)	2A

Date: Wednesday, January 27, 2010 Sheet 34 of 42





1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	VCC1.1(OZ8116LN)-7A	2A

Date: Wednesday, January 27, 2010 Sheet 35 of 42



Madison LP

External VGA_CORE Voltage Setting:

V_PWRCNTL0	VGA_CORE
0	0.95V
1	0.90V

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	VGA_CORE(OZ8116)-16A	2A

Date: Wednesday, January 27, 2010 Sheet 36 of 42

VCC1.8



Vout1 = (1+Rg/Rh)*0.5

VCC1.0



Vout1 = (1+Rg/Rh)*0.8

NO change Vcc1.0 NET name
M9x：Vcc1.1
Manhatten：Vcc1.0
BOM control PR13、PR17

2A

M92	PR17=7.5K Ohm	VCC1.0=1.1V
Park Madison	PR17=4.99K Ohm	VCC1.0=1.0V

VCC0.9

1B：Bear mount for power sequence

2A：change from PGOOD



Vout1 = (1+Rg/Rh)*0.8

VDDR_09_EN#	High	Low
VCC0.9	1.05V	0.9V

VCC2.5



Vout1 = (1+Rg/Rh)*0.8

Thermal Protection for VEDS



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	VCC1.8/0.9/2.5/1.0	2A

Date: Wednesday, January 27, 2010 Sheet 37 of 42



VIN Protection Circuit
Separate adapter OVP from UL circuit
OVP for VEDS
N.I
THERMAL PROTECT FOR PQ15
THINKING
BATTERY CONNECTOR
Same as TW1
PCN8
ACS-20288-044L
PCN7
AOP (C144Q7-107A8-L)
PL11 22/6A
PL9 22/6A
PL8 22/6A
PL10 22/6A
VAIN+
VAIN-
VA+
VA
PQ14B PIMD2/IMD2AT108
PQ14A PIMD2/IMD2AT108
AOD403 PQ15
PQ17 2N7002DW
PC37 0.1U/50V/X7R_6
PR36 220K_4
PC39 0.1U/50V/X7R_6
PC40 0.01U/50V/X7R_4
PC41 0.1U/50V/X7R_6
PR35 220K_4
(39) -VAOFF
(29,39) DC/-C
PC42 0.1U/10V/X5R_4
PR62 10K/F_4
PR65 1M_4
PR58 1M_4
PC52 0.1U/25V/X7R_6
PC55 0.1U/25V/X7R_6
PR56 249K/F_4
PD10 PDZ2.7B
PR57 470K_4
VIN
PD8 SMAJ22A-13-F
PD32 UDZ5V6B
PR237 220K_4
PR235 47K_4
PQ51 PDTC144EU
PR189 220_2512
PQ45 2N7002K/DMN601K-7
PD31 *UDZS5V6B
VCCRTC
PC137 0.1U/10V/X5R_4
PD22 PDZ6.2B
PR228 *100K_4
-UL_IN
TC7S14FU
PU19
PD21 SW1010CPT
PR195 47K_4
PC155 0.1U/10V/X5R_4
PC134 2.2U/6.3V/X5R_6
PC135 0.1U/10V/X5R_4
PR190 200K/F_4
PC157 0.1U/10V/X5R_4
PU16 TC7S14FU
PR232 10K_4
PC158 0.1U/10V/X5R_4
PU15 TC7S14FU
PQ46 SSM3K09FU
-SYS_PRS
PQ52-1 HN1K03FU
PQ52-2 HN1K03FU
PR233 1M_4
PQ50 2N7002
AD_OVP
PR198 680K_4
PR200 162K/D_4
PU18 BD4141HFV
IN VCC GND DLY PGOOD
PC138 1U/6.3V/X5R_4
PR227 3.6K/B_4
PR199 200K/F_4
PC152 0.01U/50V/X7R_4
PD30 UDZS5.1B
PR229 200K/F_4
PQ47 2N7002
PC154 1000P/50V/X7R_4
VDDNB_CORE-1 RVCC1.1-1 DYN_VCC1.1-1 1.5VSUS-1 VGA_CORE-1 VDD_CORE 3VPCU-1 RVCC5-1
PR220 30K/F_4 PR218 30K/F_4 PR207 30K/F_4 PR205 30K/F_4 PR204 30K/F_4 PR203 30K/F_4 PR202 30K/F_4 PR201 30K/F_4
PR208 140K/F_4 PR219 140K/F_4 PR206 140K/F_4 PR226 140K/F_4 PR225 140K/F_4 PR224 140K/F_4 PR223 52.3K/F_4 PR222 21.5K/F_4
PC149 PC145 PC144 PC142 PC141 PC151 PC140 0.1U/10V/X5R_4
PC150 0.1U/10V/X5R_4
RVCC5 BAT+ VA
PD23 MAZ81000ML
PR212 5.62K/F_6
PR209 27.1K/D_6
PR213 *62K/B_4
PR210 470/PTC/THINKIG_6
PR211 60.4K/D_6
PC143 10U/6.3V/X5R_8
PR214 *8.87K/B_4
PC146 *1U/6.3V/X5R_4
PD26 BAS16TW
PD28 BAS16TW
PROTECT
PD27 BAS16TW
PD25 BAS16TW
PD24 BAS16TW
PQ49-1 HN1K03FU
PQ48 2SC4738F
PR216 10K/F_4
PQ49-2 HN1K03FU
PR217 1K_4
PD29 PDZ6.2B
PR221 100K/F_4
PC148 0.1U/10V/X5R_4
PC139 *0.1U/10V/X5R_4
PU17 BD5225G
VDD OUT NC CD GND
PR215 100K_4
PC147 0.1U/25V/X7R_6
(29) BATT_ID
PD12 MMPZ5251BPT (22V+-5%)
PD13 PESD5V0S1BA
PD15 PESD5V0S1BA
PC112 47P/50V/NPO_4
PR152 22_4
PD16 PESD5V0S1BA
PC113 47P/50V/NPO_4
PR156 22_4
3VPCU
PR160 220K_4
PC117 0.1U/10V/X5R_4
PD17 PESD5V0S1BA
PD18 PESD5V0S1BA
PR159 1K_4
PR163 1K_4
(3,29) BATT_SDA
(3,29) BATT_SCK
(29) BAT_PRS#

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.

PROJECT : NE8

Size	Document Number	Rev
	BAT IN/ADA IN/UL	2A
Date: Wednesday, January 27, 2010	Sheet 38 of 42	



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	CHARGER(ISL6252A)	2A

Date: Wednesday, January 27, 2010 Sheet 39 of 42













WLAN

BT



Quanta Computer Inc.		
PROJECT : NE8		
Size	Document Number: Small board	Rev: 2A
Date: Thursday, January 28, 2010	Sheet 40 of 42	

Power on Sequence required:

SB800:
1, +3.3VDUAL ramp before +1.1VDUAL
2, +3.3V ramp before +1.8v
3, +1.8V ramp before +1.1v
4, +3.3v ramp before +1.1v
5, +3.3VALW_R ramping down time > 300us
6, 50uS <= All power rails except +3.3VALW_R <= 40mS
7, 100uS <= +3.3VALW_R <= 40mS

RS880:
1, 0 <(+3.3V) - (+1.8v) < 2.1
2, +1.8V ramp before +1.1v
3. +1.1V ramp before VCC_NB



1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	Power Squence	2A

Date: Wednesday, January 27, 2010 Sheet 41 of 42

2A Adding R159 (10K) for shut down issue.

1.Level 1 Environment-related Substances Should NEVER be Used.
2.Purchase ink, paint, wire rods, and Molding resins only from the business Partners that Sony approves as Green Partners.

Quanta Computer Inc.
PROJECT : NE8

Size	Document Number	Rev
	Change History	2A
Date: Wednesday, January 27, 2010	Sheet 42 of 42	